Representative Letter – Customer letters are brand, model and model year specific; listing the 17-digit VIN and are personalized.



IMPORTANT SAFETY RECALL

November 2019

This notice applies to your vehicle, VIN:

Dear General Motors Customer:

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

General Motors has decided that a defect which relates to motor vehicle safety exists in certain flip key/RKE transmitter assemblies that may have been sold as replacement keys for 2010 – 2015 model year Chevrolet Camaro vehicles. As a result, GM is conducting a safety recall. We apologize for this inconvenience. However, we are concerned about your safety and continued satisfaction with our products.

IMPORTANT

Your vehicle is involved in GM safety recall N192223230.

Why is your vehicle being recalled?

Our records indicate that you may have been sold the recalled flip key/RKE transmitter assembly. There is a risk that some drivers may bump the ignition "flip" key with their knee and unintentionally move the "flip" key away from the "run" position. If this occurs, engine power, and power braking will be affected, and power steering may be affected increasing the risk of a crash. If the ignition switch is not in the run position, the air bags may not deploy if the vehicle is involved in a crash, increasing the risk of injury or fatality.

What will we do?

Parts to repair your vehicle are not currently available, but when parts are available, your GM dealer will remove the key blade from the original flip key/RKE transmitter assemblies provided with your vehicle, and provide two new keys and two key rings per key. This service will be performed for you at no charge.

We are working as quickly as possible to correct this condition. When parts are available, we will send you another letter asking you to take your vehicle to your GM dealer to have your vehicle serviced. You can also check the status of this recall at: https://my.gm.com/recalls.

Until the recall has been performed, it is <u>very</u> important that you adjust your seat and steering column to allow clearance between your knee and the ignition key.

Do you have questions?

If you have questions or concerns that your dealer is unable to resolve, please contact the appropriate Customer Assistance Center at the number listed below.

Division	Number	Text Telephones (TTY)
Chevrolet	1-800-630-2438	1-800-833-2438
Puerto Rico – English	1-800-496-9992	
Puerto Rico – Español	1-800-496-9993	
Virgin Islands	1-800-496-9994	

If after contacting your dealer and the Customer Assistance Center, you are still not satisfied we have done our best to remedy this condition without charge and within a reasonable time, you may wish to write the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE., Washington, DC 20590, or call the toll-free Vehicle Safety Hotline at 1.888.327.4236 (TTY 1.800.424.9153), or go to http://www.safercar.gov. The National Highway Traffic Safety Administration Campaign ID Number for this recall is 19E064.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

Maryann Combs Vice President Global Vehicle Safety

GM Recall: #N192223230