

UPDATED May 6, 2021

CONDITION OF CONCERN

Certain subject vehicle may unexpectedly stop while driving due to inadvertent activation of the Smart Brake System (SBS) an automatic emergency braking system, increasing the risk of a rear-end crash from a following vehicle.

Incorrect programming of the SBS control software may cause the vehicle to falsely detect an obstacle in front of the vehicle while driving. Because of this, the SBS automatic emergency braking system may unexpectedly activate, along with the collision warning sound and warning message displayed on the multi-information and active driving displays, even though no collision is imminent. In certain cases, the SBS control software may automatically apply the vehicle brakes to prevent or reduce damage from a collision.

OUTLINE OF REPAIR – USE THE MDRT LABELED FOR SSPC5 AND RECALL 4621B

The software of the Vehicle Control Module (VCM) *is now updated using a superseded MDRT. The software contained in the MDRT and Labeled for campaigns SSPC5 and 4621B will also automatically update the required software updates for Recall 4219L.* Some vehicles will require an update to the electronic owner’s manual located in the CMU along with several pages of the paper Owner’s Manual will be replaced with updated printed material (*Leaflet printed and shipped to the dealer*).

Certain vehicles will also require updating the software of the Instrument Cluster (IC) *with the same MDRT tool (Tool identifies the correct repair by VIN and updates both modules if required)* or replacement of the IC.

SUBJECT VEHICLES

Model	Subject VIN range	Subject production date range
Mazda3 built at MC (Japan)	JM1 BP*** K1 100042 – 147655 JM1 BP*** L1 147656 – 154264	From September 25, 2018 through October 19, 2019
Mazda3 built at MMVO (Mexico)	3MZ BP**** KM 100048 – 115055 3MZ BP**** LM 115095 – 124858	From January 15, 2019 through October 23, 2019

The asterisk symbol “*” can be any letter or number.

OWNER NOTIFICATION

Mazda notified U.S. owners by first class mail starting February 14, 2020.

PARTS INFORMATION

Description	Part number	Quantity	Note	Scrap
Meter set	BDGG-55-430B 2.5L engine Confirm correct part in EPC by VIN	1	If "Repair Type C" is required	NO

NOTE: If you suspect your MDRT Tool is bad or need an additional MDRT Tool, please contact Dealer Recall Help on MXConnect > Warranty with at least 1 VIN that could not be repaired.

WARRANTY CLAIM PROCESSING INFORMATION

NOTE: All Mazda3 vehicles subject to this recall 4219L are also involved in the special service program (SSPC5). The VCM and instrument cluster (IC) reprogramming under this recall 4219L is completed by using the MDRT for SSPC5/recall 4621B. Because the reprogramming happens automatically during the reprogramming of SSPC5, the warranty information has been changed.

Repair type A (VCM reprogramming)

VIN and Production Range		Repair Type A using MDRT for SSPC5
MMVO Production VIN RANGE LM118755 – 124858 Dates: 8/5/19 - 10/23/19	Process Number	AK069D
	Symptom Code	99
	Damage Code	99
	Causal Part No. & Quantity	7777-SP-T22
MC Production VIN RANGE L1150242 – 154264 Dates: 7/30/19 - 10/19/19	Labor Operation	XXT3YXFX
	Labor Hours	0.1 hrs.
	Related Parts No, & Quantity	N/A

Repair type B (VCM, Instrument cluster and CMU reprogramming, and Paper Owner's Manual update)

VIN and Production Range		Repair Type B using MDRT for SSPC5
MMVO Production KM100048 – 114618 Dates: 01/15/19 - 6/20/19 LM115095 – 118752 Dates: 6/28/19 - 7/26/19	Process Number	AK069D
	Symptom Code	99
	Damage Code	99
	Causal Part No. & Quantity	7777-SP-T22
	Labor Operation	XXT3ZXFX
MC Production K1101936 – 147544 Dates: 11/5/18 - 6/28/19 L1147656 – 150225 Dates: 6/29/19 - 7/30/19	Labor Hours	0.2 hrs.
	Related Parts No, & Quantity	N/A

Repair type C (VCM and CMU reprogramming, Instrument cluster replacement and Paper Owner's Manual Update)

VIN and Production Range		Repair Type C using MDRT SSPC5 AND MDARS FOR IC CONFIGURATION
MC Production: K1100042 – 102178 Dates: 9/25/18 – 11/5/18	Process Number	AK069D
	Symptom Code	99
	Damage Code	99
	Causal Part No. & Quantity	7777-SP-T22
	Labor Operation	XXT41XFX
	Labor Hours	0.7 hrs.
	Related Parts No, & Quantity (as Mandatory)	BDGG-55-430B: Qty. 1 Confirm part # in EPC for the VIN
	Related Parts No, & Quantity	N/A

Note: Owner's Manual update has been preprinted and bulk shipped to your dealer.

RENTAL CAR INFORMATION

Mazda recommends the usage of the MCVP loaner vehicle when available. If all MCVP loaner vehicles are in use and unavailable, and the customer needs a rental car, then use your local rental facility and offer a rental car. Be sure that every effort is made to repair the car within one business day or less in order to allow the next customer the same experience.

Rental Car Warranty Claim Information

	MCVP Vehicle Preferred	Rental Agency Vehicle
Warranty Type Code	N/A MCVP does not require claim submission	A
Symptom Code		99
Damage Code		99
Part Number Main Cause		5555-42-19LR
Part Quantity		0
Labor Operation Code		MM024XR X
Labor Hours		0
Sublet – Rental Car		
Sublet Invoice Number		Number from Rental Invoice or Dealer Purchase Order
Sublet Type Code		Enter "Z9" (other)
Sublet Amount		Up to \$30.00 per day for the number of days customer had rental car
Sublet Text		Number of days rental car was supplied to customer

Rental expenses exceeding the two-day limit will require prior Warranty Department Authorization, as outlined in the Mazda Rental Car Reimbursement Program policy.