

# Part 573 Safety Recall Report

## 20V-012

**Manufacturer Name :** Toyota Motor Engineering & Manufacturing

**Submission Date :** MAR 19, 2020

**NHTSA Recall No. :** 20V-012

**Manufacturer Recall No. :** See attached report



### Manufacturer Information :

**Manufacturer Name :** Toyota Motor Engineering & Manufacturing

**Address :** 6565 Headquarters Drive

Plano TX 75024

**Company phone :** 1-800-331-4331

### Population :

**Number of potentially involved :** 1,830,752

**Estimated percentage with defect :** NR

### Vehicle Information :

**Vehicle 1 :** 2014-2015 Toyota Land Cruiser

**Vehicle Type :**

**Body Style :**

**Power Train :** NR

**Descriptive Information :** (1) Although the involved vehicles are within the above production period, not all vehicles in this range were sold in the U.S.

(2) Based on Toyota's current understanding of the condition, this recall applies to certain vehicles with specific fuel pumps supplied by Denso, containing impellers produced during specific periods under specific circumstances. These vehicles contain fuel pumps that were produced with impellers of lower density and contain either (1) a pump impeller of a type with lower surface strength or (2) a pump impeller that was exposed to production solvent drying for longer periods of time. Vehicles with fuel pumps that were not produced under the aforementioned conditions are not included at this time.

(3) Some hybrid models are equipped with the aforementioned fuel pumps. However, with the exception of LS500h and LC500h, if the condition occurs, these vehicles will enter a fail-safe driving mode, resulting in illumination of warning lights and reduced motive power in which the vehicle can still be driven for certain distances. This does not present an unreasonable risk to safety. Toyota intends to conduct a customer satisfaction campaign for these vehicles in the future.

Note: Unknown. Toyota is unable to provide an estimate of the percentage of vehicles to actually contain the defect. Whether the issue in each case will lead to a vehicle stall while driving at higher speeds depends on many variables, such as the specific production condition of fuel pump impeller and vehicle operating conditions.

**Production Dates :** SEP 02, 2013 - MAR 11, 2015

**VIN Range 1 : Begin :**

NR

**End :** NR

Not sequential

**Vehicle 2 :** 2018-2019 Toyota Highlander

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : (1) Although the involved vehicles are within the above production period, not all vehicles in this range were sold in the U.S.

(2) Based on Toyota's current understanding of the condition, this recall applies to certain vehicles with specific fuel pumps supplied by Denso, containing impellers produced during specific periods under specific circumstances. These vehicles contain fuel pumps that were produced with impellers of lower density and contain either (1) a pump impeller of a type with lower surface strength or (2) a pump impeller that was exposed to production solvent drying for longer periods of time. Vehicles with fuel pumps that were not produced under the aforementioned conditions are not included at this time.

(3) Some hybrid models are equipped with the aforementioned fuel pumps. However, with the exception of LS500h and LC500h, if the condition occurs, these vehicles will enter a fail-safe driving mode, resulting in illumination of warning lights and reduced motive power in which the vehicle can still be driven for certain distances. This does not present an unreasonable risk to safety. Toyota intends to conduct a customer satisfaction campaign for these vehicles in the future.

Note: Unknown. Toyota is unable to provide an estimate of the percentage of vehicles to actually contain the defect. Whether the issue in each case will lead to a vehicle stall while driving at higher speeds depends on many variables, such as the specific production condition of fuel pump impeller and vehicle operating conditions.

Production Dates : NOV 08, 2017 - JUL 03, 2019

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 3 : 2018-2019 Toyota Tacoma

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : (1) Although the involved vehicles are within the above production period, not all vehicles in this range were sold in the U.S.

(2) Based on Toyota's current understanding of the condition, this recall applies to certain vehicles with specific fuel pumps supplied by Denso, containing impellers produced during specific periods under specific circumstances. These vehicles contain fuel pumps that were produced with impellers of lower density and contain either (1) a pump impeller of a type with lower surface strength or (2) a pump impeller that was exposed to production solvent drying for longer periods of time. Vehicles with fuel pumps that were not produced under the aforementioned conditions are not included at this time.

(3) Some hybrid models are equipped with the aforementioned fuel pumps. However, with the exception of LS500h and LC500h, if the condition occurs, these vehicles will enter a fail-safe driving mode, resulting in illumination of warning lights and reduced motive power in which the vehicle can still be driven for certain distances. This does not present an unreasonable risk to safety. Toyota intends to

conduct a customer satisfaction campaign for these vehicles in the future.

Note: Unknown. Toyota is unable to provide an estimate of the percentage of vehicles to actually contain the defect. Whether the issue in each case will lead to a vehicle stall while driving at higher speeds depends on many variables, such as the specific production condition of fuel pump impeller and vehicle operating conditions.

Production Dates : NOV 07, 2017 - FEB 19, 2019

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 4 : 2018-2019 Toyota Tundra

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : (1) Although the involved vehicles are within the above production period, not all vehicles in this range were sold in the U.S.

(2) Based on Toyota's current understanding of the condition, this recall applies to certain vehicles with specific fuel pumps supplied by Denso, containing impellers produced during specific periods under specific circumstances. These vehicles contain fuel pumps that were produced with impellers of lower density and contain either (1) a pump impeller of a type with lower surface strength or (2) a pump impeller that was exposed to production solvent drying for longer periods of time. Vehicles with fuel pumps that were not produced under the aforementioned conditions are not included at this time.

(3) Some hybrid models are equipped with the aforementioned fuel pumps. However, with the exception of LS500h and LC500h, if the condition occurs, these vehicles will enter a fail-safe driving mode, resulting in illumination of warning lights and reduced motive power in which the vehicle can still be driven for certain distances. This does not present an unreasonable risk to safety. Toyota intends to conduct a customer satisfaction campaign for these vehicles in the future.

Note: Unknown. Toyota is unable to provide an estimate of the percentage of vehicles to actually contain the defect. Whether the issue in each case will lead to a vehicle stall while driving at higher speeds depends on many variables, such as the specific production condition of fuel pump impeller and vehicle operating conditions.

Production Dates : APR 02, 2018 - FEB 06, 2019

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 5 : 2018-2019 Lexus ES350

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : (1) Although the involved vehicles are within the above production period, not all vehicles in this range were sold in the U.S.

(2) Based on Toyota's current understanding of the condition, this recall applies to certain vehicles with specific fuel pumps supplied by Denso, containing impellers produced during specific periods under specific circumstances. These vehicles contain fuel pumps that were produced with impellers of lower density and contain either (1) a pump impeller of a type with lower surface strength or (2) a pump impeller that was exposed to production solvent drying for longer periods of time. Vehicles with fuel pumps that were not produced under the aforementioned conditions are not included at this time.

(3) Some hybrid models are equipped with the aforementioned fuel pumps. However, with the exception of LS500h and LC500h, if the condition occurs, these vehicles will enter a fail-safe driving mode, resulting in illumination of warning lights and reduced motive power in which the vehicle can still be driven for certain distances. This does not present an unreasonable risk to safety. Toyota intends to conduct a customer satisfaction campaign for these vehicles in the future.

Note: Unknown. Toyota is unable to provide an estimate of the percentage of vehicles to actually contain the defect. Whether the issue in each case will lead to a vehicle stall while driving at higher speeds depends on many variables, such as the specific production condition of fuel pump impeller and vehicle operating conditions.

Production Dates : APR 02, 2018 - MAY 06, 2019

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 6 : 2014-2015 Lexus GX460

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : (1) Although the involved vehicles are within the above production period, not all vehicles in this range were sold in the U.S.

(2) Based on Toyota's current understanding of the condition, this recall applies to certain vehicles with specific fuel pumps supplied by Denso, containing impellers produced during specific periods under specific circumstances. These vehicles contain fuel pumps that were produced with impellers of lower density and contain either (1) a pump impeller of a type with lower surface strength or (2) a pump impeller that was exposed to production solvent drying for longer periods of time. Vehicles with fuel pumps that were not produced under the aforementioned conditions are not included at this time.

(3) Some hybrid models are equipped with the aforementioned fuel pumps. However, with the exception of LS500h and LC500h, if the condition occurs, these vehicles will enter a fail-safe driving mode, resulting in illumination of warning lights and reduced motive power in which the vehicle can still be driven for certain distances. This does not present an unreasonable risk to safety. Toyota intends to conduct a customer satisfaction campaign for these vehicles in the future.

Note: Unknown. Toyota is unable to provide an estimate of the percentage of vehicles to actually contain the defect. Whether the issue in each case will lead to a vehicle

stall while driving at higher speeds depends on many variables, such as the specific production condition of fuel pump impeller and vehicle operating conditions.

Production Dates : SEP 02, 2013 - FEB 19, 2015

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 7 : 2018-2019 Lexus LC500

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : (1) Although the involved vehicles are within the above production period, not all vehicles in this range were sold in the U.S.

(2) Based on Toyota's current understanding of the condition, this recall applies to certain vehicles with specific fuel pumps supplied by Denso, containing impellers produced during specific periods under specific circumstances. These vehicles contain fuel pumps that were produced with impellers of lower density and contain either (1) a pump impeller of a type with lower surface strength or (2) a pump impeller that was exposed to production solvent drying for longer periods of time. Vehicles with fuel pumps that were not produced under the aforementioned conditions are not included at this time.

(3) Some hybrid models are equipped with the aforementioned fuel pumps. However, with the exception of LS500h and LC500h, if the condition occurs, these vehicles will enter a fail-safe driving mode, resulting in illumination of warning lights and reduced motive power in which the vehicle can still be driven for certain distances. This does not present an unreasonable risk to safety. Toyota intends to conduct a customer satisfaction campaign for these vehicles in the future.

Note: Unknown. Toyota is unable to provide an estimate of the percentage of vehicles to actually contain the defect. Whether the issue in each case will lead to a vehicle stall while driving at higher speeds depends on many variables, such as the specific production condition of fuel pump impeller and vehicle operating conditions.

Production Dates : OCT 06, 2017 - JAN 31, 2019

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 8 : 2018-2019 Lexus LS500

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : (1) Although the involved vehicles are within the above production period, not all vehicles in this range were sold in the U.S.

(2) Based on Toyota's current understanding of the condition, this recall applies to certain vehicles with specific fuel pumps supplied by Denso, containing impellers produced during specific periods under specific circumstances. These vehicles contain fuel pumps that were produced with impellers of lower density and contain either (1) a pump impeller of a type with lower surface strength or (2) a pump

impeller that was exposed to production solvent drying for longer periods of time. Vehicles with fuel pumps that were not produced under the aforementioned conditions are not included at this time.

(3) Some hybrid models are equipped with the aforementioned fuel pumps. However, with the exception of LS500h and LC500h, if the condition occurs, these vehicles will enter a fail-safe driving mode, resulting in illumination of warning lights and reduced motive power in which the vehicle can still be driven for certain distances. This does not present an unreasonable risk to safety. Toyota intends to conduct a customer satisfaction campaign for these vehicles in the future.

Note: Unknown. Toyota is unable to provide an estimate of the percentage of vehicles to actually contain the defect. Whether the issue in each case will lead to a vehicle stall while driving at higher speeds depends on many variables, such as the specific production condition of fuel pump impeller and vehicle operating conditions.

Production Dates : OCT 30, 2017 - JAN 31, 2019

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 9 : 2014-2015 Lexus LX570

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : (1) Although the involved vehicles are within the above production period, not all vehicles in this range were sold in the U.S.

(2) Based on Toyota's current understanding of the condition, this recall applies to certain vehicles with specific fuel pumps supplied by Denso, containing impellers produced during specific periods under specific circumstances. These vehicles contain fuel pumps that were produced with impellers of lower density and contain either (1) a pump impeller of a type with lower surface strength or (2) a pump impeller that was exposed to production solvent drying for longer periods of time. Vehicles with fuel pumps that were not produced under the aforementioned conditions are not included at this time.

(3) Some hybrid models are equipped with the aforementioned fuel pumps. However, with the exception of LS500h and LC500h, if the condition occurs, these vehicles will enter a fail-safe driving mode, resulting in illumination of warning lights and reduced motive power in which the vehicle can still be driven for certain distances. This does not present an unreasonable risk to safety. Toyota intends to conduct a customer satisfaction campaign for these vehicles in the future.

Note: Unknown. Toyota is unable to provide an estimate of the percentage of vehicles to actually contain the defect. Whether the issue in each case will lead to a vehicle stall while driving at higher speeds depends on many variables, such as the specific production condition of fuel pump impeller and vehicle operating conditions.

Production Dates : SEP 02, 2013 - MAR 11, 2015

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 10 : 2015-2015 Lexus NX200t

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : (1) Although the involved vehicles are within the above production period, not all vehicles in this range were sold in the U.S.

(2) Based on Toyota's current understanding of the condition, this recall applies to certain vehicles with specific fuel pumps supplied by Denso, containing impellers produced during specific periods under specific circumstances. These vehicles contain fuel pumps that were produced with impellers of lower density and contain either (1) a pump impeller of a type with lower surface strength or (2) a pump impeller that was exposed to production solvent drying for longer periods of time. Vehicles with fuel pumps that were not produced under the aforementioned conditions are not included at this time.

(3) Some hybrid models are equipped with the aforementioned fuel pumps. However, with the exception of LS500h and LC500h, if the condition occurs, these vehicles will enter a fail-safe driving mode, resulting in illumination of warning lights and reduced motive power in which the vehicle can still be driven for certain distances. This does not present an unreasonable risk to safety. Toyota intends to conduct a customer satisfaction campaign for these vehicles in the future.

Note: Unknown. Toyota is unable to provide an estimate of the percentage of vehicles to actually contain the defect. Whether the issue in each case will lead to a vehicle stall while driving at higher speeds depends on many variables, such as the specific production condition of fuel pump impeller and vehicle operating conditions.

Production Dates : OCT 20, 2014 - JUN 02, 2015

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 11 : 2018-2019 Lexus RC300

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : (1) Although the involved vehicles are within the above production period, not all vehicles in this range were sold in the U.S.

(2) Based on Toyota's current understanding of the condition, this recall applies to certain vehicles with specific fuel pumps supplied by Denso, containing impellers produced during specific periods under specific circumstances. These vehicles contain fuel pumps that were produced with impellers of lower density and contain either (1) a pump impeller of a type with lower surface strength or (2) a pump impeller that was exposed to production solvent drying for longer periods of time. Vehicles with fuel pumps that were not produced under the aforementioned conditions are not included at this time.

(3) Some hybrid models are equipped with the aforementioned fuel pumps. However, with the exception of LS500h and LC500h, if the condition occurs, these vehicles will enter a fail-safe driving mode, resulting in illumination of warning lights and reduced motive power in which the vehicle can still be driven for certain

distances. This does not present an unreasonable risk to safety. Toyota intends to conduct a customer satisfaction campaign for these vehicles in the future.

Note: Unknown. Toyota is unable to provide an estimate of the percentage of vehicles to actually contain the defect. Whether the issue in each case will lead to a vehicle stall while driving at higher speeds depends on many variables, such as the specific production condition of fuel pump impeller and vehicle operating conditions.

Production Dates : NOV 27, 2017 - JAN 31, 2019

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 12 : 2017-2019 Toyota Sienna

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : (1) Although the involved vehicles are within the above production period, not all vehicles in this range were sold in the U.S.

(2) Based on Toyota's current understanding of the condition, this recall applies to certain vehicles with specific fuel pumps supplied by Denso, containing impellers produced during specific periods under specific circumstances. These vehicles contain fuel pumps that were produced with impellers of lower density and contain either (1) a pump impeller of a type with lower surface strength or (2) a pump impeller that was exposed to production solvent drying for longer periods of time. Vehicles with fuel pumps that were not produced under the aforementioned conditions are not included at this time.

(3) Some hybrid models are equipped with the aforementioned fuel pumps. However, with the exception of LS500h and LC500h, if the condition occurs, these vehicles will enter a fail-safe driving mode, resulting in illumination of warning lights and reduced motive power in which the vehicle can still be driven for certain distances. This does not present an unreasonable risk to safety. Toyota intends to conduct a customer satisfaction campaign for these vehicles in the future.

Note: Unknown. Toyota is unable to provide an estimate of the percentage of vehicles to actually contain the defect. Whether the issue in each case will lead to a vehicle stall while driving at higher speeds depends on many variables, such as the specific production condition of fuel pump impeller and vehicle operating conditions.

Production Dates : NOV 08, 2017 - FEB 11, 2019

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 13 : 2018-2019 Toyota Corolla

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : (1) Although the involved vehicles are within the above production period, not all vehicles in this range were sold in the U.S.



(2) Based on Toyota's current understanding of the condition, this recall applies to certain vehicles with specific fuel pumps supplied by Denso, containing impellers produced during specific periods under specific circumstances. These vehicles contain fuel pumps that were produced with impellers of lower density and contain either (1) a pump impeller of a type with lower surface strength or (2) a pump impeller that was exposed to production solvent drying for longer periods of time. Vehicles with fuel pumps that were not produced under the aforementioned conditions are not included at this time.

(3) Some hybrid models are equipped with the aforementioned fuel pumps. However, with the exception of LS500h and LC500h, if the condition occurs, these vehicles will enter a fail-safe driving mode, resulting in illumination of warning lights and reduced motive power in which the vehicle can still be driven for certain distances. This does not present an unreasonable risk to safety. Toyota intends to conduct a customer satisfaction campaign for these vehicles in the future.

Note: Unknown. Toyota is unable to provide an estimate of the percentage of vehicles to actually contain the defect. Whether the issue in each case will lead to a vehicle stall while driving at higher speeds depends on many variables, such as the specific production condition of fuel pump impeller and vehicle operating conditions.

Production Dates : OCT 19, 2017 - FEB 08, 2019

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 14 : 2018-2019 Toyota Camry

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : (1) Although the involved vehicles are within the above production period, not all vehicles in this range were sold in the U.S.

(2) Based on Toyota's current understanding of the condition, this recall applies to certain vehicles with specific fuel pumps supplied by Denso, containing impellers produced during specific periods under specific circumstances. These vehicles contain fuel pumps that were produced with impellers of lower density and contain either (1) a pump impeller of a type with lower surface strength or (2) a pump impeller that was exposed to production solvent drying for longer periods of time. Vehicles with fuel pumps that were not produced under the aforementioned conditions are not included at this time.

(3) Some hybrid models are equipped with the aforementioned fuel pumps. However, with the exception of LS500h and LC500h, if the condition occurs, these vehicles will enter a fail-safe driving mode, resulting in illumination of warning lights and reduced motive power in which the vehicle can still be driven for certain distances. This does not present an unreasonable risk to safety. Toyota intends to conduct a customer satisfaction campaign for these vehicles in the future.

Note: Unknown. Toyota is unable to provide an estimate of the percentage of vehicles to actually contain the defect. Whether the issue in each case will lead to a vehicle stall while driving at higher speeds depends on many variables, such as the specific

production condition of fuel pump impeller and vehicle operating conditions.

Production Dates : NOV 20, 2017 - FEB 14, 2019

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 15 : 2018-2019 Toyota Avalon

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : (1) Although the involved vehicles are within the above production period, not all vehicles in this range were sold in the U.S.

(2) Based on Toyota's current understanding of the condition, this recall applies to certain vehicles with specific fuel pumps supplied by Denso, containing impellers produced during specific periods under specific circumstances. These vehicles contain fuel pumps that were produced with impellers of lower density and contain either (1) a pump impeller of a type with lower surface strength or (2) a pump impeller that was exposed to production solvent drying for longer periods of time. Vehicles with fuel pumps that were not produced under the aforementioned conditions are not included at this time.

(3) Some hybrid models are equipped with the aforementioned fuel pumps. However, with the exception of LS500h and LC500h, if the condition occurs, these vehicles will enter a fail-safe driving mode, resulting in illumination of warning lights and reduced motive power in which the vehicle can still be driven for certain distances. This does not present an unreasonable risk to safety. Toyota intends to conduct a customer satisfaction campaign for these vehicles in the future.

Note: Unknown. Toyota is unable to provide an estimate of the percentage of vehicles to actually contain the defect. Whether the issue in each case will lead to a vehicle stall while driving at higher speeds depends on many variables, such as the specific production condition of fuel pump impeller and vehicle operating conditions.

Production Dates : APR 02, 2018 - FEB 11, 2019

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 16 : 2014-2015 Toyota 4Runner

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : (1) Although the involved vehicles are within the above production period, not all vehicles in this range were sold in the U.S.

(2) Based on Toyota's current understanding of the condition, this recall applies to certain vehicles with specific fuel pumps supplied by Denso, containing impellers produced during specific periods under specific circumstances. These vehicles contain fuel pumps that were produced with impellers of lower density and contain either (1) a pump impeller of a type with lower surface strength or (2) a pump impeller that was exposed to production solvent drying for longer periods of time. Vehicles with fuel pumps that were not produced under the aforementioned conditions are not included at this time.

(3) Some hybrid models are equipped with the aforementioned fuel pumps. However, with the exception of LS500h and LC500h, if the condition occurs, these vehicles will enter a fail-safe driving mode, resulting in illumination of warning lights and reduced motive power in which the vehicle can still be driven for certain distances. This does not present an unreasonable risk to safety. Toyota intends to conduct a customer satisfaction campaign for these vehicles in the future.

Note: Unknown. Toyota is unable to provide an estimate of the percentage of vehicles to actually contain the defect. Whether the issue in each case will lead to a vehicle stall while driving at higher speeds depends on many variables, such as the specific production condition of fuel pump impeller and vehicle operating conditions.

Production Dates : SEP 02, 2013 - FEB 19, 2015

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 17 : 2018-2019 Toyota Sequoia

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : (1) Although the involved vehicles are within the above production period, not all vehicles in this range were sold in the U.S.

(2) Based on Toyota's current understanding of the condition, this recall applies to certain vehicles with specific fuel pumps supplied by Denso, containing impellers produced during specific periods under specific circumstances. These vehicles contain fuel pumps that were produced with impellers of lower density and contain either (1) a pump impeller of a type with lower surface strength or (2) a pump impeller that was exposed to production solvent drying for longer periods of time. Vehicles with fuel pumps that were not produced under the aforementioned conditions are not included at this time.

(3) Some hybrid models are equipped with the aforementioned fuel pumps. However, with the exception of LS500h and LC500h, if the condition occurs, these vehicles will enter a fail-safe driving mode, resulting in illumination of warning lights and reduced motive power in which the vehicle can still be driven for certain distances. This does not present an unreasonable risk to safety. Toyota intends to conduct a customer satisfaction campaign for these vehicles in the future.

Note: Unknown. Toyota is unable to provide an estimate of the percentage of vehicles to actually contain the defect. Whether the issue in each case will lead to a vehicle stall while driving at higher speeds depends on many variables, such as the specific production condition of fuel pump impeller and vehicle operating conditions.

Production Dates : APR 02, 2018 - MAR 18, 2019

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 18 : 2018-2019 Lexus IS300

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : (1) Although the involved vehicles are within the above production period, not all vehicles in this range were sold in the U.S.

(2) Based on Toyota's current understanding of the condition, this recall applies to certain vehicles with specific fuel pumps supplied by Denso, containing impellers produced during specific periods under specific circumstances. These vehicles contain fuel pumps that were produced with impellers of lower density and contain either (1) a pump impeller of a type with lower surface strength or (2) a pump impeller that was exposed to production solvent drying for longer periods of time. Vehicles with fuel pumps that were not produced under the aforementioned conditions are not included at this time.

(3) Some hybrid models are equipped with the aforementioned fuel pumps. However, with the exception of LS500h and LC500h, if the condition occurs, these vehicles will enter a fail-safe driving mode, resulting in illumination of warning lights and reduced motive power in which the vehicle can still be driven for certain distances. This does not present an unreasonable risk to safety. Toyota intends to conduct a customer satisfaction campaign for these vehicles in the future.

Note: Unknown. Toyota is unable to provide an estimate of the percentage of vehicles to actually contain the defect. Whether the issue in each case will lead to a vehicle stall while driving at higher speeds depends on many variables, such as the specific production condition of fuel pump impeller and vehicle operating conditions.

Production Dates : OCT 02, 2017 - JAN 31, 2019

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 19 : 2018-2019 Lexus GS300

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : (1) Although the involved vehicles are within the above production period, not all vehicles in this range were sold in the U.S.

(2) Based on Toyota's current understanding of the condition, this recall applies to certain vehicles with specific fuel pumps supplied by Denso, containing impellers produced during specific periods under specific circumstances. These vehicles contain fuel pumps that were produced with impellers of lower density and contain either (1) a pump impeller of a type with lower surface strength or (2) a pump impeller that was exposed to production solvent drying for longer periods of time. Vehicles with fuel pumps that were not produced under the aforementioned conditions are not included at this time.

(3) Some hybrid models are equipped with the aforementioned fuel pumps. However, with the exception of LS500h and LC500h, if the condition occurs, these vehicles will enter a fail-safe driving mode, resulting in illumination of warning lights and reduced motive power in which the vehicle can still be driven for certain distances. This does not present an unreasonable risk to safety. Toyota intends to conduct a customer satisfaction campaign for these vehicles in the future.

Note: Unknown. Toyota is unable to provide an estimate of the percentage of vehicles to actually contain the defect. Whether the issue in each case will lead to a vehicle stall while driving at higher speeds depends on many variables, such as the specific production condition of fuel pump impeller and vehicle operating conditions.

Production Dates : OCT 13, 2017 - JAN 18, 2019

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 20 : 2013-2015 Lexus GS350

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : (1) Although the involved vehicles are within the above production period, not all vehicles in this range were sold in the U.S.

(2) Based on Toyota's current understanding of the condition, this recall applies to certain vehicles with specific fuel pumps supplied by Denso, containing impellers produced during specific periods under specific circumstances. These vehicles contain fuel pumps that were produced with impellers of lower density and contain either (1) a pump impeller of a type with lower surface strength or (2) a pump impeller that was exposed to production solvent drying for longer periods of time. Vehicles with fuel pumps that were not produced under the aforementioned conditions are not included at this time.

(3) Some hybrid models are equipped with the aforementioned fuel pumps. However, with the exception of LS500h and LC500h, if the condition occurs, these vehicles will enter a fail-safe driving mode, resulting in illumination of warning lights and reduced motive power in which the vehicle can still be driven for certain distances. This does not present an unreasonable risk to safety. Toyota intends to conduct a customer satisfaction campaign for these vehicles in the future.

Note: Unknown. Toyota is unable to provide an estimate of the percentage of vehicles to actually contain the defect. Whether the issue in each case will lead to a vehicle stall while driving at higher speeds depends on many variables, such as the specific production condition of fuel pump impeller and vehicle operating conditions.

Production Dates : SEP 02, 2013 - FEB 21, 2015

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 21 : 2018-2019 Lexus GS350

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : (1) Although the involved vehicles are within the above production period, not all vehicles in this range were sold in the U.S.

(2) Based on Toyota's current understanding of the condition, this recall applies to certain vehicles with specific fuel pumps supplied by Denso, containing impellers

produced during specific periods under specific circumstances. These vehicles contain fuel pumps that were produced with impellers of lower density and contain either (1) a pump impeller of a type with lower surface strength or (2) a pump impeller that was exposed to production solvent drying for longer periods of time. Vehicles with fuel pumps that were not produced under the aforementioned conditions are not included at this time.

(3) Some hybrid models are equipped with the aforementioned fuel pumps. However, with the exception of LS500h and LC500h, if the condition occurs, these vehicles will enter a fail-safe driving mode, resulting in illumination of warning lights and reduced motive power in which the vehicle can still be driven for certain distances. This does not present an unreasonable risk to safety. Toyota intends to conduct a customer satisfaction campaign for these vehicles in the future.

Note: Unknown. Toyota is unable to provide an estimate of the percentage of vehicles to actually contain the defect. Whether the issue in each case will lead to a vehicle stall while driving at higher speeds depends on many variables, such as the specific production condition of fuel pump impeller and vehicle operating conditions.

Production Dates : OCT 03, 2017 - JAN 31, 2019

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 22 : 2014-2014 Lexus IS-F

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : (1) Although the involved vehicles are within the above production period, not all vehicles in this range were sold in the U.S.

(2) Based on Toyota's current understanding of the condition, this recall applies to certain vehicles with specific fuel pumps supplied by Denso, containing impellers produced during specific periods under specific circumstances. These vehicles contain fuel pumps that were produced with impellers of lower density and contain either (1) a pump impeller of a type with lower surface strength or (2) a pump impeller that was exposed to production solvent drying for longer periods of time. Vehicles with fuel pumps that were not produced under the aforementioned conditions are not included at this time.

(3) Some hybrid models are equipped with the aforementioned fuel pumps. However, with the exception of LS500h and LC500h, if the condition occurs, these vehicles will enter a fail-safe driving mode, resulting in illumination of warning lights and reduced motive power in which the vehicle can still be driven for certain distances. This does not present an unreasonable risk to safety. Toyota intends to conduct a customer satisfaction campaign for these vehicles in the future.

Note: Unknown. Toyota is unable to provide an estimate of the percentage of vehicles to actually contain the defect. Whether the issue in each case will lead to a vehicle stall while driving at higher speeds depends on many variables, such as the specific

production condition of fuel pump impeller and vehicle operating conditions.

Production Dates : SEP 10, 2013 - JUL 24, 2014

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 23 : 2017-2017 Lexus IS200t

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : (1) Although the involved vehicles are within the above production period, not all vehicles in this range were sold in the U.S.

(2) Based on Toyota's current understanding of the condition, this recall applies to certain vehicles with specific fuel pumps supplied by Denso, containing impellers produced during specific periods under specific circumstances. These vehicles contain fuel pumps that were produced with impellers of lower density and contain either (1) a pump impeller of a type with lower surface strength or (2) a pump impeller that was exposed to production solvent drying for longer periods of time. Vehicles with fuel pumps that were not produced under the aforementioned conditions are not included at this time.

(3) Some hybrid models are equipped with the aforementioned fuel pumps. However, with the exception of LS500h and LC500h, if the condition occurs, these vehicles will enter a fail-safe driving mode, resulting in illumination of warning lights and reduced motive power in which the vehicle can still be driven for certain distances. This does not present an unreasonable risk to safety. Toyota intends to conduct a customer satisfaction campaign for these vehicles in the future.

Note: Unknown. Toyota is unable to provide an estimate of the percentage of vehicles to actually contain the defect. Whether the issue in each case will lead to a vehicle stall while driving at higher speeds depends on many variables, such as the specific production condition of fuel pump impeller and vehicle operating conditions.

Production Dates : OCT 02, 2017 - OCT 02, 2017

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 24 : 2014-2015 Lexus IS350

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : (1) Although the involved vehicles are within the above production period, not all vehicles in this range were sold in the U.S.

(2) Based on Toyota's current understanding of the condition, this recall applies to certain vehicles with specific fuel pumps supplied by Denso, containing impellers produced during specific periods under specific circumstances. These vehicles contain fuel pumps that were produced with impellers of lower density and contain either (1) a pump impeller of a type with lower surface strength or (2) a pump impeller that was exposed to production solvent drying for longer periods of time.

Vehicles with fuel pumps that were not produced under the aforementioned conditions are not included at this time.

(3) Some hybrid models are equipped with the aforementioned fuel pumps. However, with the exception of LS500h and LC500h, if the condition occurs, these vehicles will enter a fail-safe driving mode, resulting in illumination of warning lights and reduced motive power in which the vehicle can still be driven for certain distances. This does not present an unreasonable risk to safety. Toyota intends to conduct a customer satisfaction campaign for these vehicles in the future.

Note: Unknown. Toyota is unable to provide an estimate of the percentage of vehicles to actually contain the defect. Whether the issue in each case will lead to a vehicle stall while driving at higher speeds depends on many variables, such as the specific production condition of fuel pump impeller and vehicle operating conditions.

Production Dates : SEP 02, 2013 - FEB 21, 2015

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 25 : 2018-2019 Lexus IS350

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : (1) Although the involved vehicles are within the above production period, not all vehicles in this range were sold in the U.S.

(2) Based on Toyota's current understanding of the condition, this recall applies to certain vehicles with specific fuel pumps supplied by Denso, containing impellers produced during specific periods under specific circumstances. These vehicles contain fuel pumps that were produced with impellers of lower density and contain either (1) a pump impeller of a type with lower surface strength or (2) a pump impeller that was exposed to production solvent drying for longer periods of time. Vehicles with fuel pumps that were not produced under the aforementioned conditions are not included at this time.

(3) Some hybrid models are equipped with the aforementioned fuel pumps. However, with the exception of LS500h and LC500h, if the condition occurs, these vehicles will enter a fail-safe driving mode, resulting in illumination of warning lights and reduced motive power in which the vehicle can still be driven for certain distances. This does not present an unreasonable risk to safety. Toyota intends to conduct a customer satisfaction campaign for these vehicles in the future.

Note: Unknown. Toyota is unable to provide an estimate of the percentage of vehicles to actually contain the defect. Whether the issue in each case will lead to a vehicle stall while driving at higher speeds depends on many variables, such as the specific production condition of fuel pump impeller and vehicle operating conditions.

Production Dates : OCT 02, 2017 - NOV 30, 2018

VIN Range 1 : Begin :

NR

End : NR

Not sequential



Vehicle 26 : 2018-2019 Lexus LC500h

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : (1) Although the involved vehicles are within the above production period, not all vehicles in this range were sold in the U.S.

(2) Based on Toyota's current understanding of the condition, this recall applies to certain vehicles with specific fuel pumps supplied by Denso, containing impellers produced during specific periods under specific circumstances. These vehicles contain fuel pumps that were produced with impellers of lower density and contain either (1) a pump impeller of a type with lower surface strength or (2) a pump impeller that was exposed to production solvent drying for longer periods of time. Vehicles with fuel pumps that were not produced under the aforementioned conditions are not included at this time.

(3) Some hybrid models are equipped with the aforementioned fuel pumps. However, with the exception of LS500h and LC500h, if the condition occurs, these vehicles will enter a fail-safe driving mode, resulting in illumination of warning lights and reduced motive power in which the vehicle can still be driven for certain distances. This does not present an unreasonable risk to safety. Toyota intends to conduct a customer satisfaction campaign for these vehicles in the future.

Note: Unknown. Toyota is unable to provide an estimate of the percentage of vehicles to actually contain the defect. Whether the issue in each case will lead to a vehicle stall while driving at higher speeds depends on many variables, such as the specific production condition of fuel pump impeller and vehicle operating conditions.

Production Dates : OCT 06, 2017 - JAN 28, 2019

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 27 : 2013-2015 Lexus LS460

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : (1) Although the involved vehicles are within the above production period, not all vehicles in this range were sold in the U.S.

(2) Based on Toyota's current understanding of the condition, this recall applies to certain vehicles with specific fuel pumps supplied by Denso, containing impellers produced during specific periods under specific circumstances. These vehicles contain fuel pumps that were produced with impellers of lower density and contain either (1) a pump impeller of a type with lower surface strength or (2) a pump impeller that was exposed to production solvent drying for longer periods of time. Vehicles with fuel pumps that were not produced under the aforementioned conditions are not included at this time.

(3) Some hybrid models are equipped with the aforementioned fuel pumps. However, with the exception of LS500h and LC500h, if the condition occurs, these vehicles will enter a fail-safe driving mode, resulting in illumination of warning lights and reduced motive power in which the vehicle can still be driven for certain

distances. This does not present an unreasonable risk to safety. Toyota intends to conduct a customer satisfaction campaign for these vehicles in the future.

Note: Unknown. Toyota is unable to provide an estimate of the percentage of vehicles to actually contain the defect. Whether the issue in each case will lead to a vehicle stall while driving at higher speeds depends on many variables, such as the specific production condition of fuel pump impeller and vehicle operating conditions.

Production Dates : SEP 02, 2013 - FEB 23, 2015

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 28 : 2018-2019 Lexus LS500h

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : (1) Although the involved vehicles are within the above production period, not all vehicles in this range were sold in the U.S.

(2) Based on Toyota's current understanding of the condition, this recall applies to certain vehicles with specific fuel pumps supplied by Denso, containing impellers produced during specific periods under specific circumstances. These vehicles contain fuel pumps that were produced with impellers of lower density and contain either (1) a pump impeller of a type with lower surface strength or (2) a pump impeller that was exposed to production solvent drying for longer periods of time. Vehicles with fuel pumps that were not produced under the aforementioned conditions are not included at this time.

(3) Some hybrid models are equipped with the aforementioned fuel pumps. However, with the exception of LS500h and LC500h, if the condition occurs, these vehicles will enter a fail-safe driving mode, resulting in illumination of warning lights and reduced motive power in which the vehicle can still be driven for certain distances. This does not present an unreasonable risk to safety. Toyota intends to conduct a customer satisfaction campaign for these vehicles in the future.

Note: Unknown. Toyota is unable to provide an estimate of the percentage of vehicles to actually contain the defect. Whether the issue in each case will lead to a vehicle stall while driving at higher speeds depends on many variables, such as the specific production condition of fuel pump impeller and vehicle operating conditions.

Production Dates : OCT 07, 2017 - JAN 30, 2019

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 29 : 2017-2017 Lexus RC200t

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : (1) Although the involved vehicles are within the above production period, not all vehicles in this range were sold in the U.S.

(2) Based on Toyota's current understanding of the condition, this recall applies

to certain vehicles with specific fuel pumps supplied by Denso, containing impellers produced during specific periods under specific circumstances. These vehicles contain fuel pumps that were produced with impellers of lower density and contain either (1) a pump impeller of a type with lower surface strength or (2) a pump impeller that was exposed to production solvent drying for longer periods of time. Vehicles with fuel pumps that were not produced under the aforementioned conditions are not included at this time.

(3) Some hybrid models are equipped with the aforementioned fuel pumps. However, with the exception of LS500h and LC500h, if the condition occurs, these vehicles will enter a fail-safe driving mode, resulting in illumination of warning lights and reduced motive power in which the vehicle can still be driven for certain distances. This does not present an unreasonable risk to safety. Toyota intends to conduct a customer satisfaction campaign for these vehicles in the future.

Note: Unknown. Toyota is unable to provide an estimate of the percentage of vehicles to actually contain the defect. Whether the issue in each case will lead to a vehicle stall while driving at higher speeds depends on many variables, such as the specific production condition of fuel pump impeller and vehicle operating conditions.

Production Dates : SEP 14, 2017 - NOV 28, 2017

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 30 : 2015-2015 Lexus RC350

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : (1) Although the involved vehicles are within the above production period, not all vehicles in this range were sold in the U.S.

(2) Based on Toyota's current understanding of the condition, this recall applies to certain vehicles with specific fuel pumps supplied by Denso, containing impellers produced during specific periods under specific circumstances. These vehicles contain fuel pumps that were produced with impellers of lower density and contain either (1) a pump impeller of a type with lower surface strength or (2) a pump impeller that was exposed to production solvent drying for longer periods of time. Vehicles with fuel pumps that were not produced under the aforementioned conditions are not included at this time.

(3) Some hybrid models are equipped with the aforementioned fuel pumps. However, with the exception of LS500h and LC500h, if the condition occurs, these vehicles will enter a fail-safe driving mode, resulting in illumination of warning lights and reduced motive power in which the vehicle can still be driven for certain distances. This does not present an unreasonable risk to safety. Toyota intends to conduct a customer satisfaction campaign for these vehicles in the future.

Note: Unknown. Toyota is unable to provide an estimate of the percentage of vehicles to actually contain the defect. Whether the issue in each case will lead to a vehicle stall while driving at higher speeds depends on many variables, such as the specific production condition of fuel pump impeller and vehicle operating conditions.

Production Dates : APR 15, 2014 - FEB 23, 2015

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 31 : 2018-2019 Lexus RC350

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : (1) Although the involved vehicles are within the above production period, not all vehicles in this range were sold in the U.S.

(2) Based on Toyota's current understanding of the condition, this recall applies to certain vehicles with specific fuel pumps supplied by Denso, containing impellers produced during specific periods under specific circumstances. These vehicles contain fuel pumps that were produced with impellers of lower density and contain either (1) a pump impeller of a type with lower surface strength or (2) a pump impeller that was exposed to production solvent drying for longer periods of time. Vehicles with fuel pumps that were not produced under the aforementioned conditions are not included at this time.

(3) Some hybrid models are equipped with the aforementioned fuel pumps. However, with the exception of LS500h and LC500h, if the condition occurs, these vehicles will enter a fail-safe driving mode, resulting in illumination of warning lights and reduced motive power in which the vehicle can still be driven for certain distances. This does not present an unreasonable risk to safety. Toyota intends to conduct a customer satisfaction campaign for these vehicles in the future.

Note: Unknown. Toyota is unable to provide an estimate of the percentage of vehicles to actually contain the defect. Whether the issue in each case will lead to a vehicle stall while driving at higher speeds depends on many variables, such as the specific production condition of fuel pump impeller and vehicle operating conditions.

Production Dates : NOV 27, 2017 - JAN 31, 2019

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 32 : 2017-2019 Lexus RX350

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : (1) Although the involved vehicles are within the above production period, not all vehicles in this range were sold in the U.S.

(2) Based on Toyota's current understanding of the condition, this recall applies to certain vehicles with specific fuel pumps supplied by Denso, containing impellers produced during specific periods under specific circumstances. These vehicles contain fuel pumps that were produced with impellers of lower density and contain either (1) a pump impeller of a type with lower surface strength or (2) a pump impeller that was exposed to production solvent drying for longer periods of time. Vehicles with fuel pumps that were not produced under the aforementioned conditions are not included at this time.

(3) Some hybrid models are equipped with the aforementioned fuel pumps.

However, with the exception of LS500h and LC500h, if the condition occurs, these vehicles will enter a fail-safe driving mode, resulting in illumination of warning lights and reduced motive power in which the vehicle can still be driven for certain distances. This does not present an unreasonable risk to safety. Toyota intends to conduct a customer satisfaction campaign for these vehicles in the future.

Note: Unknown. Toyota is unable to provide an estimate of the percentage of vehicles to actually contain the defect. Whether the issue in each case will lead to a vehicle stall while driving at higher speeds depends on many variables, such as the specific production condition of fuel pump impeller and vehicle operating conditions.

Production Dates : OCT 02, 2017 - JUL 25, 2019

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 33 : 2018-2019 Lexus RX350L

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : (1) Although the involved vehicles are within the above production period, not all vehicles in this range were sold in the U.S.

(2) Based on Toyota's current understanding of the condition, this recall applies to certain vehicles with specific fuel pumps supplied by Denso, containing impellers produced during specific periods under specific circumstances. These vehicles contain fuel pumps that were produced with impellers of lower density and contain either (1) a pump impeller of a type with lower surface strength or (2) a pump impeller that was exposed to production solvent drying for longer periods of time. Vehicles with fuel pumps that were not produced under the aforementioned conditions are not included at this time.

(3) Some hybrid models are equipped with the aforementioned fuel pumps. However, with the exception of LS500h and LC500h, if the condition occurs, these vehicles will enter a fail-safe driving mode, resulting in illumination of warning lights and reduced motive power in which the vehicle can still be driven for certain distances. This does not present an unreasonable risk to safety. Toyota intends to conduct a customer satisfaction campaign for these vehicles in the future.

Note: Unknown. Toyota is unable to provide an estimate of the percentage of vehicles to actually contain the defect. Whether the issue in each case will lead to a vehicle stall while driving at higher speeds depends on many variables, such as the specific production condition of fuel pump impeller and vehicle operating conditions.

Production Dates : DEC 04, 2017 - MAY 08, 2019

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 34 : 2014-2014 Toyota FJ Cruiser

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** (1) Although the involved vehicles are within the above production period, not all vehicles in this range were sold in the U.S.

(2) Based on Toyota's current understanding of the condition, this recall applies to certain vehicles with specific fuel pumps supplied by Denso, containing impellers produced during specific periods under specific circumstances. These vehicles contain fuel pumps that were produced with impellers of lower density and contain either (1) a pump impeller of a type with lower surface strength or (2) a pump impeller that was exposed to production solvent drying for longer periods of time. Vehicles with fuel pumps that were not produced under the aforementioned conditions are not included at this time.

(3) Some hybrid models are equipped with the aforementioned fuel pumps. However, with the exception of LS500h and LC500h, if the condition occurs, these vehicles will enter a fail-safe driving mode, resulting in illumination of warning lights and reduced motive power in which the vehicle can still be driven for certain distances. This does not present an unreasonable risk to safety. Toyota intends to conduct a customer satisfaction campaign for these vehicles in the future.

Note: Unknown. Toyota is unable to provide an estimate of the percentage of vehicles to actually contain the defect. Whether the issue in each case will lead to a vehicle stall while driving at higher speeds depends on many variables, such as the specific production condition of fuel pump impeller and vehicle operating conditions.

Production Dates : SEP 02, 2013 - AUG 07, 2014

VIN Range 1 : Begin :

NR

End : NR

Not sequential

## Description of Defect :

**Description of the Defect :** The subject vehicles are equipped with a low-pressure fuel pump, located in the fuel tank, that supplies fuel pressure to the fuel injection system. These fuel pumps may include impellers which have been manufactured with lower density. If these impellers are also (1) of a type with lower surface strength or (2) of a different type but were exposed to production solvent drying for longer periods of time, higher levels of surface cracking may occur. In this condition, excessive fuel absorption may occur, resulting in increased impeller deformation. In some cases, the impeller may deform to a point that creates sufficient interference with the fuel pump body to cause the fuel pump to become inoperative. An inoperative fuel pump due to these conditions could result in illumination of check engine and master warning indicators, rough engine running, engine no start and/or vehicle stall while driving at low speed.

However, in rare instances, vehicle stall could occur while driving at higher speeds, increasing the risk of a crash.

FMVSS 1 : NR

FMVSS 2 : NR

**Description of the Safety Risk :** In this condition, excessive fuel absorption may occur, resulting in increased impeller deformation. In some cases, the impeller may deform to a point that creates sufficient interference with the fuel pump body to cause the fuel

pump to become inoperative. An inoperative fuel pump due to these conditions could result in illumination of check engine and master warning indicators, rough engine running, engine no start and/or vehicle stall while driving at low speed. However, in rare instances, vehicle stall could occur while driving at higher speeds, increasing the risk of a crash.

Description of the Cause : NR

Identification of Any Warning  
that can Occur : NR

## Supplier Identification :

### Component Manufacturer

Name : Denso Corporation

Address : 1-1, Showa-cho  
Kariya-city, Aichi FOREIGN STATES 448-8661

Country : Japan

## Chronology :

Please see the attached Amended Part 573 Defect Information Report for the full chronology

## Description of Remedy :

Description of Remedy Program : All known owners of the affected Toyota and Lexus vehicles will be notified by first class mail to return their vehicles to a Toyota or Lexus dealer. Dealers will replace the fuel pump assembly with an improved one. The owner letter will instruct vehicle owners who have paid to have this condition remedied prior to this campaign to seek reimbursement pursuant to Toyota's General Reimbursement Plan.

Reimbursement Plan for pre-notification remedies:

The owner letter will instruct vehicle owners who have paid to have this condition remedied prior to this campaign to seek reimbursement pursuant to Toyota's General Reimbursement Plan.

How Remedy Component Differs  
from Recalled Component : See attached Amended Part 573 Defect Information Report.

Identify How/When Recall Condition  
was Corrected in Production : NR

**Recall Schedule :**

Description of Recall Schedule : Owners of vehicles currently included in the recall, that were not included in the amendment on March 4, 2020, will be notified by May 18, 2020. Owners of vehicles included in the amendment on March 4, 2020, that were not included in the original recall population on January 13, 2020, will be notified by May 3, 2020. Owners of the vehicles that were originally covered by this recall (as filed on January 13) and are still covered by this recall, as amended, were notified by March 13, 2020. Notifications to distributors/dealers were sent by March 19, 2020. Copies of dealer communications will be submitted as they are issued.

Planned Dealer Notification Date : MAR 19, 2020 - MAR 19, 2020

Planned Owner Notification Date : MAR 13, 2020 - MAY 18, 2020

\* NR - Not Reported