

Part 573 Safety Recall Report

20V-121

Manufacturer Name : Hyundai Motor America**Submission Date :** MAY 18, 2022**NHTSA Recall No. :** 20V-121**Manufacturer Recall No. :** 189**Manufacturer Information :****Manufacturer Name :** Hyundai Motor America**Address :** 10550 Talbert Avenue

Fountain Valley CA 92708

Company phone : 800-633-5151**Population :****Number of potentially involved :** 216,799**Estimated percentage with defect :** 1 %**Vehicle Information :****Vehicle 1 :** 2013-2014 Hyundai Sonata**Vehicle Type :** LIGHT VEHICLES**Body Style :** 4-DOOR**Power Train :** GAS

Descriptive Information : The subject vehicles include certain model year 2013-2014 Hyundai Sonata vehicles produced between November 26, 2012 and January 16, 2014 by Hyundai Motor Manufacturing Alabama ("HMMA") for sale in the U.S. market.

Production Dates : NOV 26, 2012 - FEB 07, 2014**VIN Range 1 : Begin :**

NR

End : NR☐ Not sequential**Description of Defect :**

Description of the Defect : The fuel feed line connecting the low pressure fuel pump to the direct injection fuel pump in the subject vehicles could develop a small crack over time due to ambient heat in the engine compartment.

FMVSS 1 : NR**FMVSS 2 :** NR

Description of the Safety Risk : A damaged fuel line could allow fuel to leak increasing the risk of an engine compartment fire.

Description of the Cause : Hyundai believes the material used to produce the fuel feed line might be more susceptible to heat under certain vehicle operating conditions; however, Hyundai is still actively investigating potential causes.

Identification of Any Warning that can Occur : Occupants might detect a fuel smell associated with this condition.

Involved Components :

Component Name 1 : Fuel Feed Tube Assembly

Component Description : Fuel feed line for 2.0L turbocharged engines

Component Part Number : 31310-3Q101QQH

Component Name 2 : Fuel Feed Tube Assembly

Component Description : Fuel feed line for 2.4L engines

Component Part Number : 31310-3Q901QQH

Supplier Identification :

Component Manufacturer

Name : Hanil Tube, USA

Address : 50 Hanil Dr.

Tallassee Alabama 36078

Country : United States

Chronology :

Please see Attachment A for the amended chronology of events leading to defect decision.

Description of Remedy :

Description of Remedy Program : Hyundai will notify owners of the involved vehicles by first class mail with instructions to bring their vehicles to a Hyundai dealer for an inspection of the low-pressure fuel tube for damage and/or leaking. If damage and/or leaking is found, the low-pressure tube will be replaced with a new one. If no damage or leaking is found, heat resistant tape will be installed at the connection between the low-pressure fuel tube and fuel pump.

Hyundai will provide reimbursement to owners for repairs according to the plan submitted on May 16, 2018.

How Remedy Component Differs from Recalled Component : The remedy component is manufactured with new material for the fuel tube, improved connector structure, and an added protective sleeve for increased stress and heat resistance.

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Dealers and owners will be notified in April 2020.
Planned Dealer Notification Date : APR 24, 2020 - APR 24, 2020
Planned Owner Notification Date : APR 24, 2020 - APR 24, 2020

* NR - Not Reported