#### OMB Control No.: 2127-0004

# Part 573 Safety Recall Report

Manufacturer Name :BMW of North America, LLCSubmission Date :JUN 18, 2020NHTSA Recall No. :20V-243Manufacturer Recall No. :NR

### Manufacturer Information :

Manufacturer Name : BMW of North America, LLC Address : P.O. Box 1227 Westwood NJ 07675-1227 Company phone : 18005257417

### Vehicle Information :

Vehicle 1:	2017-2017 BMW	/ 530i, 530i xD	rive, 540i, 540i xD	)rive	
Vehicle Type :	LIGHT VEHICLES	5			
Body Style :	4-DOOR				
Power Train :	GAS				
Descriptive Information :		n which the lev			e driver or nay, at some point,
	records were rev	viewed to deten nd May 30, 201	mine two specific 6) and, via parts t	production date	upplier production s of suspect parts pecific production
	-		non-recall compo ch exceeds specific		air bag may contain
Production Dates :	OCT 14, 2016 - F	EB 01, 2017			
VIN Range 1:	Begin :	NR	End: NR		Not sequential





### 20V-243

### **Population :**

Number of potentially involved :33Estimated percentage with defect :1 %

# Part 573 Safety Recall Report

20V-243

Vehicle 2:	2: 2017-2018 BMW 530e xDrive	
• •	LIGHT VEHICLES	
Body Style :		
	HYBRID ELECTRIC	
Descriptive Information :	Approximately 4 vehicles are equipped with a head air bag on the driver or passenge side in which the level of humidity within the inflator may, at some point, have exceeded specifications.	
	Basis for recall population determination: Vehicle assembly and supplier production records were reviewed to determine two specific production dates of suspect parts (May 16, 2016 and May 30 2016) and, via parts traceability, the specific production dates of potentially affected vehicles.	
	Recall component difference to non-recall component: The head air bag may contain moisture in the propellant which exceeds specifications.	
Production Dates :	AUG 31, 2016 - SEP 22, 2017	
Production Dates : VIN Range 1 :	AUG 31, 2016 - SEP 22, 2017 Begin : NR End : NR 🗌 Not sequential	
VIN Range 1 : : Description of Defect :		
VIN Range 1 : : Description of Defect :	Begin : NR End : NR Image: Not sequential   tt : This safety recall involves the driver and passenger head air bags in which the level of humidity within the inflator may, at some point, have exceeded specifications. Excessive humidity within the inflator could have an effect upon the propellant. As a result, during deployment of the head air bag, the pressure inside the inflator could be larger than intended.	
VIN Range 1 : : Description of Defect : Description of the Defe	Begin : NR End : NR Image: Not sequential   It : This safety recall involves the driver and passenger head air bags in which the level of humidity within the inflator may, at some point, have exceeded specifications. Excessive humidity within the inflator could have an effect upon the propellant. As a result, during deployment of the head air bag, the pressure inside the inflator could be larger than intended.   1 : NR	
VIN Range 1 : Description of Defect : Description of the Defe FMVSS FMVSS	Begin : NR End : NR Image: Not sequential   It : This safety recall involves the driver and passenger head air bags in which the level of humidity within the inflator may, at some point, have exceeded specifications. Excessive humidity within the inflator could have an effect upon the propellant. As a result, during deployment of the head air bag, the pressure inside the inflator could be larger than intended.   1 : NR	
VIN Range 1 : Description of Defect : Description of the Defe FMVSS FMVSS	Begin : NR End : NR Interpretation   At : This safety recall involves the driver and passenger head air bags in which the level of humidity within the inflator may, at some point, have exceeded specifications. Excessive humidity within the inflator could have an effect upon the propellant. As a result, during deployment of the head air bag, the pressure inside the inflator could be larger than intended.   1 : NR   2 : NR   k : In a crash of sufficient severity, deployment of the affected head air bag may be impaired, and/or the igniter could separate from the inflator, either of which could increase the risk of injury.	

**Involved Components :** 

The information contained in this report was submitted pursuant to 49 CFR §573

## Part 573 Safety Recall Report

20V-243

Component Name 1:	Head Air Bag - Left Side
Component Description :	Head Air Bag - Left Side
Component Part Number :	7 372 519

Component Name 2 : Head Air Bag - Right Side Component Description : Head Air Bag - Right Side Component Part Number : 7 372 520

### **Supplier Identification :**

### **Component Manufacturer**

Name : Joyson Safety Systems Address : Bahnweg 1 Aschaffenburg FOREIGN STATES 63743 Country : Germany

### Chronology :

On September 16, 2019, BMW became aware of an unusual deployment of a head air bag during recycling ignition of the air bag as part of the disposal process of an internal test vehicle. It was reported that the igniter separated from its attachment to the inflator. A review of supplier quality records indicated that the suspect inflator was produced on May 30, 2016.

A review was conducted to identify if additional test vehicles contained inflators that may have been produced from the production lot of the suspect inflator or other production lots with similarly designed inflators.

Between December 2019 and February 2020, additional inflators from test vehicles were able to be obtained, analyzed and then tested. Inflator interior humidity levels were able to be measured for 3 inflators, and indicated that the levels exceeded specifications. Inflators from 7 other test vehicles had already been through the disposal process, and there were no reported anomalies during recycling.

In March 2020, further reviews of supplier quality records showed that during inflator production, humidity levels and ballistic testing results were within specifications for all inflators subject to lot acceptance testing. Although the analysis is ongoing, at the present time, a root cause, which may have allowed the humidity level to exceed specifications, has not yet been identified.

Additional reviews were conducted to determine the number and production dates of potentially affected vehicles.

The information contained in this report was submitted pursuant to 49 CFR §573

On April 22, 2020, in an abundance of caution, BMW decided to conduct a voluntary recall for potentially affected vehicles.

BMW has not received any reports, nor is BMW otherwise aware, of any accidents or injuries related to this issue.

### **Description of Remedy :**

<b>Description of Remedy Program :</b>	The left or right head air bag will be replaced.	

Owners who have had this remedy performed at their own expense prior to the recall notification may be eligible for reimbursement according to BMW Group's reimbursement plan in accordance with 49 CFR 573.13 and 49 CFR 577.11.

How Remedy Component Differs<br/>from Recalled Component :Recalled Component: head air bag module; p/n (7 372 519 - left-side), (7<br/>372 520 - right-side).

Identify How/When Recall Condition NR was Corrected in Production :

### **Recall Schedule :**

Description of Recall Schedule :	Notification to dealers is planned to begin and end on April 29, 2020. Notification to owners is planned to begin and end on June 22, 2020.
Planned Dealer Notification Date :	APR 29, 2020 - APR 29, 2020
Planned Owner Notification Date :	JUN 22, 2020 - JUN 22, 2020

\* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573