Manufacturer Name :General Motors LLCSubmission Date :0CT 01, 2020NHTSA Recall No. :20V-603Manufacturer Recall No. :N202300860

Manufacturer Information :

Manufacturer Name : General Motors LLC

Address : 29427 Louis Chevrolet Road MAIL CODE 480-210-2V WARREN MI 48093 Company phone : 586-596-1733

Vehicle Information :

Vehicle 1:	2018-2018 Cadi	llac Escalade			
Vehicle Type :					
Body Style :					
Power Train :	NR				
Descriptive Information :	L86) engine pro	duced from GM ehicles that rece	's Spring Hil	fy vehicles that receive Il engine assembly plar sine produced after this	nt prior to
	2,640 Cadillac E	scalade vehicles	s are include	ed in this recall.	
Production Dates :	MAY 22, 2017 - S	SEP 30, 2017			
VIN Range 1:	Begin :	NR	End: NR		Not sequential
W.L. L. O.	0010 0010 Ch		1500		
Vehicle Z : Vehicle Type :	2018-2018 Chev	rolet Silverado	1500		
Body Style :					
Power Train :	NR				
Descriptive Information :	Manufacturing records were used to identify vehicles that received a 5.3L V8 (RPO L83) or 6.2L V8 (RPO L86) engine produced from GM's Spring Hill engine assembly plant prior to 10/01/2017. Vehicles that received an engine produced after this breakpoint are not included in this recall. Models that have an engine other than L83 or L86 are not affected by this recall. 3,607 Chevrolet Silverado vehicles are included in this recall.				
	5,007 Chevrolet	Silverado venio	les ale men	idea in this recail.	
Production Dates :					
	Begin :	NR	End: NR		Not sequential

The information contained in this report was submitted pursuant to 49 CFR §573

NHTSA

Number of potentially involved : 14,620

Estimated percentage with defect : 2 %

Population :

20V-603

20V-603

	2018-2018 Che	evrolet Tahoe		
Vehicle Type : Body Style :				
Power Train :	NR			
Descriptive Information :	L83) or 6.2L V8 plant prior to 1	8 (RPO L86) engi	ed to identify vehicles that r ne produced from GM's Spri nicles that received an engin chis recall.	ng Hill engine assembly
	1 Chevrolet Tal	noe vehicle is inc	luded in this recall.	
Production Dates :	AUG 22, 2017 -	AUG 22, 2017		
VIN Range 1:	Begin :	NR	End: NR	Not sequentia
Vehicle Type : Body Style :	2018-2018 GM	C Sierra 1500		
Power Train :	NR			
Descriptive Information :	L83) or 6.2L V8 plant prior to 1 breakpoint are or L86 are not a	8 (RPO L86) engi 0/01/2017. Vel not included in t affected by this r	ed to identify vehicles that r ne produced from GM's Spri nicles that received an engin this recall. Models that have ecall. ncluded in this recall.	ng Hill engine assembly e produced after this
	5,500 divic Sici	ra venicies are i	iciducu in this recail.	
Production Dates :				_
VIN Range 1:	Begin :	NR	End: NR	Not sequentia
Vehicle Type : Body Style : Power Train :				
Descriptive Information :	L83) or 6.2L V8 plant prior to 1	8 (RPO L86) engi	ed to identify vehicles that r ne produced from GM's Spri nicles that received an engin his recall.	ng Hill engine assembly
	2,992 GMC Yuk	on vehicles are i	ncluded in this recall.	
Production Dates :				
VIN Range 1:	Begin :	NR	End: NR	🗌 Not sequentia

The information contained in this report was submitted pursuant to 49 CFR \$573

Description of Defect :

FMVSS 1 :				
FMVSS 2 :				
Description of the Safety Risk :	If the vacuum level drops, customers may experience increased brake pedal effort, hard brake pedal, and/or potentially increased stopping distance. The Driver's Information Center (DIC) "Service brake assist" alert will activate 2-5 minutes after the vacuum level drops, and a Diagnostic Trouble Code (DTC) will also be set. The condition is more prevalent at low speed when softly applying the brakes. At all times, the brakes remain functional and exceed the requirements of S7.11 of Federal Motor Vehicle Safety Standard (FMVSS) No. 135, "Light Vehicle Brake Systems."			
Description of the Cause :	The prior safety recall identified a breakpoint in production that was incorrect. The vehicles subject to this recall were manufactured after the prior breakpoint, but used brake vacuum pumps of the prior design. In these vehicles, the vacuum assist pump is lubricated with engine oil, which flows into the pump through a filter screen. Under certain conditions and over a period of time, debris such as oil sludge can accumulate on the filter screen, potentially restricting the flow of oil into the pump over time and gradually reducing the amount of vacuum pressure generated. Failure to follow recommended oil change intervals could contribute to this condition. These vehicles are equipped with a secondary, hydraulic power brake assist system that activates to provide power brake assist if the vacuum drops, however, as calibrated the hydraulic brake boost assist is limited at lower speeds.			
	The driver may feel vibration in the brake pedal or a change in the amount of pressure required to depress the brake pedal. The operator and persons inside the vehicle may hear a ticking noise coming from the engine compartment or activation of the secondary hydraulic brake assist system. In addition, a "Service Brake Assist" message will appear in the Driver Information Center within two to five minutes of vacuum level less than 10 kPA.			
Involved Components :				
Component Name 1 : I	DATA FILE-ELEK BRK CONT MDL CALN			
Component Description : Braking Control Module (BCM) calibration				
Component Part Number : 8	84110293 thru 84110320, 84110322 thru 84110333, 84110335 thru 84110339			

The information contained in this report was submitted pursuant to 49 CFR §573

20V-603

Page 4

Component Name 2 :DATA FILE-ELEK BRK CONT MDL CALNComponent Description :Braking Control Module (BCM) calibrationComponent Part Number :84110341 thru 84110346, 84309752 thru 84309755

Supplier Identification :

Component Manufacturer

Name : NR Address : NR NR Country : NR

Chronology :

This is an expansion of NHTSA recall 19V645. GM defined the scope of this prior recall by analyzing manufacturing records to identify vehicles equipped with a specific vacuum brake-assist pump design. On June 2, 2020, based on an analysis of field data indicating a rise in field claims for the recall condition outside of the recall population, GM opened an investigation to determine whether the recall population was correctly defined.

After further investigation, which included an in-depth analysis of plant-level manufacturing records, GM identified additional vehicles equipped with the specific vacuum brake-assist pump design that should have been included in NHTSA recall 19V645. On September 24, 2020, GM's Safety and Field Action Decision Authority decided to conduct a safety recall.

Description of Remedy :

Description of Remedy Program :	Dealers will reprogram the Electronic Brake Control Module in these vehicles with a new calibration that will improve how the system utilizes the hydraulic brake boost assist function when vacuum assist is depleted. Pursuant to 577.11, GM will provide reimbursement to owners for repairs according to the plan submitted on May 17, 2019.
U	The new calibration improves how the system utilizes the hydraulic brake boost assist function when vacuum assist is depleted.
Identify How/When Recall Condition was Corrected in Production :	NR

The information contained in this report was submitted pursuant to 49 CFR §573

20V-603

Page 5

Recall Schedule :

Description of Recall Schedule :Dealers will be notified on October 1, 2020. Customer notification is
estimated to begin on November 16, 2020.Planned Dealer Notification Date :OCT 01, 2020 - OCT 01, 2020Planned Owner Notification Date :NOV 16, 2020 - NOV 16, 2020

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573