

# Part 573 Safety Recall Report

# 20V-685

**Manufacturer Name :** Nissan North America, Inc.**Submission Date :** DEC 18, 2020**NHTSA Recall No. :** 20V-685**Manufacturer Recall No. :** PC765**Manufacturer Information :**

Manufacturer Name : Nissan North America, Inc.

Address : P. O. BOX 685001

Franklin TN 37068-5009

Company phone : 800-647-7261

**Population :**

Number of potentially involved : 2,214

Estimated percentage with defect : 1 %

**Vehicle Information :**

Vehicle 1 : 2020-2020 Nissan Altima

Vehicle Type : LIGHT VEHICLES

Body Style : 4-DOOR

Power Train : GAS

**Descriptive Information :** This issue affects certain Nissan Altima S grade models equipped with Continental ProContact TX tires (215/60 R16 H) with TIN date code 3320 and Mold ID S-419149; part number: OETIR03035.

According to CTA Defect Information Report #20T-018, 39 affected tires were shipped to OEM and Replacement market customers. CTA has informed Nissan that it shipped two (2) affected tires to Nissan among 403 tires molded with the same TIN date code and Mold ID. Nissan has identified 2,214 vehicles that may have been fitted with these subject tires.

No other Nissan or Infiniti vehicles are affected by this issue because the affected tires are unique to this model and dates of manufacture.

Production Dates : SEP 02, 2020 - SEP 29, 2020

VIN Range 1 : Begin :

NR

End : NR

 Not sequential**Description of Defect :**

**Description of the Defect :** The affected Nissan Altima vehicles may be equipped with the subject tires. According to CTA, the affected tires in the recall may have a potential over cure condition. As a result, the affected tires may experience a carcass break in the sidewall with sudden air loss, or they could develop a belt edge separation that could lead to a partial or full tread/belt loss.

Please see CTA Defect Information Report #20T-018.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Affected tires may experience a sudden air loss without warning while others may exhibit localized tread wear which may manifest as excessive vibration and/or bulging in the tread area. These conditions could increase the risk of serious injury or death.

Description of the Cause : NR

Identification of Any Warning that can Occur : Affected tires may experience a sudden air loss without warning while others may exhibit localized tread wear which may manifest as excessive vibration and/or bulging in the tread area.

## Involved Components :

Component Name 1 : Continental ProContact TX tires

Component Description : 215/60 R16 H

Component Part Number : OETIR03035

## Supplier Identification :

### Component Manufacturer

Name : Continental Tire the Americas, LLC.

Address : 1830 Macmillan Park Drive  
Fort Mill South Carolina 29707

Country : United States

## Chronology :

September 25, 2020 – Nissan received notification from CTA about an over cure condition that occurred on certain tires that were shipped to OEM and replacement market customers. Nissan determined some of the potentially affected tires are used on certain Nissan Altima vehicles.

October 2020 to November 2020 - Nissan began an internal investigation into the issue. Specifically, Nissan conducted plant audits at both its Smyrna, TN and Canton, MS plants to determine if any suspect tires were in inventory or installed on production vehicles. The audit did not show any affected tires in inventory or on production vehicles.

During this time, Nissan met multiple times with CTA and continued to conduct internal meetings to understand CTA's investigation and evaluate the scope of affected tires. On October 26, CTA submitted a Defect Information Report concerning the subject tires and subsequently provided additional information concerning

the potential quantity of subject tires shipped to Nissan. Nissan then identified the production period of potentially affected vehicles based on the information provided by CTA.

November 4, 2020 – Based on the foregoing, Nissan decided to conduct a safety recall campaign to remedy affected vehicles.

## Description of Remedy :

Description of Remedy Program : Dealers will inspect the sidewalls of all four (4) tires for a specific TIN date code and MOLD ID number. If any subject tires are found, the dealer will remove and replace the tires with new ones. All removed tires will be collected and returned to Continental for quality and investigation purposes; after which, Continental will dispose of the tires according to local regulations.

Nissan will coordinate with CTA concerning the appropriate instructions for any reimbursement requests.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

## Recall Schedule :

Description of Recall Schedule : Nissan notified all owners of potentially affected vehicles on December 10, 2020. Dealers were notified on November 6, 2020.

Planned Dealer Notification Date : NOV 06, 2020 - NR

Planned Owner Notification Date : DEC 10, 2020 - NR

\* NR - Not Reported