

Part 573 Safety Recall Report

20V-753

Manufacturer Name : Mercedes-Benz USA, LLC.**Submission Date :** DEC 04, 2020**NHTSA Recall No. :** 20V-753**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Mercedes-Benz USA, LLC.

Address : 13470 International Parkway

Jacksonville FL 32218

Company phone : 1-877-496-3691

Population :

Number of potentially involved : 26

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2019-2019 Mercedes-Benz A220

Vehicle Type : LIGHT VEHICLES

Body Style : 4-DOOR

Power Train : GAS

Descriptive Information : Mercedes Benz 2019 A-Class 26 vehicles. The recall population was determined through production records. Vehicles outside of the recall population have all labels installed according to current production specifications.

Production Dates : AUG 20, 2018 - AUG 22, 2019

VIN Range 1 : Begin :

NR

End : NR

 Not sequential**Description of Noncompliance :**

Description of the Noncompliance : Mercedes-Benz AG ("MBAG"), the manufacturer of Mercedes-Benz vehicles, has determined that on certain Model Year ("MY") 2019 A-Class vehicles (177 platform), certain required information labels may not have been installed.

FMVSS 1 : 110 - Tire selection and rims

FMVSS 2 : NR

Description of the Safety Risk : If the vehicle does not have the all labels installed, the vehicle may not fulfill certain requirements as specified in FMVSS110 § 4.3 (c), 49 CFR 567.4, and 49 CFR 571.11

If the vehicle is missing the tire pressure label on the b-pillar or on the fuel filler flap as required by FMVSS110 § 4.3 (c), information relating to vehicle loading and maximum tire inflation pressure would not be readily available to the driver. If the driver were to inflate the tires to an incorrect tire pressure, the tires could become overloaded, potentially increasing the risk of a crash.

Description of the Cause : Due to a deviation in the production process, certain required labels may not have been properly installed on the vehicle.

Identification of Any Warning that can Occur : The customer will not receive an advance warning.

Involved Components :

Component Name 1 : Tire Label

Component Description : Tire Label

Component Part Number : A1775842603

Component Name 2 : Tire Label

Component Description : Tire Label

Component Part Number : A1775842403

Component Name 3 : Tire Label

Component Description : Tire Label

Component Part Number : A1775842303

Component Name 4 : Tire Label

Component Description : Tire Label

Component Part Number : A1775841603

Component Name 5 : Tire Label

Component Description : Tire Label

Component Part Number : A1775842003

Supplier Identification :

Component Manufacturer

Name : Mercedes-Benz AG

Address : NR

Country : NR

Chronology :

In late October 2018, MBAG found that a vehicle at one of its production plants did not have all of the labels that would normally be installed on the vehicle. MBAG initiated a plant action to manually review each vehicle to determine whether or not these vehicles included all required labels as well as other additional labels added by the manufacturer. Any vehicle that did not exhibit all required labels was reworked before being released from the production plant. Approximately 3,000 vehicles were reworked as part of the plant action, some of which included attaching the certification label and/or tire pressure labels. A review of plant actions was conducted in August 2019, as part of the company's standard process. During this review, it was found that certain vehicles had not been reworked. An investigation was launched at the end of 2019 to determine whether or not certain vehicles could have been released from the production plant without all required labels, and if so, which labels could potentially be missing. The investigation was delayed due to company-wide restrictions stemming from the COVID-19 pandemic. The investigation resumed in fall 2020, with a focus on confirming the rework status of these vehicles, as well as confirming whether or not all required labels were installed. On November 27, 2020, MBAG determined that it could not exclude the potential that certain vehicles did not have the certification label and/or tire pressure placard and decided to conduct a recall to have dealers inspect for the presence of the labels and apply them to the vehicle if necessary.

Description of Remedy :

Description of Remedy Program : An authorized Mercedes-Benz dealer will check the affected vehicles for the appropriate tire pressure labels and retrofit it, if necessary.

Pursuant to 49 C.F.R. § 577.11(e), MBUSA does not plan to provide notice about pre-notice reimbursement to owners since none of the involved vehicles would have been previously subject to the condition described and all remain covered under the new vehicle warranty.

How Remedy Component Differs from Recalled Component : None.

Tire Pressure Label	A1775842603
Tire Pressure Label	A1775842403
Tire Pressure Label	A1775842303
Tire Pressure Label	A1775841603
Tire Pressure Label	A1775842003

Identify How/When Recall Condition was Corrected in Production : A change in the production procedure of plant ensures that this issue can no longer occur from Aug 23, 2019 onwards.

Recall Schedule :

Description of Recall Schedule : Dealers will be notified of the pending voluntary recall campaign on December 11, 2020. Owners will be notified of the voluntary recall campaign approximately one week after launch to the dealers on February 2, 2021.

A copy of all communications will be provided when available.

Planned Dealer Notification Date : DEC 11, 2020 - NR

Planned Owner Notification Date : FEB 02, 2021 - NR

* NR - Not Reported