Part 573 Safety Recall Report

Manufacturer Name :Daimler Trucks North America, LLCSubmission Date :DEC 21, 2020NHTSA Recall No. :20V-806Manufacturer Recall No. :FL-871



Number of potentially involved : 278

Estimated percentage with defect : 30 %

20V-806

Manufacturer Information :

Manufacturer Name :Daimler Trucks North America, LLCAddress :4747 N. Channel AvenuePortland OR 97217-3849800-745-8000

Vehicle Information :

Vehicle 1:	2022-2022 Thomas Built Buse	es Saf-T-Liner C2	
Vehicle Type :	BUSES, MEDIUM & HEAVY VE	HICLES	
Body Style :			
Power Train :	NR		
Descriptive Information :	School bus chassis equipped w	vith suspect hydraul	ic brake calipers
Production Dates : OCT 14, 2020 - DEC 03, 2020			
VIN Range 1:	Begin : NR	End: NR	□ Not sequential

Population :

Description of Defect :

Description of the Defect :	The 73mm Bosch hydraulic caliper tie bar support fasteners on steer axles may be under torqued and/or finger loose or the tie bar may have not been installed in some cases
FMVSS 1 :	NR
FMVSS 2 :	NR
Description of the Safety Risk :	Although a loose or dangling tie bar could theoretically cause problems through coming into contact with rotating wheel-end components or brake parts flexing, we have no indication that any such things happened.
Description of the Cause :	NR
Identification of Any Warning that can Occur :	

Involved Components :

The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Recall Report

Component Name 1 : caliper tie bar Component Description : caliper tie bar Component Part Number : BW 02040J2120

Supplier Identification :

Component Manufacturer

Name : NR Address : NR NR Country : NR

Chronology :

In November of 2020, DTNA found a single failure where the tie bar fasteners where determined to be finger loose. DTNA and the axle assembly supplier immediately performed inspections at the plants. The investigation found 55 units with fasteners under torqued and two trucks in which the tie bar had not been installed during assembly but no additional finger loose fasteners. Over the course of December 2020, DTNA engaged the axle assembly supplier to determine a population. Based on the best available information currently, DTNA has developed the population cited in this DIR/DIN; we will continue to work to define the population. December 2020, with an abundance of caution, DTNA reasonably decided to conduct a voluntary safety recall.

Description of Remedy :

Description of Remedy Program :	Inspection of both steer axle wheel-ends will require the removal of the tire & wheel assembly. The 4 tie bar mounting fasteners are to torqued to 40-50 ft-lbs. If the required tie bar is missing inspection of the caliper anchor mounts and functionality (brake pad slide pins and pad movement) is required before installing a tie bar. Repairs will be performed by Daimler Trucks North America authorized service facilities. Customer notification will be done by first class mail using Daimler Trucks North America records to determine the customers affected. Details of the reimbursement plan will be included in the owner's notification letter.
How Remedy Component Differs from Recalled Component :	NR
Identify How/When Recall Condition was Corrected in Production :	NR

The information contained in this report was submitted pursuant to 49 CFR §573

20V-806

Recall Schedule :

Description of Recall Schedule :	Customer notification will be made by first class mail using Daimler
	Trucks North America records to determine the customers affected.
Planned Dealer Notification Date :	FEB 18, 2021 - FEB 18, 2021
Planned Owner Notification Date :	FEB 18, 2021 - FEB 18, 2021

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573