

N454NAS1

TECHNICAL BULLETIN

11 JUN 2020



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

SECTION:

501-05

SUBJECT/CONCERN:

Non-Compliance Recall: Incorrect Specification Replacement Headliners

AFFECTED VEHICLE RANGE:

MODEL:	MODEL YEAR:	VIN:
New Range Rover Evoque (LZ)	2020	005684
New Range Rover Evoque (LZ)	2020	006599
New Range Rover Evoque (LZ)	2020	020232

MARKETS :

CANADA, USA

CONDITION SUMMARY :
SITUATION:

A potential issue has been identified on certain vehicles within the listed Affected Vehicle Range where the headliners supplied have been incorrectly manufactured.

ACTION:

Retailers are required to HOLD affected new vehicles that are within your control and refrain from releasing the vehicles for new vehicle sale pending completion of the procedure(s) detailed in this Technical Bulletin. Unsold vehicles should have this performed as part of the Pre-Delivery Inspection (PDI) process but must have it completed prior to vehicle handover to the customer.

Affected vehicles already in the hands of customers should be updated at the next available opportunity.

PARTS :
NOTE:

Add the Vehicle Identification Number (VIN) to the Customer Material Field to process your order. Order quantity of '1' only.

DESCRIPTION	PART NUMBER	QUANTITY
Headliner	LR117807	1
PU adhesive kit	LR078295	1

WARRANTY :
NOTE:

Use the Jaguar Land Rover claims submission system to make sure that a vehicle is eligible for this program prior to undertaking any rework action.

At the time of confirming a booking for vehicle repair, make sure that all open Recall and Service Actions are identified to make sure the correct parts are available and adequate workshop time is allocated for repairs to be completed at one visit.

Warranty claims must be submitted quoting the Program Code and the relevant Option Code; this will result in payment of the stated time. The SRO and parts information is included for information only. The Option Code(s) that allows for the drive in/drive out allowance may only be claimed if the vehicle is brought back into the workshop for this action alone to be undertaken.

Repair procedures are under constant review and therefore times/prices are subject to change; those quoted here must be taken as guidance only. Use TOPIx to obtain the latest repair time.

Warranty claims must be submitted or payment within 30 calendar days of completion of the repair.

PROGRAM CODE	OPTION CODE	DESCRIPTION	SRO	TIME (HOURS)	PART NUMBER	QUANTITY
N454	A	Headliner - Sunshine/sliding roof condition - Renew	76.64.15	4.2	LR117807	1
					LR078295	1
N454	B	Headliner - Sunshine/sliding roof condition - Renew Drive in/drive out	76.64.15 02.02.02	4.2 0.2	LR117807	1
					LR078295	1
					-	-

Normal Warranty policies and procedures apply.

SERVICE INSTRUCTION:

1. Renew the headliner (see TOPIx Workshop Manual section 501-05: Interior Trim and Ornamentation - Removal and Installation - Headliner).