

ECALL CAMPAIGN BULLETIN

Classification:

Reference:

Date:

RS17-045b

NTB17-054b

January 15, 2020

VOLUNTARY SAFETY RECALL CAMPAIGN 2001-2003 MAXIMA; FRONT PASSENGER AIR BAG INFLATOR

This bulletin has been amended. See AMENDMENT HISTORY on page 26. Please discard previous versions of this bulletin.

CAMPAIGN ID #: R1711 and R1712

NHTSA #: 15V-287

APPLIED VEHICLES: 2001-2003 Maxima (A33)

Check Service COMM or Dealer Business Systems (DBS) National Service History to confirm campaign eligibility.

INTRODUCTION

Nissan is conducting this Voluntary Safety Recall Campaign on certain specific 2001-2003 Maxima vehicles to replace the front passenger air bag module and inflator. This service will be performed at no charge to customer for parts or labor.

Takata has issued return packaging, shipping labels, documents, and directions that must be used and followed in order to properly carry out this campaign. Takata's documentation is attached and is part of this bulletin.

IDENTIFICATION NUMBER

Nissan has assigned identification numbers R1711 and R1712 to this campaign. This number must appear on all communications and documentation of any nature dealing with this campaign.

DEALER RESPONSIBILITY

It is the dealer's responsibility to check Service COMM or Dealer Business Systems (DBS) National Service History for the campaign status on each vehicle falling within the range of this voluntary safety recall which for any reason enters the service department. This includes vehicles purchased from private parties or presented by transient (tourist) owners and vehicles in a dealer's inventory. **Federal law requires that new vehicles in dealer inventory which are the subject of a safety recall must be corrected prior to sale. Failure to do so can result in civil penalties by the National Highway Traffic Safety Administration.** While federal law applies only to new vehicles, Nissan strongly encourages dealers to correct any used vehicles in their inventory before they are retailed.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

REPAIR OVERVIEW



REQUIRED SPECIAL TOOL (J-51315)



Figure A

REQUIRED SPECIAL TOOL (J-52352)

Quick Scan Tool (J-52352)

- Each retailer has been shipped one Quick Scan Tool (J-52352).
- Additional tools can be obtained from Tech-Mate: nissantechmate.com or 1-800-662-2001.



Figure B

SERVICE PROCEDURE

New Inflator and New Module Registration

- 1. Obtain a new inflator and a new module from your parts department.
 - New inflator and new module are listed in the Parts Information.

2. Attach the quick scan tool (J-52352) to your CONSULT PC USB port.



Figure 1

3. On the left side of the ASIST main menu, select Tech Support Info, then Inventory Vehicle Actions.

	Last Sync. 10/10/2016 8:48:08 PM	
AS		Version 13.8.2
	VIN: Retrieve VIN Clear Model: Vination New Service Manual CONSULT Codes Symptom Days Service Hatory Compared	Ouk Reference
TECH LINE DB Search	Vinars new Servez remue Currous Looper Syncrom Lines Service Instory Lambag	Featured NEWS
Latest TSBs	Keyword Search:	
TSB Search	* Red indicates TSBs & Campaigns issued/updated within last 30 days	ASIST CRITICAL
CONSULT-II \$ NATS & Keycode \$ Speciality Tools \$ TECH LINE Support \$ TECH Support Info \$ TECH TALK/NTRA Inventory Vehicle Actions	Tech Support Info	if you see this message the ASIST update has been applied. Please check if this message is
Powertrain Call Center Pre-Call Forms Tech-Mate		displaying on your other workstations, in
Virtual Academy (¥) ASIST Support (¥)		the ASIST Synchronizer. Sept 26, 201

Figure 2

4. Select CLICK HERE (Air Bag to VIN Registration).

Service Actions -Nis	san	
PC507 2016-17 Titan	Diesel TCM Reprogram - Service Action - Dealer Announcement and Procedure CLICK HERE	
PC502 - 2017 Altima	Maxima Front Member Welds CLICK HERE	
PC522 Titan and P633	34 Armada ECM Reprogram CLICK HERE	
PC469 - 2016 Titan C	enter Seat - QAH Dealer Announcement and Repar Procedure CLICK HERE	
PC499 - 2017 Rogue	Front Camera - Service Action - Dealer Announcement & Procedure CLICK HERE	
PC543 2017 Rogue T	PMS Initialization CLICK HERE	
PM666 - 2017 Sentra	Accelerator Pedal Inspection CLICK HERE	
PC470, PC549, PC54	0 Titan Tailgate Lock CLICK HERE	
R1703 2002 Pathfinde	r Takata Passenger Air Bag Inflator CLICK HERE	
Inventory Inspection	s - Nissan	
Airbag to VIN Registr.	Select CLICK HERE	

Figure 3

Register the New Inflator

- 5. Use the quick scan tool to scan the bar code (VIN) on the B-pillar label.
 - Wipe any dirt/debris from bar code before scanning.

NOTE:

- Some labels may not scan quickly.
- Hold the scan tool approximately 6 inches away from the label.
- Hold the trigger down until the label is read (this may take several seconds).



Figure 4

- VIN will automatically populate (see Figure 5).
- If needed, VIN can be entered manually.

Dealer Code	
Key Number	
VIN	
Airbag Serial Number	Submit
	Step 7; see next page
	(Select submit after bo fields are populated).

Figure 5

- 6. Use the quick scan tool to scan the bar code (serial number) on the new inflator shipping box.
 - The serial number will automatically populate (see Figure 5 on previous page).

NOTE: If needed, the serial number can be entered manually.



7. Select **Submit** on the ASIST screen (see Figure 5 on the previous page).

Register the New Module

8. Use the quick scan tool and scan the bar code (VIN) on the vehicle B-pillar label a second time.

NOTE:

- Some labels may not scan quickly.
- Hold the scan tool approximately 6 inches away from the label.
- Hold the trigger down until the label is read (this may take several seconds).



Figure 7

• If needed, VIN can be entered manually (Figure 8).

	and Airbag Inflator Serial Number
D. L. C. L	
Dealer Code	
Key Number	
VIN	
Airbag Serial Number	Submit
	Step 12; see next page
	(Select submit after bot fields are populated).

Figure 8

- 9. Open the Module shipping container.
 - New module is listed in the Parts Information.
- 10. Locate the bar code sticker on the new module.

NOTE: The new module will be left in the shipping container until later in this procedure.

- 11. Use the quick scan tool to scan the bar code (serial number) on the new module (see Figures 9 and 10).
 - The serial number will automatically populate (see Figure 8).



Figure 9



Figure 10

12. Select **Submit** on the ASIST screen (see Figure 8 on the previous page).

Inflator and Module Replacement

IMPORTANT:

- Follow all cautions, warnings, and notes in the Electronic Service Manual (ESM) when working on or near a Supplemental Restraint System (SRS), such as an air bag.
- To help avoid damage, refer to Instrument Panel Removal Tips starting on the next page.

CAUTION: Handle interior trim carefully to avoid damage. Work with clean hands and clean tools to avoid dirt and stains. Use protective covers as needed.

13. Turn the ignition ON.

Presets	1	2	3	4	5	6
AM						
FM 1						
FM 2						
SAT 1						
SAT 2						
Bass	Treb	le	Balance	Fade	Speed Vol.	Sen.

14. Write down the radio settings.

- 15. Turn the ignition OFF.
- 16. Disconnect both battery cables, negative cable first.
- 17. Wait at least 3 minutes.
- 18. Remove the passenger air bag module (module) from the vehicle.
 - Refer to the appropriate Electronic Service Manual (ESM) for module removal information.

IMPORTANT: Follow all cautions, warnings, and notes in the Electronic Service Manual (ESM) when working on or near a Supplemental Restraint System (SRS), such as an air bag.

CAUTION: Handle interior trim carefully to avoid damage. Work with clean hands and clean tools to avoid dirt and stains. Use protective covers as needed.

19. Set the module in a clean working area.

NOTE: Do not set the module with cover facing down.

20. Securely mount the air bag module support (support) in a vice (see Figure 11).



Figure 11

WARNING:

- Work from behind and to the sides of the support.
- Wear safety glasses while performing inflator replacement.

21. Disconnect the harness clip from the module frame.



Figure 12

- 22. Attach the support bracket to the module frame.
 - Tighten the bolts holding the bracket to the module frame.
 - Use bolts supplied with the support.
 - Leave the L brackets on each end slightly loose to allow for positioning of the module in the support.

WARNING: Work from behind and to the sides of the support.



Figure 13

- 23. Mount the module in the support.
 - Use bolts and nuts supplied with the support.
- 24. Make sure the module is centered in the support.



Figure 14

NOTE: Centering the module in the support will allow access to the inflator securing nuts through the slots in the support.

25. Tighten all of the mounting bolts and nuts that hold the module to the support.



Figure 15



Figure 16

- 26. Carefully cut a few inches of the yellow corrugated harness cover in the area shown.
 - **Do not** cut the wires inside the corrugated cover.
- 27. Attach 2 shorting pins to the inflator harness as shown.
 - Make sure to pair the wires from each end of the inflator.

Blue with White

Red with Yellow

- Use an insulation displacement type wire connector as a shorting pin.
- Refer to the Parts Information for additional connector/shorting pin information.



Figure 17

28. Cut off the connector end of the harness.



Figure 18

- 29. Remove the 4 nuts from the module that hold the inflator in place (see Figures 19 and 20).
 - Use a ratchet and extension.



Figure 19

• Remove the 4 nuts.

NOTE: These nuts <u>will not</u> be reused.



Figure 20

30. Remove the inflator stopper.



Figure 21



Figure 22

- 31. Push the right side of the inflator out of the module.
 - Twist the inflator to a position that will allow the connector and harness to fit through the opening.

32. Pull the old inflator completely out of the module from the left side.



Figure 23

33. Set the old inflator in the clean working area making sure it does not roll and fall to the floor.

34. Remove the <u>old module</u> from the support and place it on a clean work surface.



Figure 24

35. Remove the support bracket from the old module.



Figure 25

- 36. Remove the <u>new module</u> from its shipping container.
 - New module is listed in the Parts Information. •

- 37. Remove the instrument panel finisher from the old module, and transfer it to the new module as follows.
 - a. Set the module on the bench with the mounting holes facing you.

Instrument panel finisher



Figure 26

- b. Use a plastic trim tool to detach the module hooks on the side facing you.
 - Detach one hook at a time.
 - Start at one end and then work towards the opposite end.
 - Detach all 7 hooks.



Figure 27

- c. Remove the old module from the finisher.
 - Lift out the side facing you.
 - Use a tilt/twist motion to detach the hooks on the other side.

NOTE: The old module will <u>not</u> be reused.



Figure 28

- d. Install the new module to the finisher.
 - Make sure the mounting bolt holes face the side of the finisher with SRS AIRBAG written on it.
 - Make sure all of the hooks are attached correctly.

NOTE: <u>SRS ARIBAG</u> is written on the front side of the finisher.



Figure 29



Figure 30



Figure 31

- 38. Attach the support bracket to the new module frame.
 - Use bolts supplied with the support.

39. Slide the paper tube completely out of the module.

IMPORTANT:

- The new module contains two inflator stopper brackets one for each side.
- In the following steps, make sure to install the correct stopper bracket on each side of the inflator.



• Make sure to **use new nuts**.

NOTE: New nuts and new stopper bracket are included with the new module.



- Use bolts and nuts supplied with the support.
- 42. Make sure the module is centered in the support.

NOTE: Centering the module in the support will allow access to the inflator securing nuts through the slots in the support.



Figure 33



Figure 34

43. Remove the new inflator from the box.

IMPORTANT:

- The new inflator has a large plastic end cap and a small plastic end cap.
- When installing, pay close attention to which end is installed first.



Figure 35

Install the New Inflator into the New Module

44. Slide the new inflator into the module assembly from the left side; <u>large plastic end cap first.</u>



Figure 36

Right side stopper bracket Tab on end of inflator

Figure 37

45. On the Right side, make sure the tab on the end of the inflator fits in the stopper bracket as shown.

- 46. Install the **left** side inflator stopper bracket and 2 inflator securing nuts <u>finger tight</u> (see Figure 38).
 - Make sure to **use new nuts**.

NOTE: Stopper bracket and new nuts are included with the new module.



Figure 38

- 47. Make sure the inflator is pushed all the way into its housing no gap on the right side (see Figure 39).
- 48. Make sure there is no gap between the inflator stopper and the inflator on the left side (see Figure 39).



Figure 39

- 49. Torque the 4 inflator securing nuts.
 - Torque nuts to: 3.9 Nm (0.39 kg-m, **34 in-lb**).
 - Torque nuts in the order shown.



Figure 40

IMPORTANT:

- In the next step you will be attaching the new harness to the new inflator.
- Once an inflator connector is attached to the inflator, it <u>cannot</u> be disconnected.
- Make sure to attach the connectors to the correct ends of the inflator (see Figure 41).
 - o Left / Right orientation is as shown in Figure 41.



Figure 41

- 50. Attach the new harness to each end of the inflator.
 - Remove the dust proof stickers covering the ends of the inflator.
 - A new harness is included with the new module.
 - Make sure to attach the correct ends (see Figure 41 on the previous page).
 - Refer to Figures 42, 43, and 44.



Figure 42

• Make sure the T shape at the inflator end aligns with the T shape of the connector.



Figure 43

• Make sure the inflator connectors are fully engaged / seated (see Figure 44).



Figure 44

51. Remove the module from the support and set it on the clean working area.

52. Remove the support bracket from the module frame.





- 53. Attach the harness clip to the module frame.
- 54. Route/attach the harness to the harness guides.



Figure 46

- 55. Reinstall the module into the vehicle in reverse order of removal.
 - Make sure to use the new "one time use" module mounting bolts included with the new module.
- 56. Re-connect both battery cables positive cable first.
- 57. Reset the clock and the radio settings.
- 58. Turn the ignition ON and observe the air bag warning light:
 - Light should illuminate for 7 seconds and then go out.

NOTE: If the Air Bag Warning light does not operate as described above there may be an issue not covered by this campaign. Refer to ASIST and the appropriate ESM for additional diagnostic and repair information.

- 59. Return the removed (old / non-deployed) inflator in the box that the new inflator arrived in.
 - Follow the return instructions provided by Takata.
 - Return instructions provided by Takata are attached to this bulletin on page 27.

PARTS INFORMATION

DESCRIPTION	PART #	QUANTITY
INFLATOR-AIR BAG (Inflator)	98561-7999E	1
MODULE KIT-SUB (Includes module mounting bolts, inflator harness, inflator securing nuts, and stopper brackets)	K8525-4Y90C	1
Shorting Pin (Insulation Displacement Connector for 22- 18 gauge wire)	NAPA item # 784566	
	Grainger Item # 4YT50	2
	or equivalent available from local auto supply	

NOTE:

- Make sure to return the removed (old / non-deployed) inflator in the box that the new inflator came in.
- Follow the return instructions provided by Takata.
- Takata supplied return instructions are attached to this bulletin on page 27.

CLAIMS INFORMATION

Submit a "CM" line claim using the following claims coding:

<u>Maxima</u>

CAMPAIGN ("CM") I.D.	DESCRIPTION	OP CODE	FRT
R1711	Remove and replace front passenger air bag sub-module and inflator	R17112	1.0 hrs.

CAMPAIGN ("CM") I.D.	CAMPAIGN ("CM") I.D. DESCRIPTION		FRT
R1712	Remove and replace front passenger air bag sub-module and inflator	R17123	1.0 hrs.

EXPENSE CODE

CODE	DESCRIPTION	MAXIMUM AMOUNT
041	Shorting Pin (Insulation Displacement Connector for 22-18 gauge wire)	\$0.50

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
July 19, 2017	NTB17-054	Original bulletin published
March 27, 2018	NTB17-054a Changes made throughout	
January 15, 2020	NTB17-054b	CLAIMS INFORMATION revised and Campaign ID # added

Takata Document

