

TECHNICAL INSTRUCTIONS

FOR

SAFETY RECALL 20LA02

CERTAIN ENGINE BLOCKS CAN CAUSE ENGINE FAILURE LEADING TO FIRE RISK


CERTAIN 2020 ES 300h

The repair quality of covered vehicles is extremely important to Lexus. All dealership technicians performing this recall are required to successfully complete the most current version of the E-Learning course “Safety Recall and Service Campaign Essentials”. To ensure that all vehicles have the repair performed correctly; technicians performing this recall repair are required to currently hold at least one of the following certification levels:

- Senior
- Master

It is the dealership’s responsibility to select technicians with the above certification level or greater to perform this recall repair. Carefully review your resources, the technician skill level, and ability before assigning technicians to this repair. It is important to consider technician days off and vacation schedules to ensure there are properly trained technicians available to perform this repair at all times.

I. OPERATION FLOW CHART



II. BACKGROUND

Some of the subject vehicles may be equipped with an engine block that was manufactured incorrectly. This issue may cause coolant to leak internally and/or externally during normal engine operation. This can lead to engine noise, engine smoke, warning lights/malfunction indicator illumination, an audible chime sounding, and/or, in some cases, engine overheating and possible internal mechanical engine damage. If the mechanical engine damage occurs, it could cause engine oil to leak, which, in the presence of an ignition source, can lead to an increased risk of fire.


III. IDENTIFICATION OF AFFECTED VEHICLES

- Check the TIS Vehicle Inquiry System to confirm the VIN is involved in this Safety Recall, and that it has not already been completed prior to dealer shipment or by another dealer.
- TMS warranty will not reimburse dealers for repairs completed on vehicles that are not affected or were completed by another dealer.

IV. BLOCK ID No. INSPECTION

1. REMOVE CENTER No. 4 ENGINE UNDER COVER

- Raise the car on a lift to gain access to the bottom of the vehicle.
- Remove the 4 screws to remove the Center No. 4 Engine Under Cover below the engine oil pan.





2. LOCATE ENGINE BLOCK ID No.

- Reference the photo below to locate the Block ID No. stamping.

3. CLEAN THE SURFACE

- Use a clean, wet rag to wipe the area of the Block ID No. If necessary, use a wire brush to remove any additional dirt or corrosion.





4. TAKE A PHOTO OF THE BLOCK ID No.

- a. Use a camera to take a photo of the Block ID No. Be sure to place the camera as straight and level as possible to the surface of the stamping.



5. REVIEW PHOTO

- a. Zoom in on the Block ID No. in the photo to be sure all 12 characters can be clearly read. If all 12 digits are not legible, retake the photo.

Note: If Necessary, clean the area with a wire brush to remove any dirt and corrosion.

Note: If the Block ID No. is unreadable after properly cleaning the surface and retaking the photos, send an email to Quality Compliance:

Email address: Quality_Compliance@Toyota.com

Subject: Block ID Unreadable

Provide the following:

- **Attachment: Quality photo of the Block ID No.**
- **Dealer Code**
- **Technician Name**
- **VIN #**
- **Explanation of the problem**

Once this email has been sent, please wait for an email response from Quality Compliance. They will provide directions for your next step.

V. DETERMINE INSPECTION RESULT

1. OPEN INSPECTION WEBSITE

- a. Open the 20LA02 Inspection Website by selecting the following link:

<https://20TA04-20LA02-safety-recall.imagespm.info/>

- b. Enter your dealer code in the User ID field.
- c. Enter xxxxx for the Password. It will then prompt you to change the password. You can enter the same (5 x's) again, or create your own password. If you do change the password, be sure to advise other technicians of the updated password.

Note: Selecting the “Forgot Password” link will reset the password to the default password: xxxxx

- d. Enter the vehicles VIN. It is critical that the VIN be entered accurately.

2. ENTER BLOCK ID No.

- a. Enter the top row of the Block ID No. (6 digits) when prompted.

NOTE: All 6 digits are NUMBERS.



- b. Enter the bottom row of the Block ID No. (6 digits) when prompted.

NOTE: The first digit is a LETTER, the remaining digits are NUMBERS.



Image Upload

Take a photo of the Block ID Number and save to computer. Browse to select the file location and upload.

VIN:

Block ID Number:

Choose File | No file chosen


Submit

3. UPLOAD PHOTO


- a. The website will require a photo of the Block ID No. to be uploaded. Be sure that all 12 digits of the Block ID No. are legible in the photo.

4. REVIEW INSPECTION RESULTS

a. Review the results provided by the website after inputting the Block ID No.



VI. REASSEMBLE VEHICLE (Engine Replacement NOT Necessary)




1. INSTALL CENTER No. 4 ENGINE UNDER COVER

a. Install the center No. 4 engine under cover with the 4 screws.

The Campaign is now complete. Return the vehicle to the customer.

VII. ENGINE REPLACEMENT



1. **INSTALL CENTER No. 4 ENGINE UNDER COVER**
 - a. Install the center No. 4 engine under cover with the 4 screws.

2. **ADVISE SERVICE MANAGER**

Advise your Service Manager about this vehicle's need for engine replacement. The Engine Replacement repair is currently not available. When available, instructions will be provided to complete this repair. At this time, it's critical to discuss this vehicle with your Service Manager to insure the customer is correctly informed of their options.

Safety Recall 20LA02 Dealer Letter will provide details to discuss with the customer:

[Safety Recall 20LA02 Dealer Letter](#)

◀ VERIFY REPAIR QUALITY ▶

- Confirm the Center No. 4 Engine Under Cover has been properly installed.
- If Engine replacement is required, be sure the Service Manager has been properly informed and the customer has been informed of their options.

If you have any questions regarding this update, please contact your area representative.

VIII. APPENDIX

A. PARTS DISPOSAL

In accordance with Federal law, please make sure all recalled parts (original parts) removed from the vehicle are disposed of in a manner in which they will not be reused, **unless requested for parts recovery return.**

B. CAMPAIGN DESIGNATION DECORDER

