

H283NAS1

TECHNICAL BULLETIN

26 JUN 2020



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Jaguar service facility to determine whether this bulletin applies to a specific vehicle.

SECTION:

310-01

SUBJECT/CONCERN:

SAFETY RECALL: Fuel Tank Outlet Flange

AFFECTED VEHICLE RANGE:

MODEL:	MODEL YEAR:	VIN:	APPLICABILITY:
XF (X250)	2010	R46314-R73338	V8 N/A 4.2L Petrol

MARKETS:

CANADA, USA

CONDITION SUMMARY:

SITUATION:

An issue has been identified on certain Jaguar vehicles within the listed Affected Vehicle Range where fuel odor has been reported, the amber Malfunction Indicator Lamp on the Instrument Cluster illuminates, and occasionally liquid fuel is on the ground. On investigation, technicians are finding that the fuel outlet flange mounted in the fuel tank is cracked.

The driver may also experience fuel odor and in some circumstances, with the vehicle static, there could be liquid fuel underneath the rear of the vehicle, which in the presence of an ignition source could lead to a fire.

ACTION:

Retailers are required to HOLD affected new vehicles that are within your control and refrain from releasing the vehicles for new vehicle sale pending completion of the procedure(s) detailed in this Technical Bulletin. Unsold vehicles should have this performed as part of the Pre-Delivery Inspection (PDI) process but must have it completed prior to vehicle handover to the customer.

Affected vehicles already in the hands of customers should be updated at the next available opportunity.

PARTS INFORMATION:

NOTES:

- Order only the expected percentage demand of parts as identified.
- Use the Vehicle Identification Number (VIN) and the Electronic Parts Catalogue (EPC) to confirm part number(s) necessary to perform repairs.

DESCRIPTION	PART NUMBER	QUANTITY	EXPECTED PERCENTAGE DEMAND
Fuel tank outlet flange	C2D25076	1	100
Fuel tank outlet flange - O-ring	C2Z7361	1	100

WARRANTY INFORMATION:

NOTE:

Use the Jaguar Land Rover claims submission system to make sure that a vehicle is eligible for this program prior to undertaking any rework action.

At the time of confirming a booking for vehicle repair, make sure that all open Recall and Service Actions are identified to make sure the correct parts are available and adequate workshop time is allocated for repairs to be completed at one visit.

Warranty claims must be submitted quoting the Program Code and the relevant Option Code; this will result in payment of the stated time. The SRO and parts information is included for information only. The Option Code(s) that allows for the drive in/drive out allowance may only be claimed if the vehicle is brought back into the workshop for this action alone to be undertaken. Repair procedures are under constant review and therefore times/prices are subject to change; those quoted here must be taken as guidance only. Use TOPIx to obtain the latest repair time. Warranty claims must be submitted or payment within 30 calendar days of completion of the repair.

PROGRAM CODE	OPTION CODE	DESCRIPTION	SRO	TIME (HOURS)	PART NUMBER	QUANTITY
H283	A	Fuel tank outlet flange - Renew	19.55.24	0.6	C2D25076	1
					C2Z7361	1
		Read and clear Diagnostic Trouble Code(s) (DTC)	85.18.06	0.2	-	-
H283	B	Fuel tank outlet flange - Renew	19.55.24	0.6	C2D25076	1
					C2Z7361	1
		Read and clear <u>DTC</u> Drive in/drive out	85.18.06 10.10.10	0.2 0.2	- -	- -

Normal Warranty policies and procedures apply.

SERVICE INSTRUCTION:

1.

NOTE:

Fuel pump fuse F25 is located in the luggage compartment junction box. Refer to the Owner's Manual for further information.

Remove and discard the fuel tank outlet flange (see TOPIx Workshop Manual section 310-01: Removal and Installation - Fuel Pump Driver Module - Removal steps 1-9).

2.

NOTE:

Make sure to install a new fuel tank outlet flange O-ring.

Install the new fuel tank outlet flange (see TOPIx Workshop Manual section 310-01: Removal and Installation - Fuel Pump Driver Module - Reverse removal steps 1-9).

3. Use the Jaguar Land Rover-approved diagnostic equipment to read and clear any stored **DTC**.