

# RECALL CAMPAIGN

CR5136ER1

REFERENCE:	Nova Bus Manuals
SECTION:	09: Engine and Cooling
RS Nº:	MQR 7621-2169
EFFECTIVE IN PROD.:	N/A
TC RECALL N°:	2021-568
NHTSA RECALL N°:	20V568

APPLICATION DEADLINE: NA
CLAIM REFERENCE NUMBER: SR-5136

SUBJECT:	Power Steering
JUSTIFICATION:	Certain power steering pipes may separate at the connection joint. This may cause a power steering assist lost and power steering fluid spillage from the ceiling in the cabin.

LEVEL	DESCRIPTION	DIRECT CHARGES		TIME
	DESCRIPTION	LABOUR	MATERIAL	IIIVIE
1	Replace hydraulic pipe N77549-01.	Nova Bus	Nova Bus	10.5 h
2	-	_	_	_

## Matérial list on page 2

#### **DISPOSAL OF PARTS**

REMOVED PARTS ARE:	DISCARDED *	RETAINED	* Dispose of the unused parts and the defective parts in
	Yes	-	accordance with local environmental standards in effect.

#### **REVISION HISTORY**

REVIOLOGY IIIO TORY					
REV.	DATE	CHANGE DESCRIPTION	WRITTEN BY		
NR	2021OC22	Initial release	Annie St-Jacques		
		- Material list on page 2 of 10.			
R1	2022FE18	- Shop supply added in material list.	Annie St-Jacques		
		- Steps 1.35.f and 1.37.g added.			

APPROVED BY: PAGE 1 OF 10




### **MATERIAL**

QTY	PART N°	REV.	DESCRIPTION	REPLACES PART N°		
LEVEL 1						
2	G5007995	_	CABLE TIE (PRV# 504637)	_		
2	N26360	С	TUBE INSULATION 5/8" (6 FT)	_		
1	N77549-01	_	PIPE SUPPLY ASSY STEEL	_		
LEVEL 1	LEVEL 1 - SHOP SUPPLY					
3 Li	HYDRAULIC OIL		A MAXIMUM OF 3 LITERS OF HYDRAULIC OIL WILL BE REFUNDABLE UPON CLAIM.	_		
65 ml	N35535-01	_	SIKAFLEX 552 AEROGRAY DARK/400* (1 sausage = 400 ml)	-		
*SPECIFY THE QUANTITY REQUIRED ACCORDING TO YOUR NUMBER OF VEHICLE.						
LEVEL 2						
_	_	_	_	_		

Materials will be available within 105 days once your order has been placed. To order, please contact novabus.parts@volvo.com or by phone for CANADA 1-800-771-6682, for USA 1-877-999-8808. Specify document number, quantity of parts required and shipping address.

CLIENT	ODDED	ROAD NUMBER		VIN (2NVY/4RKY)		OTV
CLIENT	ORDER	FROM	то	FROM	то	QTY
San Antonio Texas - VIA	LD11	726	738	L82K1L97775	L82K8L97775	13
San Antonio Texas - VIA	LD12	988	989	L82KXL97775	L82K1L97775	2
San Antonio Texas - VIA	LD13	739	747	L82K4L97776	L82K4L97776	9





FOLLOW YOUR INTERNAL SAFETY PROCEDURES.

## **PROCEDURE**



NOTE

Your configuration may differ.



NOTE

Unless otherwise specified retain the hardware removed during the procedure for later reinstallation.

### PREPARE VEHICLE

- Park the vehicle on a level surface with the transmission on neutral.
- Apply the parking brake and set the master control switch to the stop position.
- 1.3. Set the battery disconnect switch in the battery compartment to the off position and lock out the switch.

### DRAIN HYDRAULIC OIL



NOTE

Refer to the maintenance manual, section 09: Engine and Cooling, for HYDRAULIC OIL DRAIN PROCEDURE.

- 1.4. Open the rear engine access door. Locate the hydraulic reservoir and place a clean container to recover the oil (Figure 1).
- 1.5. Drain the oil. Keep the oil, it will be reused to fill the reservoir after the work has been completed.
- Open the right front access door, locate the drain plug on the 90 deg fitting and place a clean container under it (Figure 2).
- 1.7. Remove plug and drain the remaining oil from the pipe. Keep the oil, it will be reused to fill the reservoir after the work has been completed.



Figure 1 - Place Container to Collect Hydraulic Oil




Figure 2 - Place Container to Collect Remaining Hydraulic Oil

## **HYDRAULIC PIPE N77549-01**

#### **GET ACCESS**

- 1.8. Inside the vehicle behind the driver's partition remove the transversal seat on the wheelhouse.
  - a. Disconnect any electrical connection underneath the seat.
  - b. Unscrew the 8 screws and remove the seat. Be careful that the spacers between the fibreglass wheelhouse and the stainless wheelhouse do not fall in between. **Note their positions for reinstallation.**
  - c. Keep the 8 screws, the 8 lock washers, the 8 washers and the spacers (quantity and spacer height depend of your vehicle).



- 1.9. Next to the ceiling, to access the hydraulic pipe N77549-01 (Figure 3), remove as needed:
  - a. Access panel
  - b. Curtains
  - c. Fluorescent light. If needed, loosen the top of the windows clamping.
- 1.10. Remove the chime (Figure 3).
  - a. Unscrew the 4 screws to remove the chime cover.
  - b. Disconnect the 2 rounds terminals.
  - Unscrew the 2 mounting screws and remove the chime (to not lose the spacers behind the chime, do not
    pull out the screws completely).
- 1.11. Remove the chime cord (Figure 3).
  - a. Unscrew the screws above and below and remove the cover.
  - b. Disconnect the 2 round terminals.
  - c. Unscrew the 2 mounting locknuts and remove the module and the cord.




Figure 3 - Components to remove

- 1.12. Remove the upper/wall seat rail (Figure 4).
  - a. Cut sealant at each end.
  - b. Unscrew the 3 M10 bolts with a manual tool to avoid spinning the rivnuts.
  - c. Keep the rail, the 3 M10 bolts and the 3 rectangular retainers.
  - 1.13. Remove the air duct plate (Figure 4).
  - 1.14. Remove the lower/floor seat rail (Figure 4).
    - a. Cut sealant at each end.
    - b. Underneath the vehicle, unscrew the 3 nuts.
    - c. Keep the rail, the 3 bolts, the 3 square plates, the 3 washers and the 3 nuts.



- 1.15. Remove the melamine panels
  - Remove the melamine panel between the windows. If needed, loosen the windows clamping (the melamine panel is fragile, especially the corners).
  - b. Remove the trim and the lower melamine panel.




Figure 4 - Components to remove

#### REMOVE HYDRAULIC PIPE N77549-01

- 1.16. Locate hydraulic pipe N77549-01 (Figure 5).
- 1.17. Remove the 2 support brackets.
- 1.18. In order to remove the hydraulic pipe N77549-01, it is necessary to first remove the return hydraulic pipe located next to it because of the presence of the chime cord mounting plate.
  - a. Disconnect the ORS fitting at each end of both pipes (note: a small amount of oil will pour).
  - b. Remove the return pipe.
  - c. Remove the pipe N77549-01.

#### **INSTALL NEW HYDRAULIC PIPE N77549-01**

- 1.19. Install new insulation N26360 on the new hydraulic pipe N77549-01 as on the old one.
- Install the pipe N77549-01 in the vehicle and hand tighten the ORS fittings.
- Reinstall the return hydraulic pipe and hand tighten the ORS fittings.
- 1.22. Tighten the 4 ORS fittings to the torque value of 48 lb-ft (65 N·m).



Refer to the maintenance manual, section 99: General Practices, for ORS-TYPE FITTING INSTALLATION.

- 1.23. Reinstall the 2 support brackets.
- 1.24. Discard the old hydraulic pipe N77549-01.






Figure 5 - Hydraulic Pipe N77549-01

## REFILL HYDRAULIC RESERVOIR



Refer to the maintenance manual, section 09: Engine and Cooling, for HYDRAULIC OIL FILLING PROCEDURE.

- 1.25. Fill the hydraulic oil reservoir to the required level.
- 1.26. Start the vehicle and turn the steering wheel back and forth.
- 1.27. Inspect pipe N77549-01 and return pipe connections to ensure there are no leaks.
- 1.28. Stop the engine.



## CLEAN AND CLOSE

#### CLEAN

1.29. Clean any excess oil.

#### **CLOSE ACCESS**

- 1.30. Reinstall the melamine panels and the between trim (don't forget to pass thru any electrical cables).
- 1.31. Reinstall the chime cord.
  - a. Pass the electrical cable thru the pass hole.
  - Insert the module onto the mounting screw and tighten with the M5 locknut.
  - c. Reconnect the 2 round terminals, the white wire to the top contact and the black wire to the bottom contact.
  - d. Reinstall the cover with its 2 screws.
- 1.32. Reinstall the chime.
  - a. Pass the electrical cable thru the pass hole.
  - b. Apply new thread locker, Loctite 242 (Nova Bus #9985283) or equivalent, on the two M5 x 25 mm screws. Reinstall chime on the wall with the two 1/2 in. spacers.
  - c. Reconnect the 2 terminals to the terminal strip.
  - d. Reinstall cover with the 4 screws.
- 1.33. Reinstall the first fluorescent light, the curtains and the access panel.
- 1.34. If the windows clamping was loosened torque the screws.



#### NOTE

Refer to the maintenance manual, section 03: Windows, Windshield and Accessories, for the TORQUE SEQUENCE AND VALUE.

- 1.35. Reinstall the floor rail in the same position with the removed hardware: 3 M10 mushroom square bolts, 3 square plates, 3 M10 oversize washers and 3 M10 nuts.
  - a. Clean the 3 bolts to remove any old anti-seize compound and dirt.
  - b. Reinsert the 3 bolts and the 3 square plates into the rail.
  - c. Put the rail in place inserting the bolts into the floor. Position the rail like before.
  - d. Underneath the vehicle, apply new anti-seize compound, NeverSeez (Nova Bus #R085023) or equivalent, on bolts and install the 3 washers and the 3 nuts.
  - e. Torque the nuts to the torque value show in Figure 6 and apply torque seal on nuts.
  - f. Apply sealant Sikaflex 552 N35535-01 to both ends of the rail to fill in the gaps.
- 1.36. Reinstall the air duct plate.
- 1.37. Reinstall the upper/wall rail with the removed hardware: 3 M10 screws and 3 rectangular retainers.
  - a. Clean the screws and the rivnuts to remove the old thread locker.
  - Apply new thread locker, Loctite 242 (Nova Bus #9985283) or equivalent, on screws.
  - c. Install the rail with the 3 rectangular retainers and the 3 screws. Hand tighten.
  - d. From the rear to the front, make a first tightening to the torque value shown in Figure 7.
  - e. Again from the rear to the front make a second tightening to the same torque value.
  - f. Apply torque seal on bolts.
  - g. Apply sealant Sikaflex 552 N35535-01 to both ends of the rail to fill in the gaps.






Figure 6 - Lower/Floor Seat Rail




Figure 7 - Upper/Wall Seat Rail

#### 1.38. Reinstall the transversal seat.

- a. Reinstall the spacers to their original position. To ease the installation, the spacers can be temporarily glued with cyanoacrylate adhesive Loctite 414 (Nova Bus #9985337) or equivalent.
- b. Reinstall seat and secure with the 8 washers, the 8 lock washers and the 8 screws.
- c. Torque the screws to the torque value shown in Figure 8.
- Apply torque seal on screws.
- e. If applicable, reconnect any electrical connection and secure with cable ties.
- 1.39. The vehicle can return in service. .






Figure 8 - Torque to Apply for Transversal Seat (Typical)