

**TITLE: 2018~2020 NINJA H2™ SX, SX SE & SX SE+  
GEAR MISENGAGEMENT MAY CAUSE TRANSMISSION DAMAGE****RECALL****THIS BULLETIN IS OF THE HIGHEST PRIORITY AND MUST BE ACTED UPON IMMEDIATELY  
TO ENSURE CUSTOMER SAFETY.****Eligibility****Eligible Units**

Year	Model	Model Codes
2018	NINJA H2 SX	ZX1002AJFL
	NINJA H2 SX	ZX1002AJF
	NINJA H2 SX SE	ZX1002BJF
	NINJA H2 SX SE	ZX1002BJFL
2019	NINJA H2 SX SE+	ZX1002DKF
	NINJA H2 SX SE+	ZX1002DKFL
2020	NINJA H2 SX SE+	ZX1002DLF
	NINJA H2 SX SE+	ZX1002DLFL

**Verify eligibility using VIP in K-Dealer before starting the repair.**

Please check VIP (Vehicle Information Portal) in K-Dealer for other possible repair campaigns for eligible units.

**Subject**

On affected units, if the transmission gears are not properly engaged while shifting into 4th or 5th gear, high engine RPM can cause the output gears of 4th or 5th gear to fracture when the gears re-engage. The engine control program of the electronic control unit (ECU) doesn't have the capability to suppress high RPM during transmission gear misengagement, allowing this problem to occur. Jamming of broken gears can cause the engine to lock up, increasing the risk of a crash.

**Kawasaki Action****Initiate Campaign:**

Kawasaki has initiated a Recall campaign to repair all eligible units. The repair consists of reprogramming the ECU. Reprogramming will not affect vehicle performance or emission levels.

**Notify Registered Owners:**

Kawasaki is sending a Recall letter to all registered owners of eligible units. A copy of the letter is printed on page 17 of this bulletin.

**Dealer Action****Repair Eligible Units:**

Repair all eligible units including sold units in the field and unsold units in your dealership inventory prior to delivery to the retail purchaser. It is the obligation of authorized Kawasaki retail Dealers to repair eligible units in Dealer's possession prior to retail sale. Failure to comply with this obligation to repair all units eligible for Recall or FDM campaigns by the Dealer constitutes a breach of the Dealer Sales and Service Agreement. Refer to Service Policies bulletin SP 08-01. Refer to the Repair Procedure section of this bulletin for details.

**IMPORTANT NOTE:**

- o *It's the law! Under the U.S. National Highway Traffic Safety Administration (NHTSA), Federal Law 49 U.S.C. Section 30120(i) requires dealers to perform Recall repairs before delivering any vehicle affected by the Recall to a purchaser.*

**Document Completed Repairs:**

Federal law requires manufacturers to maintain accurate follow-up records on repairs performed on eligible units. Dealers MUST submit a Warranty Claim for each repair. Refer to the Warranty Information section of this bulletin for details.

**NOTE:**

- o *If you fail to submit a Warranty Claim for a new unit that is subsequently sold and registered, the new owner will receive the Recall letter requesting the return of the vehicle to you for repair.*

**Submit Product Registration:**

Submit the product registration to Kawasaki via K-Dealer immediately after retail sale of any eligible unit. Be sure to supply the correct customer name and mailing address. Kawasaki uses the product registration information for customer notification. Also, if you know that the customer has moved, please submit a Customer Update via K-Dealer.

**Parts Information**

This repair procedure does not require any repair kit parts.

**Special Tool Requirements**

This repair procedure requires the following special tools

- KVCS Kit
- Computer or lap top with Windows 8.1 or 10 installed
- Computer or laptop with KVCS installed
- Internet connection

**ECU Reprogramming Sequence**

Reprogramming consists of four main procedures. All steps must be completed to successfully reprogram the ECU:

**1. SAVE VEHICLE ECU DATA FROM VEHICLE TO KVCI DEVICE**

- Connect KVCI device to vehicle
- Save ECU Data on the KVCI device
- Disconnect KVCI device from vehicle

**2. DOWNLOAD REPROGRAMMING DATA FROM SERVER TO KVCI DEVICE**

- Start KVCS software
- Connect KVCI device to laptop or computer running KVCS
- Search available programming data
- Download reprogramming data
- Confirm download
- Remove KVCI device from laptop or computer

**3. WRITE NEW PROGRAMMING DATA TO VEHICLE ECU**

- Connect KVCI device to vehicle
- Write new programming data to ECU
- Verify reprogramming
- Remove KVCI device from vehicle
- Start vehicle to verify that there are no error lamps illuminated

**4. REPORT REPROGRAMMING TO KAWASAKI SERVER**

- Connect KVCI device to laptop or computer
- Report reprogramming to Kawasaki server
- Confirm "0 unreported items"
- Remove KVCI device from laptop or computer

**REPROGRAMMING COMPLETE**

## ECU Reprogramming

### ECU REPROGRAMMING VIDEO TUTORIAL:

- o PLEASE WATCH THIS VIDEO PRIOR TO REPROGRAMMING THE ECU.
- o OPEN THIS BULLETIN IN K-DEALER TO CLICK ON THE BUTTON TO VIEW THE VIDEO



### IMPORTANT NOTES:

- o The vehicle's battery voltage must be greater than 10.5 Volts to perform this procedure. Do not attempt to reprogram the ECU if the battery voltage is below 10.5 Volts. Charge the battery as required.
- o This procedure requires an internet connection and a computer with KVCS installed.

### Save Vehicle ECU Data

- Connect cable **57001-1843** to the KVCI device.

#### NOTE:

- o Only the KVCI device and the vehicle will be connected to each other while saving the vehicle ECU data.
- Confirm the **power switch** on the KVCI device is in the **OFF** position.



- Remove the passenger seat and locate the KVCS connectors next to the fuse box.



## ECU Reprogramming (cont'd)

- Remove the cover from the FI ECU connector. It is the six pin connector with the light blue wire.



- Connect KVICI device to vehicle's white, **six pin FI ECU connector**, using cable **57001-1843**.
- Turn the **ignition switch ON** but do not start the vehicle.
- Wait 5 seconds.



- Slide the **power switch** on the KVICI device to the **ON** position.



- Wait 10 seconds for the KVICI device to power up and connect with the vehicle ECU. The flashing blue light under the motorcycle icon indicates the device is ready.
- Press the **A button** on the KVICI device.



## ECU Reprogramming (cont'd)

- The **Main Menu** appears.
- Press the **A** button to select **Refresh**.



-The **Battery Terminal Voltage** screen will appear.

- ★ If the battery voltage is below 10.5 V, stop this procedure. Charge the battery and begin at step one again.
- ★ If the battery voltage is greater than 10.5 V, proceed to the next step.




- Press the A button to open the Menu.
- Press the **A** button again when the Menu screen appears with **Save vehicle ECU data** as the option.



- Verify that the message **Downloading Vehicle ECU Data** is displayed.

- ★ If the “**Downloading Vehicle ECU Data**” screen does not appear shut down and start over.



- Confirm the downloaded vehicle ECU data on the **Completion of Vehicle ECU Data** screen.

ECU #	21175-XXXX
Cal ID	49245-XXXX
VIN	FRAME NUMBER

- ★ If the ECU VIN is different from the FRAME VIN, use the FRAME VIN in the warranty request.



## ECU Reprogramming (cont'd)

- Slide the mode switch of KVIC device to the **OFF** position.



- Turn the ignition switch to the **OFF** position and wait ten seconds before proceeding to the next step,



### NOTICE

Turn the ignition switch of the vehicle to the **OFF** position, wait for 10 seconds, and then release the connection between the KVIC device and the vehicle. If you release the connection while power is still being supplied the KVIC device may fail.

- Remove the KVIC device from the vehicle.

### Download Reprogramming Data

- Connect KVIC device to your KVCS equipped computer with **USB cable 57001-1844**.

#### NOTE:

- Only the KVIC device and the computer running KVCS will be connected to each other while downloading the reprogramming data from the server.*



- Slide the power switch on the KVIC device to the **ON** position.
- Wait 10 seconds.




- Launch the **KVCS** program on the laptop or PC.



## ECU Reprogramming (cont'd)


- Select **ECU Reflash**.




- Confirm ECU data in the “**Vehicle ECU Data**” field.
- WRITE DOWN THE VIN TO BE ENTERED LATER DURING THE PROCEDURE.**
- Click on the **Search Reprogramming Data** button.

**NOTE:**

*This may take several minutes depending on the speed of the internet connection.*



- Select **United States** as the Region.
- Enter your KVCS Dealer Code and Password then click the **Login** button. (Call Kawasaki Dealer Care at (800) 854-3800 if you do not have your dealer code and password.)
- Verify the reprogramming data for the vehicle based on the following tables:





ZX1002A		
ECU P/N	CallID	Note
21175-1343	49245-1859	USA
21175-1340	49245-1857	L Model

ZX1002B		
ECU P/N	CallID	Note
21175-1351	49245-1867	USA
21175-1346	49245-1862	L Model


ZX1002D		
ECU P/N	CallID	Note
21175-1476	49245-1877	USA
21175-1471	49245-1873	L Model

- Click on the **DL** button to download the vehicle data.



## ECU Reprogramming (cont'd)

- When the download is complete, the **Confirm Download** screen will appear.




- Enter the **VIN** on the vehicle frame in the VIN field.
- Click on the **Continue** button.

- The **Proceed to VIN Verification** message will appear if the correct VIN is entered.
- Click on the **OK** button.
- Proceed to page 8 of this bulletin and resume at the **Activation Code** step.



**The following screens will only appear if the VIN was entered incorrectly or the wrong VIN was entered. Proceed to ACTIVATION CODE on page 8 if the VIN is correct.**

- ★ If VIN is not entered or VIN format is incorrect, error message is displayed. Please enter VIN stamped on the vehicle frame and click **Continue** again.



## ECU Reprogramming (cont'd)

- ★ If the VIN entered does not match with ECU VIN, an error message is displayed. If the entered VIN is incorrect, please enter the correct VIN stamped on the vehicle frame and click **Verify again**.

The screenshot shows a web interface titled "Confirm Download". At the top, a red-bordered box contains the error message: "VIN entered does not match with ECU VIN." Below this is an image of a motorcycle with a callout 'A' pointing to the VIN plate on the frame. Underneath the image, the text reads: "A VIN (Frame Number)" and "Double check the VIN on the vehicle frame matches the VIN entered." At the bottom, there is a "VIN" input field, a "Verify again" button (highlighted with a red box), and a "VIN entered is correct." button.

- ★ If VIN entered is correct, please click **VIN entered is correct**. Reprogramming can be done even if the VINs do not match.

This screenshot shows the same "Confirm Download" screen as above, but the "VIN entered is correct." button is highlighted with a red box, indicating the correct action to take when the VIN matches.

- ★ If the message **The VIN entered does not match the ECU VIN. Proceed to download the reprogramming data with the VIN entered?** is displayed, click on the **OK** button.

A dialog box titled "Message from webpage" is shown. It contains a question mark icon and the text: "The VIN entered does not match the ECU VIN. Proceed to download the reprogramming data with the VIN entered?". At the bottom, there are two buttons: "OK" (highlighted with a red box) and "Cancel".

### Activation Code

- A new screen will appear that has a field to enter the **Activation Code**.
- Enter Activation Code **DAJ430A** then click on the **Certification** button. (Activation code **DAJ430A** is used for all vehicles for this step.)


The screenshot shows the "ECU Reflash" screen. At the top, it says "ECU Reflash" and "Confirm Download". Below this is a list of fields: "ECU P/No. : 21175-xxxx", "CallID : 49245-xxxx", "Applicable ECU Part Number : 21175-xxxx", "Remarks : DAJxxxx", "Notes : This is an important ECU update for this vehicle. ECU must be updated before performing other ECU reprogramming.", and "Registration Date : xxxxxxxxxx". At the bottom, there is an "Activation Code" input field containing "DAJ430A" (highlighted with a red box) and a "Certification" button (also highlighted with a red box). A "Cancel" button is at the very bottom.

## ECU Reprogramming (cont'd)


- A confirmation dialog box will appear asking if you would like to authenticate the Activation Code. Click on the **OK** button.

### NOTE:

- This may take several minutes depending on the speed of the internet connection.*




- A checkmark  symbol will appear to the right of the activation code indicating that the correct code was used.
- Click on the **Download** button to initiate the download process.
- A confirmation dialog box will appear asking if you would like to download the program. Click on the **OK** button.




### NOTE:


- Downloading may take several minutes depending on the speed of the internet connection.*




- A progress bar will indicate the progress of the download. It may take a few seconds before the progress bar begins to display in green. If the progress bar does not appear, minimize then maximize KVCS to refresh.



- When the download is complete, the bar will disappear and information of reprogramming data will be displayed in the **Reprogramming Data** field.



- Click on the  button next to the image of the KVCI device.



- Slide the power switch on the KVCI device to the **OFF** position.
- Disconnect the KVCI device from the PC.
- Close the KVCS software.



## ECU Reprogramming (cont'd)

### Write Reprogramming Data to ECU

- Connect cable 57001-1843 to the KVCI device.


#### NOTE:

- o *Only the KVCI device and the vehicle will be connected to each other while saving the vehicle ECU data.*

- Verify the power switch on the KVCI device is in the OFF position.



- Connect KVCI device to vehicle's white, six pin FI ECU coupler, using cable 57001-1843.



- Turn the ignition switch **ON** but do not start the vehicle.
- Wait 5 seconds.



- Slide the power switch on the KVCI device to the **ON** position and wait approximately 10 seconds for the device to connect with vehicle ECU. The flashing blue light under the motorcycle icon indicates the device is ready



- Press the **A** button on the KVCI device.
- The Main Menu appears.
- Press the A button.



- The **Battery Terminal Voltage** screen will appear.
- Press the **A** button.



## ECU Reprogramming (cont'd)

- The KVC1 **Menu** is displayed.
- Use the down arrow key on the KVC1 device to select **Reprogram Vehicle ECU**.
- Press the **A** button.



- Confirm the downloaded **Reprogramming data for rewriting**.

Name	Description
ECU P/No	21175-XXXX
Cal ID	49245-XXXX
Remarks	Displayed reference information such as contents of program.
VIN	Frame Number



- During the reprogramming, the **Reprogramming in Progress** status is displayed as a percentage and the green light under the  symbol on the KVC1 device flashes.

### NOTE:

- o *This may take several minutes depending on the speed of the internet connection.*

### NOTE:

- o *The ECU will not be recognized during reprogramming and the warning lamp will be blinking. It will return to its original display state when the reprogramming is complete.*



### IMPORTANT NOTE:

- o *WAIT FOR THE **Completion of Reprogramming** SCREEN TO APPEAR BEFORE TURNING OFF THE KVC1 DEVICE OR THE VEHICLE IGNITION SWITCH. TURNING THE POWER OFF TOO SOON WILL RESULT IN INCOMPLETE REPROGRAMMING.*

- When the reprogramming is complete, the **Completion of Reprogramming** window opens.
- **DON'T PRESS ANY BUTTONS ON THE KVC1 DEVICE.**




## ECU Reprogramming (cont'd)

- ★ If you receive a message on the KVIC device with the message “**There is a possibility that the previous reprogramming did not finish properly. Would you like to run the recovery process?**” you will need to perform the recovery process. Select **YES** then press the **A** button to perform the recovery process. Otherwise, proceed to the next step below.

### IMPORTANT NOTE:

- *WAIT FOR THE **Completion of Reprogramming** SCREEN TO APPEAR BEFORE TURNING OFF THE KVIC DEVICE OR THE VEHICLE IGNITION SWITCH. TURNING THE POWER OFF TOO SOON WILL RESULT IN INCOMPLETE REPROGRAMMING.*



- Slide the mode switch of Kawasaki Smart VCI to the **OFF** position only when the **Completion of Reprogramming** screen is displayed.



### NOTICE


Turn the ignition switch of the vehicle to the **OFF** position, wait for around 10 seconds, and then release the connection between Kawasaki Smart VCI and the vehicle. If you release the connection while power is still being supplied, Kawasaki Smart VCI may fail.

- Turn the ignition switch to the **OFF** position.

### NOTE:

- *The engine light will be flashing during reprogramming. This is normal.*

- Remove Kawasaki Smart VCI from the vehicle.
- Start the vehicle and verify that the engine light is not flashing.
- Turn the ignition switch to the **OFF** position.




## Reporting the Vehicle ECU Reprogramming to the Server

- Launch the KVCS software.


### NOTE:

- o Only the KVIC device and the computer running KVCS will be connected to each other while downloading the reprogramming data from the server.


- Select **ECU Reflash**.
- Connect the KVIC device to the computer with the USB cable.
- Slide the power KVIC device power switch to the **ON** position.
- Wait 10 seconds.




- On the KVCS software select **Report** on the **Reprogramming Completion Report** column.
  - ★ If the **Unreported 0 Items** is displayed on the **Reprogramming Completion Report** column, ECU reprogramming is not finished completely. Please perform the reprogramming process again. (Click on the **Search History** button to display all reported items.)
  - ★ If the **Unreported 1 Items** is displayed on the **Reprogramming Completion Report** column, ECU reprogramming is complete.
- Click on the **Report** button only if **Unreported 1 Items** is displayed.



- Enter **MC20-10** in the Remarks field.



- Click on the **OK** button on the **Would you like to report the results?** screen.



## ECU Reprogramming (cont'd)

- Click on the  button at the bottom of the page displaying “Reported to server”.




- Confirm **Unreported 0 Items** is displayed on the **Reprogramming Completion Report** column.
- If **Unreported 1 item** is displayed on the **Reprogramming Completion Report**, Reporting is not finished completely. Please report the download vehicle ECU Data to the server again.

### NOTE:

- If there are unreported vehicle ECU data, you cannot download another reprogramming data. After reporting the downloaded vehicle ECU data to the server, please download other unit's reprogramming data and write the reprogramming data.*

- Slide the mode switch of KVCI device to the **OFF** position.
- Remove KVCI device from the PC.




**ECU REPROGRAMMING IS NOW COMPLETE**

## Warranty Information

This is a safety Recall campaign. Repair is authorized regardless of ownership or warranty status.

Repairs **MUST BE PERFORMED IMMEDIATELY ON ALL ELIGIBLE UNITS** in the field and during initial assembly and preparation.

See the Warranty Policies and Procedures Manual (claim type 3 information) for detailed instructions when submitting the Warranty Claim.

<b>Reprogram ECU</b>	
Job Code	22532
Flat Rate Time	0.3
Claim Type	3
Part Number	99999-0788
Description	KIT
Quantity	0

## Repair Verification

- Make a white paint mark on the rear of the frame as shown to serve as repair verification.

**NOTE:**

- o *Repair verification is an essential part of the repair procedure. Along with the physical repair verification, check VIP (Vehicle Information Portal) in K-Dealer for other possible repair campaigns for eligible units.*



**2018~2020 NINJA H2™ SX, SX SE, SX SE+  
GEAR MISENGAGEMENT MAY CAUSE TRANSMISSION DAMAGE**

**IMPORTANT SAFETY RECALL  
NHTSA RECALL NO. 20V-676**

Dear Kawasaki Motorcycle Owner:

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act. Kawasaki Motors Corp., U.S.A., has decided that a defect which relates to motor vehicle safety exists in certain 2018~2020 NINJA H2 SX, SX SE, SX SE+ models.

**The reason for this notice:**

On affected units, if the transmission gears are not properly engaged while shifting into 4th or 5th gear, high engine RPM can cause the output gears of 4th or 5th gear to fracture when the gears re-engage. The engine control program of the electronic control unit (ECU) doesn't have the capability to suppress high RPM during transmission gear misengagement, allowing this problem to occur. Jamming of broken gears can cause the engine to lock up, increasing the risk of a crash. Our records indicate that you have purchased one of these units.

**What Kawasaki and your dealer will do:**

Kawasaki has authorized your dealer to reprogram the ECU on your motorcycle free of charge. Reprogramming will not affect vehicle performance or emission levels. The actual repair will take up to twenty minutes but may take longer due to scheduling at the dealership.

**What should you do to ensure your safety?**

Please call your Kawasaki dealer to schedule an appointment to have your motorcycle inspected and repaired as required. Please have your Vehicle Identification Number (VIN) ready when calling. To locate the nearest authorized Kawasaki motorcycle dealer, please visit [www.kawasaki.com](http://www.kawasaki.com) and click on the "LOCATE DEALER" link. If you are unable to transport your motorcycle to your nearest Kawasaki dealer, please contact Kawasaki Motors Corp., U.S.A. to make arrangements for the transportation and repair of your motorcycle. The transportation and repair will be conducted with no cost to you.

**DO NOT RIDE YOUR MOTORCYCLE UNTIL THE REPAIR HAS BEEN COMPLETED.**

**If you need help:**

If you have questions or concerns that your dealer is not able to resolve, please contact Kawasaki Customer Care at (866) 802-9381 (toll-free) between 7:00 a.m. and 4:00 p.m. PT Monday through Friday. Please have your Vehicle Identification Number ready when calling.

If your dealer fails or is unable to remedy this defect without charge within a reasonable amount of time (60 days after your first attempt to obtain remedy), you may submit a written complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave. S.E., Washington, D.C. 20590, or call the toll-free Vehicle Safety Hotline at 1(888) 327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

**If you received this notice in error:**

Our records indicate you are the current owner of the motorcycle described in this letter. If you no longer have the vehicle described in this letter, please help us to update our records at [www.kawasaki.com](http://www.kawasaki.com) by clicking on "OWNER CENTER => KAWASAKI SUPPORT => UPDATE OWNER INFO" or by calling Kawasaki toll free at (866) 802-9381. Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

**Reimbursement:**

If you have experienced the failure described above prior to receiving this letter and have paid to have it corrected, you may be eligible for full or partial reimbursement for your documented cost of repair(s). To apply for reimbursement, please send copies of current owner and VIN information along with copies of repair orders and payment confirmation to the following address:

Kawasaki Motors Corp., U.S.A.  
ATTN: Customer Care  
P.O. Box 25252  
Santa Ana, California 92799-5252

**Please note the following conditions for reimbursement:**

Claims may be excluded if proper documentation is not included. Current owner and VIN information along with copies of repair orders and payment confirmation must be provided.

We are sorry for any inconvenience this may cause, but we have taken this action in the interest of your safety and your continued satisfaction with your Kawasaki motorcycle.

Sincerely,

Kawasaki Motors Corp., U.S.A.