2021-02-19



SIB 12 01 21 **RECALL: CHECK 48 V CABLE CONNECTIONS ON STARTER** GENERATOR (SGR)

This Service Information Bulletin (Revision 1) replaces SI B12 01 21 dated February 2021.

What's New (Specific text highlighted):

Entire content except Model, Affected Vehicles

Please perform the procedure outlined in this Service Information on all affected vehicles before customer delivery. In the event the customer has already taken delivery of the vehicle, please perform the procedure the next time the vehicle is in the shop.

#### MODEL

| E-Series | Model Description          | Production Date                       |
|----------|----------------------------|---------------------------------------|
| G01      |                            | November 16, 2020 – November 30,      |
|          | X3 Sports Activity Vehicle | 2020                                  |
| G02      | X4 Sports Activity Coupe   | November 21, 2020                     |
| G05      | X5 Sports Activity Vehicle | September 30, 2020 – January 13, 2021 |
| G06      | X6 Sports Activity Coupe   | October 2, 2020 – December 1, 2020    |
| G07      | X7 Sports Activity Vehicle | October 1, 2020 – January 11, 2021    |
| G30      | 5 Series Sedan             | September 9, 2020                     |

### AFFECTED VEHICLES

Vehicles which require this Recall Campaign to be completed will show it as "Open" when checked either in AIR, the "Service Menu" of DCSnet (Dealer Communication System), ISPA Next or Warranty Vehicle Inquiry.

### SITUATION

BMW AG is conducting a Voluntary Safety Recall (effective February 12, 2021) on a small number of Model Year 2021 BMW vehicles that were produced between September 9, 2020 and January 13, 2021.

This is an expansion of recall 20V-761 that was launched in early December 2020.

The 48-Volt battery cable connections to the starter / generator (SGR) may not have been assembled to specifications. Over time, this could lead to increased resistance at the connection(s) and, in rare cases, a thermal event.


### CORRECTION

Check the M8 flange nuts and cable connections on the SGR. If necessary, replace the flange nut and torque to spec.

## PROCEDURE

Check the positive (1) and negative (2) cables for play at the mounting lugs on the SGR.

2/23/2021



If the connections are tight and the cables cannot be moved by hand-

• No further action is necessary

If there is play in the connection to the SGR -

- Deactivate the 48 V electrical system (Repair instruction REP-TAT-P-6124-18-B47\_48V)
- Remove and discard the flange nut on the B+ or B- cable
- Install a new flange nut so that it's carefully started by hand to avoid cross-threading
- Torque to 19 Nm

## PARTS INFORMATION

Only use and invoice the part numbers below that apply.

Performing a part number look-up in ETK (EPC) by VIN or model in place of using/invoicing the following part numbers may result with the wrong part numbers being invoiced and installed, this could delay the payment of the claim.

| Part Number   | Description               | Quantity |
|---------------|---------------------------|----------|
| 07 14 3413174 | Flange nut (rounds to 10) | Up to 2  |

## WARRANTY INFORMATION

Reimbursement for this Recall will be via normal claim entry utilizing the applicable work package information below, and when required, the part number listed above:

|--|--|

Completion before the first vehicle delivery to a customer or the vehicle is already in the workshop

| Work Pkg | Labor<br>Operation | Description (Plus work)   | Labor Allowance                          |
|----------|--------------------|---|--|
| # 1      | 00 70 743          | Checking the positive/negative battery cable and reworking if necessary | 3 FRU (G07);<br>4 FRU (G05, G06,<br>G30) |

Or:

The vehicle arrives at your center and this Recall shows open (No other main work will be performed or claimed during this workshop visit)

|   |     | Description (Main work)            |      |
|---|-----|------------------------------------|------|
| 1 | Сор | yright ©2021 BMW of North America, | Inc. |

| Work Pkg | Labor<br>Operation |  | Labor Allowance |
|----------|--------------------|--|-----------------|
| # 2      |                    | Checking the positive/negative battery<br>cable and reworking if necessary | 5 FRU (All)     |

Only one of the flat rate labor operation codes listed above can be used for claim submission and reimbursement. Also, only one Main work flat rate labor operation code can be claimed per workshop visit.

#### **Claim Repair Comments**

Only reference the SIB number and the work package (Pkg) number performed in the RO technician notes and the claim comments (For example: B12 01 20 WP 1), unless otherwise required by State law.

And, if applicable:

#### **Consequential Repair**

When additional work and/or parts are required as a direct result of the issue described in this Service Information Bulletin, claim these items under the under the defect code listed above together with the corresponding labor operations (including any additional diagnosis) listed in AIR if applicable.

Please explain the reason for this consequential repair work (the why and what) on the repair order and in the claim comments section.

#### **Reimbursement of Prior Customer-Pay Repairs (TREAD Act)**

Based on the issue and the age of the Affected Vehicles being addressed by this Safety Recall Campaign, a reimbursement request for a qualifying prior customer-pay repair is not likely.

However, if you receive a reimbursement request from a customer for a prior repair that may qualify, please contact the Warranty department (include a legible copy of the invoice) through IDS by selecting Coverage, Policy, Coding Questions and Mileage Corrections. The Warranty department will review and respond to your inquiry accordingly.

## **QUESTIONS REGARDING THIS BULLETIN**

| Technical<br>inquiries | Submit feedback at the top of this bulletin  |
|------------------------|--|
| Warranty inquiries     | Please contact the Warranty department by either using the Live Chat<br>that's available in the Warranty Documentation Portal or through IDS<br>by selecting Coverage, Policy, Coding Questions and Mileage<br>Corrections |
| Parts inquiries        | Submit an IDS ticket to the Parts Department   |

Supporting Materials <u>picture\_as\_pdf</u> B120121 Recall Notice.pdf

# SAFETY RECALL NOTICE

To: All Center Operators, Sales Managers, Service Manager, Parts Manager and Warranty Processor

RE: Safety Recall: 48-Volt Battery Connections – B12 01 21

BMW AG is conducting a Voluntary Safety Recall (effective February 12, 2021) on a small number of Model Year 2021 BMW vehicles that were produced between September 9, 2020 and January 13, 2021.

Please be reminded that it is a violation of federal law (The Safety Act) for you to sell, lease or deliver any new motor vehicle covered by this notification until the recall repair has been performed. This means that centers may not legally deliver new motor vehicles to consumers until they are fixed or use/sell replacement equipment/parts subject to this recall. Note also that substantial civil penalties apply to violations of the Safety Act.

Also, you should not sell, lease or deliver any Certified Pre-Owned or used vehicles subject to a safety recall until the repair is completed.

Please follow any special instructions that we provide to you for the return or disposition of recall parts.

We appreciate all your assistance with this Recall.