OMB Control No.: 2127-0004

# Part 573 Safety Recall Report

## 21V-112

**Manufacturer Name:** Navistar, Inc. **Submission Date:** FEB 24, 2021 NHTSA Recall No.: 21V-112 **Manufacturer Recall No.:** None



#### **Manufacturer Information:**

Manufacturer Name: Navistar, Inc.

Address: 2701 Navistar Drive

**Lisle IL 60532** 

Company phone: 331-332-1590

## **Population:**

Number of potentially involved: Estimated percentage with defect: 100 %

#### Vehicle Information:

Vehicle 1: 2021-2021 International LT

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style: OTHER Power Train: DIESEL

Descriptive Information: • The suspect population and corresponding vehicle dates of manufacture are identified by models equipped with certain Cummins X15 engines having flywheel-to crankshaft attachment cap screws improperly torqued and were identified by Cummins, Inc. (Cummins) using their manufacturing records for cap screw torque. • The vehicles in the suspect population were built with Cummins X15 engines built within the Cummins suspect engine population and all other similar vehicles were

There are 7 LT series trucks in the suspect population

Production Dates: NOV 07, 2020 - DEC 18, 2020

VIN Range 1 : Begin : NR End: NR Not sequential

## **Description of Defect:**

Description of the Defect: As reported by Cummins in 21E-009, cap screws attaching the flywheel to the

crankshaft may not have been properly torqued to the specification.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: As reported in Cummins 21E-009, on affected engines, the flywheel may be

susceptible to detaching from the crankshaft, possibly leading to loss of motive power, which may increase the risk of a crash. Additionally, driveline pieces may be ejected from the engine compartment, which may increase the

risk of personal injury.

Description of the Cause: AS reported by Cummins in 21E-009, during the affected production period,

the torque gun used during the engine assembly process did not have a lower

control limit in place.

Identification of Any Warning As reported in Cummins 21E-009, prior to failure, the driver may notice noise, that can Occur: vibration or difficult clutch operation in vehicles equipped with manual transmissions. In vehicles equipped with automated transmissions, a clutch fault lamp may illuminate.

## **Involved Components:**

Component Name 1: Cap Screw Component Description: Cap Screw

Component Part Number: D103109BX03

## **Supplier Identification:**

## **Component Manufacturer**

Name: Cummins, Inc.

Address: 500 Jackson Street

Columbus Indiana 47202

**Country: United States** 

### **Chronology:**

- 02/05/2021 Navistar and Cummins meet to discuss Cummins recall 21E-009 and Navistar initiates investigation to determine the impact on International trucks.
- 02/09/2021 Navistar and Cummins review suspect ESN data to Navistar vehicle manufacturing data to identify suspect population.
- 02/16/2021 Navistar and Cummins meet to understand the extent of the low torque condition, review root cause, and verify the start and stop dates of the suspect population.
- 02/18/2021 Navistar finalizes suspect vehicle population and declares a safety recall.

#### **Description of Remedy:**

- Description of Remedy Program: As reported by Cummins in 21E-009, Cummins will conduct a safety campaign to properly torque the subject cap screws and inspect for possible damage and, if necessary, repair the damage.
  - Cummins will administer the campaign, notify customers, supply remedy, and provide quarterly completion reports as outlined in Cummins' defect report 21E-009.
  - As reported by Cummins in 21E-009, a pre notification reimbursement for a product product failure would have been replaced under the manufacturer's limited engine warranty.

How Remedy Component Differs Cummins reported in 21E-009 that the remedy does not consist of from Recalled Component: replacing a recalled component. If inspection reveals any damaged parts, those parts will be replaced with the identical OE part.

Identify How/When Recall Condition As reported by Cummins in 21E-009, a Lower Control Limit with a failsafe was Corrected in Production: was implemented on the torque gun used during the engine assembly process on January 11, 2021.

#### **Recall Schedule:**

Description of Recall Schedule: • Cummins estimates in 21E-009 that the Customer notification letters

will be mailed by 03/29/2021.

• Cummins estimates in 21E-009 that the dealer notification letters will

be mailed by 02/26/2021.

Planned Dealer Notification Date: FEB 26, 2021 - FEB 26, 2021

Planned Owner Notification Date: MAR 29, 2021 - MAR 29, 2021

<sup>\*</sup> NR - Not Reported