Manufacturer Name: Ford Motor Company Submission Date : MAR 10, 2021 NHTSA Recall No.: 21V-155 Manufacturer Recall No.: 21S10

Manufacturer Information :

Manufacturer Name: Ford Motor Company Address: 330 Town Center Drive Company phone : 1-866-436-7332

Vehicle Information :

	2018-2018 Ford F-150 LIGHT VEHICLES			
• •	PICKUP TRUCK			
Power Train :				
Descriptive Information :	This condition affects certain F-150, F-Super Duty and Escape vehicles equipped with Continental Tire of America (CTA) supplied tires built within the time periods specified. Continental notified Ford that it supplied 19 potentially overcured tires to Ford within the timeframes identified above: one tire for Escape, six tires for F-150 and twelve tires for Super Duty. Ford's team reviewed supplier manufacturing and shipping records for certain DOT and production mold combinations to determine the population of potentially affected vehicles to inspect. These vehicles are not produced in VIN order. Information as to the applicability of this action to specific vehicles can best be obtained by either calling Ford's toll-free line (1-866-436-7332) or by contacting a local Ford or Lincoln dealer who can obtain specific information regarding the vehicles from the Ford On-line Automotive Service Information System (OASIS) database. F-150 Vehicles Affected: 6,345 F-250 Vehicles Affected: 6,208 F-350 Vehicles Affected: 2,489 Escape Vehicles Affected: 727			
Draduction Datas	- ADD 19 2010 SED 04 2010			
	APR 12, 2018 - SEP 04, 2018			
VIN Range 1:1	Begin :NREnd :NRNot sequential			

The information contained in this report was submitted pursuant to 49 CFR §573



Number of potentially involved : 15,729 Estimated percentage with defect : 1%

Population :

21V-155

Suite 500 Dearborn MI 48126-2738

21V-155

Vehicle 2 :	2018-2020 Ford	F-Super Duty (F	-250 a	and F-350)	
Vehicle Type :	LIGHT VEHICLES				
Body Style :	PICKUP TRUCK				
Power Train :	NR				
Descriptive Information :	 This condition affects certain F-150, F-Super Duty and Escape vehicles equipped Continental Tire of America (CTA) supplied tires built within the time periods specified. Continental notified Ford that it supplied 19 potentially overcured tir Ford within the timeframes identified above: one tire for Escape, six tires for F- and twelve tires for Super Duty. Ford's team reviewed supplier manufacturing shipping records for certain DOT and production mold combinations to determ population of potentially affected vehicles to inspect. These vehicles are not produced in VIN order. Information as to the applicability this action to specific vehicles can best be obtained by either calling Ford's toll-f line (1-866-436-7332) or by contacting a local Ford or Lincoln dealer who can of specific information regarding the vehicles from the Ford On-line Automotive S Information System (OASIS) database. 		the time periods ially overcured tires to upe, six tires for F-150 er manufacturing and nations to determine th to the applicability of calling Ford's toll-free n dealer who can obtain		
	F-150 Vehicles Af F-250 Vehicles Af F-350 Vehicles Af Escape Vehicles A	fected: 6,208 fected: 2,489 ffected: 727			
Production Dates :			c 1	ND	
VIN Range 1:1	Begin :	NR	End :	NK	Not sequential

21V-155

Vehicle 3 ·	2019-2019 Ford	dEscane				
	LIGHT VEHICLES					
Body Style :						
Power Train :						
	This condition affects certain F-150, F-Super Duty and Escape vehicles equipped with Continental Tire of America (CTA) supplied tires built within the time periods specified. Continental notified Ford that it supplied 19 potentially overcured tires to Ford within the timeframes identified above: one tire for Escape, six tires for F-150 and twelve tires for Super Duty. Ford's team reviewed supplier manufacturing and shipping records for certain DOT and production mold combinations to determine the population of potentially affected vehicles to inspect. These vehicles are not produced in VIN order. Information as to the applicability of this action to specific vehicles can best be obtained by either calling Ford's toll-free line (1-866-436-7332) or by contacting a local Ford or Lincoln dealer who can obtain specific information regarding the vehicles from the Ford On-line Automotive Service Information System (OASIS) database.					
	F 150 V 1 · 1					
	F-150 Vehicles A F-250 Vehicles A F-350 Vehicles A Escape Vehicles	Affected: 6,20 Affected: 2,48	8 9			
Production Dates :	F-250 Vehicles A F-350 Vehicles A Escape Vehicles	Affected: 6,20 Affected: 2,48 Affected: 727	8 9 7			
Production Dates : VIN Range 1 : 2	F-250 Vehicles A F-350 Vehicles A Escape Vehicles MAR 19, 2019 -	Affected: 6,20 Affected: 2,48 Affected: 727	8 9 7		□ Not sequential	
VIN Range 1:	F-250 Vehicles A F-350 Vehicles A Escape Vehicles MAR 19, 2019 - Begin : ct : According to (CTA), certai a carcass bro	Affected: 6,20 Affected: 2,48 Affected: 727 MAR 22, 2019 NR o defect notifie in tires have b eak in the side	8 9 7 End: NR cation 21T-001 been cured beyo ewall with sudd	ond specifications or content of the second specification of the second se	ental Tire of America on, and may experience ould develop a belt	
VIN Range 1 : : Description of Defect : Description of the Defe	F-250 Vehicles A F-350 Vehicles A Escape Vehicles MAR 19, 2019 - Begin : ct : According to (CTA), certai a carcass bro edge separat	Affected: 6,20 Affected: 2,48 Affected: 727 MAR 22, 2019 NR o defect notifie in tires have b eak in the side	8 9 7 End: NR cation 21T-001 been cured beyo	ond specifications or content of the second specification of the second se	ental Tire of America on, and may experience ould develop a belt	
VIN Range 1 : Description of Defect : Description of the Defe FMVSS	F-250 Vehicles A F-350 Vehicles A Escape Vehicles MAR 19, 2019 - Begin : ct : According to (CTA), certai a carcass bre edge separat 1 : NR	Affected: 6,20 Affected: 2,48 Affected: 727 MAR 22, 2019 NR o defect notifie in tires have b eak in the side	8 9 7 End: NR cation 21T-001 been cured beyo ewall with sudd	ond specifications or content of the second specification of the second se	ental Tire of America on, and may experience ould develop a belt	
VIN Range 1 : : Description of Defect : Description of the Defe	F-250 Vehicles A F-350 Vehicles A Escape Vehicles MAR 19, 2019 - Begin :	Affected: 6,20 Affected: 2,48 Affected: 727 MAR 22, 2019 NR o defect notifie in tires have heak in the side tion that could o CTA, affected h sudden air l	8 9 7 End: NR End: NR cation 21T-001 been cured beyo ewall with sudd d lead to a parti d lead to a parti	ond specification len air loss or c al or full tread erience a carca velop a belt ed	ental Tire of America on, and may experience ould develop a belt /belt loss. ss break in the ge separation which	
VIN Range 1 : Description of Defect : Description of the Defe FMVSS FMVSS	F-250 Vehicles A F-350 Vehicles A Escape Vehicles MAR 19, 2019 - Begin :	Affected: 6,20 Affected: 2,48 Affected: 727 MAR 22, 2019 NR O defect notifie in tires have b eak in the side tion that could O CTA, affected h sudden air b o partial or ful	8 9 7 End: NR End: NR cation 21T-001 been cured beyo ewall with sudd d lead to a parti d lead to a parti	ond specification len air loss or c al or full tread erience a carca velop a belt ed	eental Tire of America on, and may experience ould develop a belt /belt loss. ss break in the	
VIN Range 1 : Description of Defect : Description of the Defe FMVSS FMVSS	F-250 Vehicles A F-350 Vehicles A Escape Vehicles MAR 19, 2019 - Begin :	Affected: 6,20 Affected: 2,48 Affected: 2,48 Affected: 727 MAR 22, 2019 NR o defect notifie in tires have b eak in the side tion that could b CTA, affected h sudden air b o partial or ful sh.	8 9 7 End: NR End: NR cation 21T-001 been cured beyo ewall with sudd d lead to a parti d lead to a parti d lead to a parti l tires may expo oss or could de l tread/belt los ed tires were ov	ond specification len air loss or c lal or full tread erience a carca velop a belt ed s. These condit	ental Tire of America on, and may experience ould develop a belt /belt loss. ss break in the ge separation which	

The information contained in this report was submitted pursuant to 49 CFR §573

21V-155

volved Components :	
Component Name 1:	265/70 R17 113H TL AMERITRAC TR
Component Description :	F-150 Spare Tire
Component Part Number :	GL34-1508-CA
-	275/65 R18 123S TL CONTITRAC
Component Description :	F-Super Duty Road Tire
Component Part Number :	DC34-1508-YA
Component Name 3:	275/65 R18 123S TL CONTITRAC
Component Description :	F-Super Duty Spare Tire
Component Part Number :	JC3C-1508-ZA
Component Name 4 :	235/55 R17 99H TL CONTIPROCONTACT
Component Description :	
Component Part Number :	-

Supplier Identification :

Component Manufacturer

Name : Continental Tire the Americas, LLC

Address : 1791 Harmon Road Auburn Hills Michigan 48326 Country : United States

Chronology:

February 2021

On February 19, 2021, Ford's Critical Concern Review Group (CCRG) was informed of an issue regarding a Continental Tire the Americas (CTA) tire durability concern. CTA notified Ford that it had shipped nineteen potentially over cured tires to four Ford Assembly Plants between 2018 and 2020. CTA filed a defect notice with NHTSA (21T-001) on February 15, 2021 identifying ten affected OEMs including Ford. Ford utilized CTA's

The information contained in this report was submitted pursuant to 49 CFR §573

Page 5

manufacturing and shipping records for certain DOT and production mold combinations to determine the population of potentially affected vehicles.

On March 3, 2021, Ford's Field Review Committee reviewed the concern and approved a field action.

Ford is not aware of any reports of accident or injury related to this condition.

Description of Remedy :

Description of Remedy Program :	Owners will be notified by mail and instructed to take their vehicle to a Ford or Lincoln dealer to have their tires inspected for the suspect DOT and production mold numbers. If a tire's DOT and production mold numbers match the suspect tire list provided by CTA, the dealer will replace the suspect tire. On vehicles that have been sold, the dealer will also replace the corresponding tire on the opposite side of the axle. If a pair of tires are replaced, the new tires will be installed/moved to the rear axle locations. There will be no charge for this service. Ford is excluding reimbursement for costs because the original warranty program would provide for a free repair for this concern. Ford will forward a copy of the notification letters to dealers to the agency when available.
from Recalled Component : Identify How/When Recall Condition	Remedy tires will have DOT number and production mold number combinations not affected by the condition. N/A
from Recalled Component :	Remedy tires will have DOT number and production mold number combinations not affected by the condition.

Recall Schedule :

Description of Recall Schedule :	Notification to dealers is expected to occur on March 11, 2021. Mailing of owner notification letters is expected to begin March 29, 2021 and is
Planned Dealer Notification Date :	expected to be completed by April 2, 2021.
Planned Owner Notification Date :	

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573