

Part 573 Safety Recall Report

21V-157

Manufacturer Name : Porsche Cars North America, Inc.**Submission Date :** MAR 10, 2021**NHTSA Recall No. :** 21V-157**Manufacturer Recall No. :** AMA3**Manufacturer Information :**

Manufacturer Name : Porsche Cars North America, Inc.

Address : One Porsche Drive

Atlanta GA 30354

Company phone : 1-800-767-7243

Population :

Number of potentially involved : 396

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2021-2021 Porsche Taycan Turbo

Vehicle Type : LIGHT VEHICLES

Body Style : 4-DOOR

Power Train : HYBRID ELECTRIC

Descriptive Information : Affected vehicles have been identified through automatically stored production screwing protocols of each relevant threaded connection.

Production Dates : DEC 02, 2020 - DEC 03, 2020

VIN Range 1 : Begin : WPOAC2Y15MSA62480 End : WPOAC2Y12MSA62517 Not sequential

Vehicle 2 : 2021-2021 Porsche 911 Turbo S Coupe

Vehicle Type : LIGHT VEHICLES

Body Style : 2-DOOR

Power Train : GAS

Descriptive Information : Affected vehicles have been identified through automatically stored production screwing protocols of each relevant threaded connection.

Production Dates : OCT 26, 2020 - DEC 15, 2020

VIN Range 1 : Begin : WPOAD2A93MS257617 End : WPOAD2A93MS258041 Not sequential

Vehicle 3 : 2021-2021 Porsche Cayman

Vehicle Type : LIGHT VEHICLES

Body Style : 2-DOOR

Power Train : GAS

Descriptive Information : Affected vehicles have been identified through automatically stored production screwing protocols of each relevant threaded connection.

Production Dates : OCT 23, 2020 - DEC 10, 2020

VIN Range 1 : Begin : WPOAA2A8XMK260241 End : WPOAA2A88MK260402 Not sequentialVIN Range 2 : Begin : WPOAA2A88MS260187 End : WPOAA2A88MS260254 Not sequential

Vehicle 4 : 2021-2021 Porsche Cayman T

Vehicle Type : LIGHT VEHICLES

Body Style : 2-DOOR

Power Train : GAS

Descriptive Information : Affected vehicles have been identified through automatically stored production screwing protocols of each relevant threaded connection.

Production Dates : OCT 23, 2020 - DEC 03, 2020

VIN Range 1 : Begin : WPOAA2A87MK260245 End : WPOAA2A89MK260389 Not sequential

Vehicle 5 : 2021-2021 Porsche 911 Carrera Coupe

Vehicle Type : LIGHT VEHICLES

Body Style : 2-DOOR

Power Train : GAS

Descriptive Information : Affected vehicles have been identified through automatically stored production screwing protocols of each relevant threaded connection.

Production Dates : OCT 20, 2020 - DEC 08, 2020

VIN Range 1 : Begin : WPOAA2A92MS205520 End : WPOAA2A92MS205775 Not sequential

Vehicle 6 : 2021-2021 Porsche Taycan

Vehicle Type : LIGHT VEHICLES

Body Style : 4-DOOR

Power Train : HYBRID ELECTRIC

Descriptive Information : Affected vehicles have been identified through automatically stored production screwing protocols of each relevant threaded connection.

Production Dates : DEC 03, 2020 - DEC 03, 2020

VIN Range 1 : Begin : WPOAA2Y10MSA12706 End : WPOAA2Y10MSA12706 Not sequential

Vehicle 7 : 2021-2021 Porsche 911 Carrera S Coupe

Vehicle Type : LIGHT VEHICLES

Body Style : 2-DOOR

Power Train : GAS

Descriptive Information : Affected vehicles have been identified through automatically stored production screwing protocols of each relevant threaded connection.

Production Dates : OCT 28, 2020 - NOV 28, 2020

VIN Range 1 : Begin : WPOAB2A95MS221563 End : WPOAB2A91MS221740 Not sequential

Vehicle 8 : 2021-2021 Porsche 911 Carrera 4S Coupe

Vehicle Type : LIGHT VEHICLES

Body Style : 2-DOOR

Power Train : GAS

Descriptive Information : Affected vehicles have been identified through automatically stored production screwing protocols of each relevant threaded connection.

Production Dates : NOV 09, 2020 - DEC 14, 2020

VIN Range 1 : Begin : WPOAB2A95MS221613 End : WPOAB2A9XMS221770 Not sequential

Vehicle 9 : 2021-2021 Porsche Cayman S

Vehicle Type : LIGHT VEHICLES

Body Style : 2-DOOR

Power Train : GAS

Descriptive Information : Affected vehicles have been identified through automatically stored production screwing protocols of each relevant threaded connection.

Production Dates : OCT 26, 2020 - OCT 26, 2020

VIN Range 1 : Begin : WPOAB2A86MK275025 End : WPOAB2A86MK275025 Not sequential

Vehicle 10 : 2021-2021 Porsche Taycan 4S

Vehicle Type : LIGHT VEHICLES

Body Style : 4-DOOR

Power Train : HYBRID ELECTRIC

Descriptive Information : Affected vehicles have been identified through automatically stored production screwing protocols of each relevant threaded connection.

Production Dates : NOV 04, 2020 - JAN 11, 2021

VIN Range 1 : Begin : WPOAB2Y15MSA40627 End : WPOAB2Y12MSA41914 Not sequential

Vehicle 11 : 2021-2021 Porsche Cayman GT4

Vehicle Type : LIGHT VEHICLES

Body Style : 2-DOOR

Power Train : GAS

Descriptive Information : Affected vehicles have been identified through automatically stored production screwing protocols of each relevant threaded connection.

Production Dates : OCT 22, 2020 - DEC 16, 2020

VIN Range 1 : Begin : WPOAC2A89MK289157 End : WPOAC2A81MK289377 Not sequential

VIN Range 2 : Begin : WPOAC2A88MS289232 End : WPOAC2A81MS289265 Not sequential

Vehicle 12 : 2021-2021 Porsche Taycan Turbo S
Vehicle Type : LIGHT VEHICLES
Body Style : 4-DOOR
Power Train : HYBRID ELECTRIC

Descriptive Information : Affected vehicles have been identified through automatically stored production screwing protocols of each relevant threaded connection.

Production Dates : NOV 09, 2020 - DEC 17, 2020

VIN Range 1 : Begin : WPOAC2Y18MSA62148 End : WPOAC2Y18MSA62666 Not sequential

Vehicle 13 : 2021-2021 Porsche 911 Carrera 4S Targa
Vehicle Type : LIGHT VEHICLES
Body Style : 2-DOOR
Power Train : GAS

Descriptive Information : Affected vehicles have been identified through automatically stored production screwing protocols of each relevant threaded connection.

Production Dates : NOV 05, 2020 - DEC 15, 2020

VIN Range 1 : Begin : WPOBB2A94MS235216 End : WPOBB2A93MS235451 Not sequential

Vehicle 14 : 2021-2021 Porsche 911 Carrera Cabriolet
Vehicle Type : LIGHT VEHICLES
Body Style : 2-DOOR
Power Train : GAS

Descriptive Information : Affected vehicles have been identified through automatically stored production screwing protocols of each relevant threaded connection.

Production Dates : OCT 23, 2020 - DEC 08, 2020

VIN Range 1 : Begin : WPOCA2A98MS239292 End : WPOCA2A92MS239398 Not sequential

Vehicle 15 : 2021-2021 Porsche 911 Carrera S Cabriolet
Vehicle Type : LIGHT VEHICLES
Body Style : 2-DOOR
Power Train : GAS

Descriptive Information : Affected vehicles have been identified through automatically stored production screwing protocols of each relevant threaded connection.

Production Dates : NOV 13, 2020 - DEC 10, 2020

VIN Range 1 : Begin : WPOCB2A91MS248347 End : WPOCB2A98MS248507 Not sequential

Vehicle 16 : 2021-2021 Porsche 911 Turbo Coupe
Vehicle Type : LIGHT VEHICLES
Body Style : 2-DOOR
Power Train : GAS

Descriptive Information : Affected vehicles have been identified through automatically stored production screwing protocols of each relevant threaded connection.

Production Dates : NOV 12, 2020 - DEC 12, 2020

VIN Range 1 : Begin : WPOAD2A9XMS257694 End : WPOAD2A95MS257943 Not sequential

Vehicle 17 : 2021-2021 Porsche 911 Carrera 4S Targa Heritage Design Edition
Vehicle Type : LIGHT VEHICLES
Body Style : 2-DOOR
Power Train : GAS

Descriptive Information : Affected vehicles have been identified through automatically stored production screwing protocols of each relevant threaded connection.

Production Dates : DEC 17, 2020 - DEC 22, 2020

VIN Range 1 : Begin : WPOBB2A99MS235342 End : WPOBB2A9XMS235401 Not sequential

Vehicle 18 : 2021-2021 Porsche Boxster
Vehicle Type : LIGHT VEHICLES
Body Style : 2-DOOR
Power Train : GAS

Descriptive Information : Affected vehicles have been identified through automatically stored production screwing protocols of each relevant threaded connection.

Production Dates : NOV 04, 2020 - NOV 04, 2020

VIN Range 1 : Begin : WPOCA2A86MS210249 End : WPOCA2A86MS210249 Not sequential

Vehicle 19 : 2021-2021 Porsche 911 Carrera 4S Cabriolet
Vehicle Type : LIGHT VEHICLES
Body Style : 2-DOOR
Power Train : GAS

Descriptive Information : Affected vehicles have been identified through automatically stored production screwing protocols of each relevant threaded connection.

Production Dates : DEC 01, 2020 - DEC 03, 2020

VIN Range 1 : Begin : WPOCB2A97MS248465 End : WPOCB2A90MS248467 Not sequential

Vehicle 20 : 2021-2021 Porsche 911 Turbo Cabriolet
Vehicle Type : LIGHT VEHICLES
Body Style : 2-DOOR
Power Train : GAS

Descriptive Information : Affected vehicles have been identified through automatically stored production screwing protocols of each relevant threaded connection.

Production Dates : NOV 11, 2020 - NOV 13, 2020

VIN Range 1 : Begin : WPOCD2A92MS263367 End : WPOCD2A96MS263372 Not sequential

Vehicle 21 : 2021-2021 Porsche 718 Spyder
Vehicle Type : LIGHT VEHICLES
Body Style : 2-DOOR
Power Train : GAS

Descriptive Information : Affected vehicles have been identified through automatically stored production screwing protocols of each relevant threaded connection.

Production Dates : NOV 11, 2020 - NOV 11, 2020

VIN Range 1 : Begin : WPOCC2A81MS240351 End : WPOCC2A81MS240351 Not sequential

Vehicle 22 : 2021-2021 Porsche 911 Turbo S Cabriolet
Vehicle Type : LIGHT VEHICLES
Body Style : 2-DOOR
Power Train : GAS

Descriptive Information : Affected vehicles have been identified through automatically stored production screwing protocols of each relevant threaded connection.

Production Dates : NOV 03, 2020 - DEC 16, 2020

VIN Range 1 : Begin : WPOCD2A99MS263334 End : WPOCD2A9XMS263522 Not sequential

Description of Defect :

Description of the Defect : Individual threaded connections at the vehicle's suspension might not be tightened to the specification.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : A loose threaded connection might cause movement of respective suspension component beyond its intended position.

If the screw connection fails it might cause a sudden driving instability with significant changes of the driving behavior and the potential loss of control.

Description of the Cause : Due to a temporarily insufficiently cut thread of a locknut, the thereby increased friction might have caused a premature stop of the automated screwing process.

Thus, the durability of the threaded connection could not be guaranteed over

the full service life of the affected vehicles.

Identification of Any Warning that can Occur : A warning is not ensured. Abnormal noises might be perceivable, due to the movement of respective components.

Involved Components :

Component Name 1 : Hexagonal flange nut M12x1.5

Component Description : This nut is used to affix several threaded connections on the front and rear suspension of multiple vehicle types.

Component Part Number : N 90966402

Supplier Identification :

Component Manufacturer

Name : HEWI

Address : Dellinger Weg 1
Spaichingen Foreign States 78545

Country : Germany

Chronology :

On February 9, 2021, Porsche was informed that certain screw connections at the subject vehicle's suspension might not have been tightened according to specification.

Subsequently, the automatically stored production screwing protocols of each relevant threaded connection have been analyzed.

On February 24, 2021, this topic was presented to the product safety committee at Dr. Ing. h.c. F. Porsche AG with first results of internal worst-case tests (with the greatest possible load). The results showed a minimum mileage of 20,000 km without the screw connection might fail. The product safety committee has commissioned to find out what might happen after 20,000 km to better understand the potential safety implications.

On March 3, 2021, out of abundance of caution, a safety defect was decided for the subject vehicles.

Description of Remedy :

| | |
|--|---|
| Description of Remedy Program : | The threaded connections in question will be replaced with a new nut and bolt and tightened to the original specification. Additionally, surrounding components will be checked for any consequential damage. Depending on the inspection result, all damaged parts will be replaced. |
| How Remedy Component Differs from Recalled Component : | The remedy components are manufactured within the original design specification. |
| Identify How/When Recall Condition was Corrected in Production : | The recall condition was corrected at the component production beginning December 11, 2020 by clearing up all stored parts in question at the production line and the production warehouse. |

Recall Schedule :

| | |
|------------------------------------|---|
| Description of Recall Schedule : | Dealers and Customers will be notified on or before May 9, 2021 |
| Planned Dealer Notification Date : | MAY 09, 2021 - MAY 09, 2021 |
| Planned Owner Notification Date : | MAY 09, 2021 - MAY 09, 2021 |

* NR - Not Reported