OMB Control No.: 2127-0004

Part 573 Safety Recall Report

21V-196

Manufacturer Name: Mercedes-Benz USA, LLC

Submission Date: APR 30, 2021 **NHTSA Recall No.:** 21V-196 **Manufacturer Recall No.:** 2021040012



Manufacturer Information:

Manufacturer Name: Mercedes-Benz USA, LLC

Address: 13470 International Parkway

Jacksonville FL 32218

Company phone: 1-877-496-3691

Population:

Number of potentially involved: 1,909 Estimated percentage with defect: 20 %

Vehicle Information:

Vehicle 1: 2006-2007 Mercedes-Benz C230

Vehicle Type: LIGHT VEHICLES

Body Style : 4-DOOR Power Train : GAS

Descriptive Information: Mercedes-Benz MY2006-2007 C230 296 vehicles. The recall population was

determined through production records. Vehicles outside of the recall population

have sunroofs with bonding that meets current production specifications.

Production Dates: DEC 12, 2005 - SEP 14, 2006

VIN Range 1 : Begin : NR End : NR Not sequential

Vehicle 2: 2006-2007 Mercedes-Benz C280

Vehicle Type: LIGHT VEHICLES

Body Style : 4-DOOR Power Train : GAS

Descriptive Information : Mercedes-Benz MY2006-2007 C280 249 vehicles. The recall population was

determined through production records. Vehicles outside of the recall population

have sunroofs with bonding that meets current production specifications.

Production Dates: DEC 12, 2005 - SEP 14, 2006

Vehicle 3:	2006-2007 Mer	cedes-Benz C35	0			
Vehicle Type :	LIGHT VEHICLES					
Body Style :	4-DOOR					
Power Train:	GAS					
Descriptive Information :	Mercedes-Benz	MY2006-2007	C 350 34	4 vehicles. The recall popu	lation was	
-	determined through production records. Vehicles outside of the recall population					
	have sunroofs with bonding that meets current production specifications.					
Production Dates :	·		_ ,			
VIN Range 1:	Begin :	NR	End:	NR	■ Not sequential	
W.l.!.l. 4.	9000 9000 M	l D	AMC			
	2006-2006 Mer		AMG			
~ -	LIGHT VEHICLE					
Body Style : Power Train :						
		MV2006 CEE AI	MC 9 vo	hiolog The recall nanulati	on was datarminad	
Descriptive Information :						
	through production records. Vehicles outside of the recall population have sunroofs with bonding that meets current production specifications.					
Production Dates:	DEC 12, 2005 - SEP 14, 2006					
VIN Range 1:		NR	End:	NR	Not sequential	
	U					
Vehicle 5:	2006-2007 Mercedes-Benz CLK350					
Vehicle Type :	LIGHT VEHICLES					
Body Style :	2-DOOR					
Power Train :	GAS					
Descriptive Information :						
	determined through production records. Vehicles outside of the recall population					
		_	it meets	s current production speci	fications.	
Production Dates :			_ ,			
VIN Range 1:	Begin :	NR	End:	NR	■ Not sequential	
Vehicle 6: 2006-2006 Mercedes-Benz CLK500						
	LIGHT VEHICLES					
Body Style:		.5				
Power Train :						
		MV2006 CLK50	ıΩ 19 ₃₇₀	hicles. The recall populati	on was datarminad	
Descriptive information.	n: Mercedes-Benz MY2006 CLK500 12 vehicles. The recall population was determined through production records. Vehicles outside of the recall population have sunroofs					
	- ·			action specifications.		
Production Dates: DEC 12, 2005 - SEP 14, 2006						
VIN Range 1:		NR	End:	NR	■ Not sequential	
					_	

Vehicle 7:	2007-2007 Mer	cedes-Benz CL	X550				
Vehicle Type :	LIGHT VEHICLE	ES					
Body Style :							
Power Train :							
Descriptive Information :	Mercedes-Benz	MY2007 CLK5	50 17 ve	hicles. The rec	all population was determined		
1					ecall population have sunroofs		
	with bonding th	with bonding that meets current production specifications.					
Production Dates:	DEC 12, 2005 - S	SEP 14, 2006					
VIN Range 1:							
Vehicle 8:	2006-2006 Mer	cedes-Benz CL	5500				
Vehicle Type :	LIGHT VEHICLE	ES					
Body Style :	4-DOOR						
Power Train :	GAS						
Descriptive Information :	Mercedes-Benz	MY2006 CLS50	00 148 v	ehicles. The re	call population was determined		
	through production records. Vehicles outside of the recall population have sunroofs						
	with bonding th		nt produ	iction specifica	tions.		
Production Dates :	DEC 12, 2005 - SEP 14, 2006						
VIN Range 1:	Begin:	NR	End:	NR	☐ Not sequential		
Vahiela 0 :	Vehicle 9: 2006-2006 Mercedes-Benz CLS55 AMG						
			OJJ AIVI	л			
Body Style :	LIGHT VEHICLES						
Power Train:							
		Managa at an		4 1 1 771	11		
Descriptive Information :	Mercedes-Benz MY2006 CLS55 AMG 34 vehicles. The recall population was determined through production records. Vehicles outside of the recall population						
		~ ·			ection specifications.		
Production Dates :		_	at meet	current proud	ection specifications.		
VIN Range 1:		NR	End:	NR	☐ Not sequential		
viiv Range 1.	Degiii.	TVIC	Liiu .	NIC	Not sequential		
Vehicle 10:	0: 2007-2007 Mercedes-Benz CLS550						
Vehicle Type :	: LIGHT VEHICLES						
Body Style :							
Power Train :	GAS						
Descriptive Information :	: Mercedes-Benz MY2007 CLS550 94 vehicles. The recall population was determined						
					recall population have sunroofs		
	with bonding th						
Production Dates :	DEC 12, 2005 - S	SEP 14, 2006					
VIN Range 1:	Begin:	NR	End:	NR	☐ Not sequential		

Vehicle Type : Body Style :			OCDI			
Power Train:	DIESEL					
Descriptive Information :	Mercedes-Benz MY2006-2007 E320 70 vehicles. The recall population was determined through production records. Vehicles outside of the recall population have sunroofs with bonding that meets current production specifications.					
Production Dates:	DEC 12, 2005 - S	EP 14, 2006				
VIN Range 1:	Begin:	NR	End:	NR	■ Not sequential	
	GAS Mercedes-Benz	S MY2007 CLS63	AMG 24	4 vehicles. The recall popu		
	determined through production records. Vehicles outside of the recall population have sunroofs with bonding that meets current production specifications.					
Production Dates :	DEC 12, 2005 - SEP 14, 2006					
VIN Range 1:	Begin :	NR	End:	NR	■ Not sequential	
Vehicle Type : Body Style : Power Train :	Mercedes-Benz MY2006-2007 E350 Wagon 47 vehicles. The recall population was					
	determined through production records. Vehicles outside of the recall population have sunroofs with bonding that meets current production specifications.					
Production Dates :		_		1 1		
VIN Range 1:		NR	End:	NR	☐ Not sequential	
Descriptive Information :	Mercedes-Benz MY2006-2007 E350 671 vehicles. The recall population was determined through production records. Vehicles outside of the recall population have sunroofs with bonding that meets current production specifications.					
Production Dates: DEC 12, 2005 - SEP 14, 2006						
VIN Range 1:	Begin :	NR	End:	NR	☐ Not sequential	

Vehicle 15:	2006-2006 Mer	cedes-Benz E50	00 Wago	on			
	LIGHT VEHICLE		Ü				
V 2	STATIONWAGO						
Power Train :							
Descriptive Information :	Mercedes-Benz	MY2006 E500	Wagon	10 vehicles. The reca	all population was		
	Mercedes-Benz MY2006 E500 Wagon 10 vehicles. The recall population was determined through production records. Vehicles outside of the recall population						
	have sunroofs with bonding that meets current production specifications.						
Production Dates:	DEC 12, 2005 - S	SEP 14, 2006					
VIN Range 1:	Begin:	NR	End:	NR	☐ Not sequential		
Vehicle 16:	2006-2006 Mer	cedes-Benz E50	00				
Vehicle Type :	LIGHT VEHICLE	S					
Body Style :	4-DOOR						
Power Train :	GAS						
Descriptive Information :	Mercedes-Benz	MY2006 E500	17 vehi	cles. The recall popu	lation was determined		
	<u> </u>				population have sunroofs		
	with bonding th	at meets curre	nt produ	action specifications			
Production Dates :	DEC 12, 2005 - S	SEP 14, 2006					
VIN Range 1:	Begin:	NR	End:	NR	☐ Not sequential		
17.1.1.1. 17	W. 1. 1. 4. 2000 2000 W 1. D TWY 1. 1. 2						
		2006-2006 Mercedes-Benz E55 AMG					
• -	LIGHT VEHICLES						
Body Style :							
Power Train:							
Descriptive Information :				-	-		
	<u> </u>			outside of the recall] action specifications	population have sunroofs		
Draduction Dates	g		nt produ	action specifications	•		
Production Dates:			End.	MD	□ Not acquential		
VIN Range 1:	begin:	NR	End:	IVK	☐ Not sequential		
Vehicle 18:	2007-2007 Mer	cedes-Benz E5	50				
	: LIGHT VEHICLES						
Body Style :							
Power Train :							
Descriptive Information: Mercedes-Benz MY2007 E550 76 vehicles. The recall population was determined							
through production records. Vehicles outside of the recall population have sunroofs							
	<u> </u>			action specifications			
Production Dates :	DEC 12, 2005 - S	SEP 14, 2006					
VIN Range 1:	Begin:	NR	End:	NR	■ Not sequential		
-							

☐ Not sequential

Vehicle 19: 2007-2007 Mercedes-Benz E63 AMG Vehicle Type: LIGHT VEHICLES Body Style: 4-DOOR Power Train: GAS Descriptive Information: Mercedes-Benz MY2007 E63 AMG 19 vehicles. The recall population was determined through production records. Vehicles outside of the recall population have sunroofs with bonding that meets current production specifications. Production Dates: DEC 12, 2005 - SEP 14, 2006 VIN Range 1 : Begin : NR End: NR Not sequential Vehicle 20: 2007-2007 Mercedes-Benz E63 Wagon AMG Vehicle Type: LIGHT VEHICLES **Body Style: STATIONWAGON** Power Train: GAS Descriptive Information: Mercedes-Benz MY2007 E63 Wagon AMG 4 vehicles. The recall population was determined through production records. Vehicles outside of the recall population have sunroofs with bonding that meets current production specifications. Production Dates : DEC 12, 2005 - SEP 14, 2006

Description of Defect:

Description of the Defect: Mercedes-Benz AG ("MBAG"), the manufacturer of Mercedes-Benz vehicles,

has determined that on certain MY2006-2007 C-Class (203 platform), CLK-Class (209 platform), E-Class (211 platform) and CLS-Class (219 platform) vehicles the bonding between the glass panel and the sliding roof frame might

End: NR

not meet specifications.

NR

FMVSS 1: NR FMVSS 2: NR

VIN Range 1: Begin:

Description of the Safety Risk: In this case, the adhesion of this bonding might deteriorate gradually over

time. If the bonding adhesion were to deteriorate, the durability

requirements might not be met which could lead to a separation of the glass panel from the vehicle. A displaced panel could increase the risk of a potential

crash or injury for other road users.

Description of the Cause: Due to a production deviation at a supplier, glass panels might have been

bonded without proper application of the primer (bonding agent). The correct usage of the primer is necessary in order to ensure the specified strength of the

bonded joint.

Identification of Any Warning The customer will not receive an advance warning due to the nature of the

that can Occur: failure mechanism.

Involved Components:

Component Name 1: Sunroof

Component Description: Sunroof (203, 211 platform)

Component Part Number: A2117800300

Component Name 2: Sunroof

Component Description: Sunroof (209 platform)

Component Part Number: A2097800200

Component Name 3: Sunroof

Component Description: Sunroof (219 platform)

Component Part Number: A2197800100

Supplier Identification:

Component Manufacturer

Name: Webasto Roof & Components SE

Address: Krailinger Strasse 5

Stockdorf Foreign States 82131

Country: Germany

Chronology:

In the beginning of December 2017, MBAG launched initial investigations based on isolated field reports from outside the US claiming that the sliding roof detached from the vehicle. No damage or injuries were reported as a result of these events. The sliding roofs of the affected vehicles were requested and returned by the individual markets. The returned field parts were analyzed by the supplier as well as by an external laboratory. The analysis of the supplier and outside laboratory were inconclusive. Since these analyses did not indicate a potential root cause and this type of sliding roof was already out of production, MBAG began to look for vehicles from the global used car market to carry out further investigations. By November 2018, three sliding roofs were retrieved and analyzed. From these three sliding roofs, two did not indicate any issues. While one of the sliding roof panels exhibited indications of an impaired bonding, and the others did not, it was unclear why the bonding on this particular sliding roof was less strong than the other field samples. MBAG, along with the supplier, also undertook a thorough review of the supplier's production records to determine if there were any changes made during the course of production. That review concluded in May, 2019. MBAG found that the

supplier had changed the process of the primer application several times over the course of the full production period, including having changed the drying time for the bonding agent. MBAG then conducted testing featuring various test methods to determine whether reduction of drying time may have had an effect on bonding performance over time. MBAG additionally undertook to correlate the testing results, suggesting that there could be a diminution in bonding performance depending on the production period of sliding roofs.

Please see Chronology Supplement.

Description of Remedy:

Description of Remedy Program: As a precautionary measure an authorized Mercedes-Benz dealer will

check the glass panel bonding on the affected vehicles and replace the

sliding roof, as necessary.

Pursuant to 49 C.F.R. § 577.11(e), MBUSA plans to provide notice about pre-notice reimbursement to owners since some of the involved vehicles

would have been previously subject to the condition described.

How Remedy Component Differs Sliding roof with correct bonding of the glass panel.

from Recalled Component:

Sunroof Cover + Screws (203, 211 platform) -A2117800400

Sunroof Cover + Screws (209 platform) - A2097800300 Sunroof Cover + Screws (219 platform) -A2197800200

Front Panel - A2107840144 Glass Cover - A2097840044 Left side panel - A2157801540

Identify How/When Recall Condition A review of the supplier's production records reveals that there were was Corrected in Production: changes in its production processes that establish a clean point after

September 14, 2006.

Recall Schedule:

Description of Recall Schedule: Dealers will be notified of the amendment to voluntary recall campaign

on March 26, 2021. Owners will be notified of the voluntary recall

campaign approximately one week after launch to the dealers on May 15,

2021. A copy of all communications will be provided when available.

Planned Dealer Notification Date: MAR 26, 2021 - NR

Planned Owner Notification Date: MAY 14, 2021 - NR

* NR - Not Reported