OMB Control No.: 2127-0004

Part 573 Safety Recall Report

21V-482

Manufacturer Name: Oshkosh Corporation

Submission Date: AUG 27, 2021 NHTSA Recall No.: 21V-482 Manufacturer Recall No.: NR



Manufacturer Information:

Population:

Manufacturer Name: Oshkosh Corporation

Address: 2307 Oregon Street

PO Box 2566 Oshkosh WI 54903-2566

Company phone: 920-235-9151

Number of potentially involved: 897 Estimated percentage with defect: 100 %

Vehicle Information:

Vehicle 1: 2019-2022 Oshkosh S-Series

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style: ALL Power Train: DIESEL

Descriptive Information: Oshkosh determined through investigation that the ABS fuses may not be adequate

for a full ABS braking stop.

Production Dates: APR 01, 2019 - JUN 22, 2021

VIN Range 1 : Begin : NR End: NR Not sequential

Description of Defect:

Description of the Defect: 10 amp ABS fuses were installed while the parts manufacturer has stated that

a 15 amp fuse is necessary for modulation of any and all axles during an active

ABS stopping event.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: Incorrectly sized ABS fuses have the chance of blowing during an active ABS

event. If a fuse were to blow during an active ABS event, this may increase the potential that the driver may not be unable to maintain vehicle control

and increase the risk of a crash.

Description of the Cause: Incorrectly sized ABS fuses installed in the vehicle.

Identification of Any Warning If fuses are blown then ABS fault light will show on cluster.

that can Occur:

Involved Components:

Component Name 1: 10A fuse

Component Description: Fuse

Component Part Number: A000P663

Component Name 2: 15A fuse

Component Description: Fuse

Component Part Number: A000V854

Supplier Identification:

Component Manufacturer

Name: NR

Address: NR

NR

Country: NR

Chronology:

In April 2021 Oshkosh engineering began a broad investigation into all fault code data received through our telematics solution. The fault code that indicates a blown ABS fuse was present on "<10 trucks".

Oshkosh Engineering reached out to our ABS supplier to confirm the required fuse size in May 2021, and was advised by the supplier that a 15amp fuse was recommended but a 10amp fuse was being installed in S-Series trucks. Since not all functions of the supplier's ABS system are used on S-Series trucks, further confirmation was requested from the supplier to determine if a 10amp fuse would enable sufficient performance for the S-Series application. Based on the supplier's feedback and evaluation of potential consequences, on June 23, 2021- Oshkosh determined that this issue was a safety issue and went to the field with a Safety Recall to fix population of vehicles.

Oshkosh has not received notice of any near miss or incidents with the ABS fuse blowing during an event but out of abundance of caution is going to the field to correct this issue.

Description of Remedy:

Description of Remedy Program: Oshkosh will send new fuses, new fuse label, and procedure on how to

replace the fuses by adding larger size fuses for the ABS. This will come at no cost to the customer. Customers would file warranty through normal

process for reimbursement of claims.

How Remedy Component Differs The remedy is installing 15 amp fuses in the ABS locations where 10 amp from Recalled Component: fuses were previously installed. A new label will also be installed over the previous fuse label that indicates any replacement fuses should be 15 amp

instead of 10 amp.

was Corrected in Production: circuit.

Identify How/When Recall Condition Production is now installing 15 amp fuses instead of 10 amp for the ABS

Recall Schedule:

Description of Recall Schedule: Notifications to customers will be made via a customer letter. The 577

customer letter will be mailed pending NHTSA approval. Oshkosh does

not distribute vehicles through dealers.

Planned Dealer Notification Date: NR - NR

Planned Owner Notification Date: JUL 30, 2021 - AUG 06, 2021

* NR - Not Reported