

# Part 573 Safety Recall Report

# 21V-506

**Manufacturer Name :** Newmar Corporation**Submission Date :** AUG 16, 2021**NHTSA Recall No. :** 21V-506**Manufacturer Recall No. :** Cummins 21E-032**Manufacturer Information :**

Manufacturer Name : Newmar Corporation

Address : 355 North Delaware Street  
PO Box 30 Nappanee IN 46550

Company phone : 574-773-7791

**Population :**

Number of potentially involved : 1,737

Estimated percentage with defect : 100 %

**Vehicle Information :**

Vehicle 1 : 2017-2021 Newmar Dutch Star

Vehicle Type : BUSES, MEDIUM &amp; HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, as described in Cummins recall #21E-032, the fuel rail assembly on the engine may develop leaks, which may result in an undetected prolonged diesel fuel spray. A leak involving spraying/misting fuel in the presence of an ignition source may increase the risk of fire.  
Dutch Star=992

Production Dates : MAR 01, 2017 - APR 14, 2021

VIN Range 1 : Begin : NR End : NR

 Not sequential

Vehicle 2 : 2017-2021 Newmar Ventana

Vehicle Type : BUSES, MEDIUM &amp; HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, as described in Cummins recall #21E-032, the fuel rail assembly on the engine may develop leaks, which may result in an undetected prolonged diesel fuel spray. A leak involving spraying/misting fuel in the presence of an ignition source may increase the risk of fire.  
Ventana= 486

Production Dates : MAR 01, 2017 - APR 14, 2021

VIN Range 1 : Begin : NR End : NR

 Not sequential

Vehicle 3 : 2020-2021 Newmar New Aire

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, as described in Cummins recall #21E-032, the fuel rail assembly on the engine may develop leaks, which may result in an undetected prolonged diesel fuel spray. A leak involving spraying/misting fuel in the presence of an ignition source may increase the risk of fire.

New Aire= 209

Production Dates : MAR 01, 2017 - APR 14, 2021

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 4 : 2017-2019 Newmar Mountain Aire

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, as described in Cummins recall #21E-032, the fuel rail assembly on the engine may develop leaks, which may result in an undetected prolonged diesel fuel spray. A leak involving spraying/misting fuel in the presence of an ignition source may increase the risk of fire.

Mountain Aire=50

Production Dates : MAR 01, 2017 - APR 14, 2021

VIN Range 1 : Begin :

NR

End : NR

Not sequential

## Description of Defect :

Description of the Defect : On certain motorhomes, as described in Cummins recall #21E-032, the fuel rail assembly on the engine may develop leaks, which may result in an undetected prolonged diesel fuel spray. A leak involving spraying/misting fuel in the presence of an ignition source may increase the risk of fire.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : On certain motorhomes, as described in Cummins recall #21E-032, the fuel rail assembly on the engine may develop leaks, which may result in an undetected prolonged diesel fuel spray. A leak involving spraying/misting fuel in the presence of an ignition source may increase the risk of fire.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

## Involved Components :

Component Name 1 : Accumulator

Component Description : high pressure fuel rail assembly

Component Part Number : 4307034

Component Name 2 : Accumulator

Component Description : high pressure fuel rail assembly

Component Part Number : 4307377

## Supplier Identification :

### Component Manufacturer

Name : Cummins, Inc.

Address : P.O. Box 3005

Columbus Indiana 47202

Country : United States

## Chronology :

On 06/24/2021, Cummins notified Newmar of a potential safety defect on Freightliner chassis using certain Cummins engines. On 06/25/2021 Newmar decided there is a safety defect on Newmar motorhomes with Freightliner chassis. On 07/02/2021, Newmar is giving notice to NHTSA.

## Description of Remedy :

Description of Remedy Program : Cummins, Inc. will provide owners of all affected motorhomes a remedy for the potential defect at no charge for parts or labor. Cummins will notify owners by mail and instruct you to take your motorhome to a Cummins authorized service center to inspect the fuel rail. If damage is found, the fuel rail and fuel lines will be replaced. If no damage is found, the fuel rail will be reassembled with new crush washers using a special tool. Estimated time for repair is 2.5 hrs. This will be done at no cost to the customer.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

**Recall Schedule :**

Description of Recall Schedule : on or before 8/31/21, customer/dealers letters will be mailed out.  
Planned Dealer Notification Date : AUG 31, 2021 - AUG 31, 2021  
Planned Owner Notification Date : AUG 31, 2021 - AUG 31, 2021

\* NR - Not Reported