OMB Control No.: 2127-0004

Part 573 Safety Recall Report

21V-725

Manufacturer Name: Kia Motors America

NHTSA Recall No.: 21V-725

Manufacturer Recall No.: SC217



Manufacturer Information:

Manufacturer Name: Kia Motors America

Address: 111 Peters Canyon Road

Irvine CA 92606

Company phone: 800-333-4542

Population:

Number of potentially involved: 88,576 Estimated percentage with defect: 1 %

Vehicle Information:

Vehicle 1: 2015-2017 Kia Sedona

Vehicle Type: LIGHT VEHICLES

Body Style : ALL Power Train : GAS

Descriptive Information: Certain 2015-2017 model year Sedona vehicles manufactured from 7/21/2014

through 6/10/2016.

The recall population was determined by a review of vehicle production records. The vehicles subject to this recall were not produced in VIN order. Customers seeking information about their specific vehicle will be referred to Kia's Consumer Assistance

Center or their Kia dealer.

Production Dates: JUL 21, 2014 - JUN 10, 2016

VIN Range 1 : Begin : NR End : NR Not sequential

Description of Defect:

Description of the Defect: The Smart Junction Box (SJB) in the subject vehicles interprets the signal from

the multifunction switch to determine the intended turn signal direction. The SJB software logic may not properly interpret the signals received from the multifunction switch in certain circumstances. As a result, the turn signal may intermittently activate in the opposite direction of what was intended by the

driver, thereby increasing the risk of a crash.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: A turn signal that activates in the opposite direction of what was intended by

the driver increases the risk of crash.

Description of the Cause: The Smart Junction Box software logic may improperly interpret the signals

received from the multifunction switch.

Identification of Any Warning If this condition occurs, the unintended turn signal direction will be visible to

that can Occur: the driver on the instrument cluster.

Involved Components:

Component Name 1: Junction Box Assy / I/PNL

Component Description: Smart Junction Box

Component Part Number: 91950-A9710

Component Name 2: Junction Box Assy / I/PNL

Component Description: Smart Junction Box

Component Part Number: 91950-A9740

Component Name 3: Junction Box Assy / I/PNL

Component Description: Smart Junction Box

Component Part Number: 91950-A9760

Component Name 4: Junction Box Assy / I/PNL

Component Description: Smart Junction Box

Component Part Number: 91950-A9770

Component Name 5: Junction Box Assy / I/PNL

Component Description: Smart Junction Box

Component Part Number: 91950-A9780

Supplier Identification:

Component Manufacturer

Name: Kyungshin

Address: 98, Gaetbeol-ro

Yeonsu-gu Incheon Foreign States 21999

Country: Korea, Republic of

Chronology:

See attached document titled "Sedona Turn Signal Misdirection Chronology"

Description of Remedy:

Description of Remedy Program: All owners of the subject vehicles will be notified by first class mail with

instructions to bring their vehicles to a Kia dealer to have the Smart Junction Box software logic updated with an improved version. Kia will reimburse owners for repair expenses already incurred pursuant to Kia's

General Reimbursement Plan filed May 11, 2020.

How Remedy Component Differs The Smart Junction Box software logic has been improved to prevent the

from Recalled Component: activation of a turn signal that was not intended by the driver.

Identify How/When Recall Condition The improved SJB software logic was applied to the Sedona vehicle

was Corrected in Production : production beginning June 10, 2016. However, the SJB with the improved software logic was not installed in some Sedona vehicles produced on June

10, 2016. As a result, these vehicles are included within the scope of this

recall.

Recall Schedule:

Description of Recall Schedule: The Dealer Notification is scheduled for November 8, 2021 and the

Owner Notification is scheduled for November 12, 2021.

Planned Dealer Notification Date : NOV 08, 2021 - NOV 08, 2021 Planned Owner Notification Date : NOV 12, 2021 - NOV 12, 2021

The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Recall Report	21V-725	Page 4
* NR - Not Reported		
The information contained in this report was subm	nitted pursuant to 49 CFR §573	