

# Part 573 Safety Recall Report

# 21V-793

**Manufacturer Name :** Winnebago Industries, Inc.

**Submission Date :** OCT 12, 2021

**NHTSA Recall No. :** 21V-793

**Manufacturer Recall No. :** NR



## Manufacturer Information :

## Population :

**Manufacturer Name :** Winnebago Industries, Inc.

**Number of potentially involved :** NR

**Address :** PO BOX 152  
605 W. Crystal Lake Rd. Forest City IA  
50436

**Estimated percentage with defect :** NR

**Company phone :** 1-641-585-3535

## Vehicle Information :

**Vehicle 1 :** 2022-2022 Winnebago Travato

**Vehicle Type :**

**Body Style :**

**Power Train :** NR

**Descriptive Information :** Population was determined by receiving a serialized component list provided by Volta Power Systems LLC.

**Production Dates :** MAY 25, 2021 - OCT 08, 2021

**VIN Range 1 : Begin :** NR

**End :** NR

☐ Not sequential

**Vehicle 2 :** 2022-2022 Winnebago Boldt

**Vehicle Type :**

**Body Style :**

**Power Train :** NR

**Descriptive Information :** Population was determined by receiving a serialized component list provided by Volta Power Systems LLC.

**Production Dates :** JUN 01, 2021 - OCT 01, 2021

**VIN Range 1 : Begin :** NR

**End :** NR

☐ Not sequential

## Description of Defect :

**Description of the Defect :** An incorrectly built wire harness resulted in the loss of overcurrent protection.

**FMVSS 1 :** NR

**FMVSS 2 :** NR

**Description of the Safety Risk :** Loss of overcurrent protection can cause wires to overheat, resulting in a thermal event.

**Description of the Cause :** NR

Identification of Any Warning NR  
that can Occur :

### Involved Components :

Component Name 1 : Wire Harness

Component Description : Alternator Control Wire Harness

Component Part Number : 100001146

### Supplier Identification :

#### Component Manufacturer

Name : Volta Power Systems LLC.

Address : 12550 Superior Court  
Holland Michigan 50436

Country : United States

### Chronology :

On Thursday September 30, 2021 Winnebago Product Compliance was made aware of a vehicle fire which was a Travato in delivery. No injuries or property damage was reported. An immediate investigation was launched. Winnebago retained a fire and electrical experts, each arriving on Thursday October 7th. Upon completion of their investigation, the potential source was determined to be in a section of wire harness supplied by Volta Power Systems LLC. Winnebago Product Safety Committee met on Thursday October 7th and decided to issue a voluntary recall of the affected units.

### Description of Remedy :

Description of Remedy Program : Remedy will be performed by Winnebago Dealers at no cost to the consumer.

How Remedy Component Differs from Recalled Component : Proper overcurrent protection has been properly located in the harness.

Identify How/When Recall Condition was Corrected in Production : The recall condition is corrected in production by using a harness with over current protection properly located. This has been corrected at the supplier.

**Recall Schedule :**

Description of Recall Schedule : Notification will be sent within the 60 day requirement

Planned Dealer Notification Date : DEC 03, 2021 - DEC 03, 2021

Planned Owner Notification Date : DEC 03, 2021 - DEC 03, 2021

\* NR - Not Reported