

Part 573 Safety Recall Report

21V-843

Manufacturer Name : Mercedes-Benz USA, LLC**Submission Date :** OCT 29, 2021**NHTSA Recall No. :** 21V-843**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Mercedes-Benz USA, LLC

Address : 13470 International Parkway

Jacksonville FL 32218

Company phone : 1-877-496-3691

Population :

Number of potentially involved : 9,120

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2021-2022 Mercedes-Benz S580

Vehicle Type : LIGHT VEHICLES

Body Style : 4-DOOR

Power Train : GAS

Descriptive Information : Mercedes-Benz 2021-2022 S-Class 8862 Vehicles

The recall population was determined through production records.

Vehicles outside of the recall population have the engine control unit software that meets current production specifications.

Production Dates : JUL 29, 2020 - OCT 26, 2021

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 2 : 2021-2022 Mercedes-Benz Maybach S580

Vehicle Type : LIGHT VEHICLES

Body Style : 4-DOOR

Power Train : GAS

Descriptive Information : Mercedes-Benz 2021- 2022 Maybach S-Class 258 vehicles

The recall population was determined through production records.

Vehicles outside of the recall population have the engine control unit software that meets current production specifications.

Production Dates : JUL 29, 2020 - OCT 26, 2021

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Description of Defect :

Description of the Defect : Mercedes-Benz AG (“MBAG”), the manufacturer of Mercedes-Benz vehicles, has determined that on certain Model Year (“MY”) 2021-2022 S-Class and Mercedes-Benz Maybach S-Class (223 platform) vehicles, the engine control unit software might not meet current production specifications.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : In this case, the vehicle may stall shortly after engine start, and a subsequent restart might not be possible. This might occur suddenly without pre-warning, and independent of the driving situation, increase the risk of a crash.

Description of the Cause : Due to a deviation in the software development process of a supplier, an error might occur while accessing the storage of the engine control unit. In this case, it would not be possible to write data from the vehicle immobilizer into the engine control unit after engine start, as intended.

Identification of Any Warning that can Occur : The driver will not receive a warning due to the nature of the failure mechanism.

Involved Components :

Component Name 1 : Engine Control Unit

Component Description : Software ECU

Component Part Number : A1779023611

Component Name 2 : Engine Control Unit

Component Description : Software ECU

Component Part Number : A1769035500

Component Name 3 : Engine Control Unit

Component Description : Software ECU

Component Part Number : A1779023911

Component Name 4 : Engine Control Unit

Component Description : Software ECU

Component Part Number : A1769035600

Supplier Identification :

Component Manufacturer

Name : Robert-Bosch GmbH
Address : Wernerstr. 51
Stuttgart Foreign States The driver
Country : Germany

Chronology :

In July 2021, MBAG launched initial investigations based on individual field reports describing instances in which customers allegedly experienced the subject condition outlined above.

In the further course of the investigation, engine control units from complaint vehicles were analyzed together with the supplier. In September 2021, these investigations concluded that the reported complaints were related to write errors in the control units' internal storage, impairing the proper operation of the vehicle's immobilizer.

In October 2021, potential consequences of the issue were analyzed and potentially affected vehicles were identified.

On October 22, 2021, MBAG determined that a potential safety risk cannot be ruled out and decided to conduct a recall.

Description of Remedy :

Description of Remedy Program : An authorized Mercedes-Benz dealer, will update the engine control unit software on the affected vehicles.

Pursuant to 49 C.F.R. § 577.11(e), MBUSA does not plan to provide notice about pre-notice reimbursement to owners since none of the involved vehicles would have been previously subject to the condition described and all remain covered under the new vehicle warranty.

How Remedy Component Differs from Recalled Component : Engine control unit software according to specifications.

Remedy: software No

Software ECU A1779021919
Software ECU A1769031201

Identify How/When Recall Condition was Corrected in Production : A change in the engine control unit software ensures that this issue can no longer occur from October 27,2021 onwards.

Recall Schedule :

Description of Recall Schedule : Dealers will be notified of the pending voluntary recall campaign on November 5, 2021. Owners will be notified of the voluntary recall campaign before December 28, 2021.
A copy of all communications will be provided when available.

Planned Dealer Notification Date : NOV 05, 2021 - NR

Planned Owner Notification Date : DEC 28, 2021 - NR

* NR - Not Reported