OMB Control No.: 2127-0004

## Part 573 Safety Recall Report

### 21V-867

Manufacturer Name: Autocar, LLC
Submission Date: JAN 10, 2022
NHTSA Recall No.: 21V-867
Manufacturer Recall No.: ACX-2106



#### **Manufacturer Information:**

Manufacturer Name: Autocar, LLC

Address: 551 S WASHINGTON STREET

**HAGERSTOWN IN 47346** 

Company phone: 7654895499

#### **Population:**

Number of potentially involved: 947 Estimated percentage with defect: 100 %

#### **Vehicle Information:**

Vehicle 1: 2019-2022 Autocar Xpeditor

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER Power Train : NR

Descriptive Information: All Xpeditor units manufactured with the suspect programming are included.

Production Dates: SEP 04, 2018 - JUL 19, 2021

VIN Range 1: Begin: 5VCACLDF6KC228021 End: 5VCACLEF8NC237239 ✓ Not sequential

#### **Description of Noncompliance:**

Description of the . The hazard lamps will not function with the ignition off.

Noncompliance:

FMVSS 1: 108 - Lamps, reflective devices, and assoc. Equipment

FMVSS 2: NR

Description of the Safety Risk: Non-compliance as the hazard lighting is disabled with the ignition and

increases the risk of personal injury or a crash.

Description of the Cause: A programming error during Autocar manufacturing that allows the hazard

lighting function to be disabled with the ignition.

Identification of Any Warning Hazard lamps will not function with the ignition off.

that can Occur:

#### **Involved Components:**

Component Name 1: Hazard Light Software

Component Description: Software- Autocar Proprietary

Component Part Number: No part numbers are assigned

#### **Supplier Identification:**

#### **Component Manufacturer**

Name: Autocar LLC

Address: 551 S Washington St

Hagerstown Indiana 47346

**Country: United States** 

#### **Chronology:**

9/16/21 Autocar quality team reported the hazard lighting malfunction following a routine vehicle software update. 9/22/2021 An internal corrective action was issued and assigned to Autocar quality team for investigation. 9/22/21 to 9/29/21, investigation continued, and a new software version created to address the concern and establish a clean point for production. 10/11/21 The new software version was validated and released for production. 10/29/21 Final investigations are completed, and VIN list compiled. 11/1/21 The final investigation results were presented to Autocar management team and decision to move forward with a voluntary safety recall due to non-compliance was made.

#### **Description of Remedy:**

Description of Remedy Program: Autocar will voluntarily initiate an owner notification and recall of all

affected vehicles. Autocar will distribute to owners of affected vehicles an Owner Notification Letter, which will describe the defect and provide instructions for scheduling the inspection/repair of the vehicle at no cost to the vehicle's owner and will instruct vehicle owners who have paid to

have this condition remedied prior to this campaign to seek

reimbursement pursuant to Autocar's General Reimbursement Plan.

How Remedy Component Differs Reprogramming will allow the hazard lighting to function independently

from Recalled Component: from the ignition.

Identify How/When Recall Condition The programming error was corrected and a clean point established for

was Corrected in Production: production 10/29/21.

#### **Recall Schedule:**

# **Part 573 Safety Recall Report**

21V-867

Page 3

Description of Recall Schedule: Dealer and customer notifications are scheduled to begin January 7, 2022

and end January 13, 2022.

Planned Dealer Notification Date : JAN 07, 2022 - JAN 13, 2022 Planned Owner Notification Date : JAN 07, 2022 - JAN 13, 2022

\* NR - Not Reported