OMB Control No.: 2127-0004

Part 573 Safety Recall Report

21V-902

Manufacturer Name: Aluminum Trailer Company (ATC)

Submission Date: NOV 19, 2021 NHTSA Recall No.: 21V-902 Manufacturer Recall No.: NR



Manufacturer Information:

Manufacturer Name: Aluminum Trailer Company (ATC)

Address: 751 N Tomahawk Trail

Nappanee IN 46650

Company phone: 574-773-2440

Population:

Number of potentially involved: 461 Estimated percentage with defect: 39 %

Vehicle Information:

Vehicle 1: 2021-2021 ATC Quest/Raven

Vehicle Type: TRAILERS

Body Style : Power Train : NR

Descriptive Information: On certain, ATC Quest/Raven trailers specifially with a spring assist ramp door

assemblies, an incorrect fastener assembly may have been used as the attachement

point for the cable.

Production Dates: JUN 10, 2021 - SEP 03, 2021

VIN Range 1: Begin: 5JX1A2221MD222160 End: 5JX1C2821ND225207 ✓ Not sequential

Description of Defect:

Description of the Defect: On certain, ATC Quest/Raven trailers specifially with a spring assist ramp door

assemblies, an incorrect fastener assembly (washer, bushing, fastener) may have been used as the attachement point for the cable and may have been

overtorqued.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: If the trailer specified has the incorrect cable fastener assembly and was over

torqued, the excessive stress on the bushing could cause the fastener/bishing assembly to deform and break. If one cable bushing fails, this adds stress to the opposite side bushing potentially causing failure. The failed connection could potentially cause the cables to violently retract. Also if both cable fail,

there will be no assitance to open the ramp door.

Description of the Cause: NR

Identification of Any Warning NR

that can Occur:

Involved Components:

Component Name 1 : NR
Component Description : NR
Component Part Number : NR

Supplier Identification:

Component Manufacturer

Name: Transglobal

Address: 500 North Warpole

Upper Sandusky Ohio 46651

Country: United States

Chronology:

No field failures to date. During regualr QC inspection of trailers, it was noted by a QC inspector that the fastener assembly (bushing, fastener and washer) was compressing the plastic assembly and a small crack int he bushing was identified. An investigation was started and research and testing was completed and it was determined on 11/15/21, that in fact, the bushings could potentially break if over torqued or under extreme stress. It was also determined through testing that if one cable bushing fails, it adds additional stress to the other cable bushing which could potentially cause that bushing to fail. If both cable bushings fail with the door open, the cables may potentially violently retract. Also if both cable fail, the door will have no assitance when opened to close the door. The notification to NHTSA occurred on 11/19/21 in accordance with the reporting rules.

Description of Remedy:

Description of Remedy Program: NR

How Remedy Component Differs NR

from Recalled Component:

Identify How/When Recall Condition NR

was Corrected in Production:

Recall Schedule:

Description of Recall Schedule: NR

Part 573 Safety Recall Report

21V-902

Page 3

Planned Dealer Notification Date : NR - NR Planned Owner Notification Date : NR - NR

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573