# Part 573 Safety Recall Report

Manufacturer Name :Daimler Trucks North America, LLCSubmission Date :DEC 20, 2021NHTSA Recall No. :21V-945Manufacturer Recall No. :FL913



Number of potentially involved : 1,218

Estimated percentage with defect : 4 %

21V-945

### Manufacturer Information :

Manufacturer Name :Daimler Trucks North America, LLCAddress :4747 N. Channel AvenuePortland OR 97217-3849800-745-8000

### Vehicle Information :

Vehicle 1:	2022-2022 Thomas Built Buses Saf-T-Liner C2 School Bus		
Vehicle Type :	BUSES, MEDIUM & HEAVY VEHICLES		
Body Style :			
Power Train :	NR		
Descriptive Information :	On C2 buses equipped with a certain accelerator pedal, the accelerator pedal could be misaligned, allowing it to rub against the floor and potentially stick in an off-idle position without the driver's knowledge.		
Production Dates :	AN 05, 2021 - SEP 22, 2021		
VIN Range 1:	egin: NR End: NR 🗌 Not sequential		

**Population :** 

#### **Description of Defect :**

Description of the Defect :	On affected chassis, the accelerator pedal may be contacting the floor mat potentially wearing a hole into the mat. In a rare, extreme case, the pedal could catch on the edge of the hole, possibly not allowing the pedal to return to idle.
FMVSS 1 :	NR
FMVSS 2 :	NR
	An accelerator pedal stuck in an off idle position, may cause an unexpected loss of control of the vehicle speed, increasing the risk of a crash.
Description of the Cause :	NR
	During a pre-trip or post trip inspection, operators could visually detect wear marks or a hole being worn into the floor mat directly under the accelerator pedal.

#### **Involved Components :**

The information contained in this report was submitted pursuant to 49 CFR §573

## Part 573 Safety Recall Report

Component Name 1 : ACCEL CTRL-C2, ADJ Component Description : ELECTRONIC ACCELERATOR CONTROL Component Part Number : A01-34001-000

Component Name 2 :ACCEL CTRL-C2, ADJComponent Description :ELECTRONIC ACCELERATOR CONTROLComponent Part Number :A01-34001-001

#### **Supplier Identification :**

#### **Component Manufacturer**

Name : Kongsburg Automotive Address : NR NR Country : NR

Chronology :

In September of 2021, DTNA received a complaint from a dealer of the throttle pedal sticking to the floor. DTNA immediately opened an investigation into the issue. From late September thru mid-October, DTNA conducted inspections on similarly configured buses at Thomas Built Bus and at Freightliner Custom Chassis. In mid-October, an engineering design evaluation was conducted. In late October, suspect parts were sent to the supplier for testing. In early November, DTNA began its own testing of parts in parallel with the supplier. In mid-November, additional warranty analysis reports were reviewed as well as any customer complaint tickets. On Dec. 1, 2021, DTNA with an abundance of caution, decided to conduct a voluntary recall campaign on certain Thomas Built Buses Saf-T-Liner C2 model school buses with the potential for the accelerator pedal to stick. There are no reported injuries or deaths related to this issue.

The initial report contained three additional VINs, alleging to have pedal contact with the floor matting. In mid October, a warranty report revealed a single claim filed in late Sept. 2021 for the pedal contacting the floor. No deaths or injuries have been reported for this issue.

# Part 573 Safety Recall Report

Page 3

Description of Remedy :		
Description of Remedy Program :	The accelerator pedal assembly will be inspected and replaced if necessary. Repairs will be performed by Daimler Trucks North America authorized service facilities. Details of the reimbursement plan will be included in the owner's notification letter.	
How Remedy Component Differs from Recalled Component :	NR	
Identify How/When Recall Condition was Corrected in Production :	NR	
Recall Schedule :		
Description of Recall Schedule : Customer notification will be made by first class mail using Daimle		
Planned Dealer Notification Date :	Trucks North America records to determine the customers affected. FEB 05, 2022 - FEB 05, 2022	
Planned Owner Notification Date :		

\* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573