Part 573 Safety Recall Report

Manufacturer Name :	Carson Trailer, Inc.
Submission Date :	DEC 15, 2021
NHTSA Recall No. :	21V-948
Manufacturer Recall No. :	Recall4

Manufacturer Information :

Manufacturer Name : Carson Trailer, Inc. Address : 14831 S. Maple Ave

Gardena CA 90248 Company phone : 999

Vehicle Information :

Vehicle 1 : 2018-2020 Dometic R1731			
Vehicle Type : TI	Vehicle Type : TRAILERS		
Body Style : VA	AN		
Power Train : N	R		
Descriptive Information : Dometic the manufacturer became aware of warranty leak back in May 2020. Dometic hasn't determined the cause of these leaks. But is continuing to gather facts and the potential defect and will forward additional relevant information as it becomes available.			
Production Dates : M	IAY 01, 2018 - JUL 09, 2020		
VIN Range 1 : Beg	gin: 4hxb22025lc214341 End	: 4hxb22025lc214341	Not sequential
VIN Range 2 : Beg	gin : 4hxb22025lc214341 End	4hxb22025lc214341	Not sequential
VIN Range 3: Beg	gin: 4hxb22025lc214341 End	4hxb22025lc214341	Not sequential
VIN Range 4 : Beg	gin: 4hxb22025lc214341 End	4hxb22025lc214341	Not sequential
VIN Range 5 : Beg	gin: 4hxb22025lc214341 End	4hxb22025lc214341	Not sequential
VIN Range 6 : Beg	gin: 4hxb22025lc214341 End	4hxb22025lc214341	Not sequential
VIN Range 7 : Beg	gin: 4hxb22025lc214341 End	4hxb22025lc214341	Not sequential
VIN Range 8: Beg	gin: 4hxb22025lc214341 End	4hxb22025lc214341	Not sequential
Vehicle 2 : 2018-2020 Fun Runner FC20			
Vehicle Type : TRAILERS			
Body Style : VA			
Power Train : N	R		
Descriptive Information : ga	as leak		
Production Dates : M	IAY 18, 2018 - JUL 09, 2020		



Number of potentially involved :

Estimated percentage with defect : 100 %

Population :

3

21V-948

Page 2

Description of Defect :

Description of the Defect :	The defect enunciation can occur in a mobile environment, such as recreational vehicle. generally after an install or usage period of 3 to 6 months. User of the appliance smells gas and apparently attempts to tighten the securement bolts that hold one or more the stove saddle valves in place and sealed to the manifold. this action may result in the overtightening of the securement bolt for the saddle valve which may cause damage to the o-ring seal between the saddle valve and the manifold resulting in a continuous gas leak that is readily detectable from the smell.
FMVSS 1 :	NR
FMVSS 2 :	NR
Description of the Safety Risk :	overtightening of the saddle valve securement bolt onto the manifold of the stove may cause a gas leak which may ignite and cause a fire.
Description of the Cause :	Dometic has not determined the cause of these leaks but is continuing to gather facts on the potential defect and will forward additional relevant information as it becomes available.
Identification of Any Warning that can Occur :	The smell of gas fumes are indicative of the identified leak.

Involved Components :

Component Name 1:	gas stove
Component Description :	3 burner cooking stoves
Component Part Number :	s31,r1731,r2131

Supplier Identification :

Component Manufacturer

Name : DOMETIC CORP Address : 5155 VERDANT DR ELKHART Indiana 46516 Country : United States

Chronology:

Dometic has not determined the cause of these leaks

The information contained in this report was submitted pursuant to 49 CFR §573

Description of Remedy :

Description of Remedy Program :	the overtightening of saddle valve securement bolt on the manifold of the stove may cause a gas leak.
	Dometic has not yet identified a proposed remedy or remedies designed to mitigate the defect but will advise NHTSA of such remedy or remedies at the time they are identified
Identify How/When Recall Condition was Corrected in Production :	Dometic does have a fix in place they are currently processing all of the recall kit requests.

Recall Schedule :

Description of Recall Schedule :	NR
Planned Dealer Notification Date :	DEC 20, 2021 - DEC 23, 2021
Planned Owner Notification Date :	JAN 10, 2022 ⁻ JAN 31, 2022

* NR - Not Reported