#### OMB Control No.: 2127-0004

# Part 573 Safety Recall Report

Manufacturer Name :Terex Advance Mixer, Inc.Submission Date :JAN 03, 2022NHTSA Recall No. :21V-981Manufacturer Recall No. :NR

### Manufacturer Information :

Manufacturer Name : Terex Advance Mixer, Inc. Address : 7727 Freedom Way Fort Wayne IN 46818 Company phone : 999

### **Population** :

Number of potentially involved : 1,016 Estimated percentage with defect : 100 %

### Vehicle Information :

|                           | 2016-2022 Terex Advance Mixer Front Discharge Mixer Trucks<br>BUSES, MEDIUM & HEAVY VEHICLES  |  |  |  |
|---------------------------|---|--|--|--|
| Body Style :              | OTHER   |  |  |  |
| Power Train :             | DIESEL  |  |  |  |
| Descriptive Information : | The Cummins engines installed in the impacted vehicles are equipped with High<br>Pressure Common Rail fuel systems and sold for installation in mixer trucks (Terex<br>vehicles). The recall consists of the entire population of engines equipped with a<br>certain injector fuel supply tube (fuel tube) prior to the implementation of corrective<br>action. |  |  |  |
| Production Dates :        | APR 26, 2016 - OCT 01, 2021   |  |  |  |
| VIN Range 1:              | Begin :NREnd :NRNot sequential  |  |  |  |

### **Description of Defect :**

| Description of the Defect :      | The fuel tubes between the fuel rail and the injector for cylinders 4, 5 and 6 may be susceptible to cracking, resulting in a high pressure fuel leak.  |
|----------------------------------|---|
| FMVSS 1 :                        | NR  |
| FMVSS 2 :                        | NR  |
| Description of the Safety Risk : | A high pressure fuel leak in the presence of an ignition source may increase the risk of fire.  |
| Description of the Cause :       | The subject fuel tubes (for cylinders 4, 5 and 6) are susceptible to cracking due to metal fatigue failure resulting from a combination of vibration strain, assembly strain and material strength. |
|                                  | Fuel leaks may be detected during maintenance. An operator may smell fuel or observe a mist due to the fuel leak.   |

### **Involved Components :**

The information contained in this report was submitted pursuant to 49 CFR \$573



21V-981

# Part 573 Safety Recall Report

| J = J = J = J = J = J = J = J = J = J =  |
|--|
|  |
|  |
| Component Name 1 : NR  |
| Component Description : NR   |
| Component Part Number : NR   |
|  |
| Supplier Identification :  |
| Component Manufacturer   |
| Name : Cummins, Inc.   |
| Address : 500 Jackson Street   |
| Columbus Indiana 47202-3005  |
| Country : United States  |
|  |
| Chronology :   |
| Cummins notified Terex Advance Mixer on December 10, 2021 that they were declaring a safety recall (21E-099).    |
| Terex agrees with Cummins determination and are filing a 573 defect report to formalize this.                    |
| Cummins will manage the campaign through their dealer body and file quarterly completion updates.                |
| Terex will cooperate with Cummins to identify affected VINs and provide customer contact information to Cummins. |
| Cummins.   |
|  |
|  |
| Description of Remedy :  |
| Description of Remedy Program : Cummins to manage  |
| How Remedy Component Differs NR<br>from Recalled Component :   |
| Identify How/When Recall Condition NR<br>was Corrected in Production :   |
|  |

## **Recall Schedule :**

| Description of Recall Schedule :   | NR |      |
|------------------------------------|----|------|
| Planned Dealer Notification Date : | NR | - NR |
| Planned Owner Notification Date :  | NR | - NR |

\* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573