News Channel Update | Vans Customer Service and Parts

To: Mercedes-Benz Principals, General Managers, Sales Managers, Service Managers, Parts Managers	From: Anthony Washington, Department Manager, Regulations and Certifications
Re: Recall Campaign Launch Notification Models 907 (Sprinter) Model Years 2019 Update Incorrect VIN	Date: May, 2021



IMPORTANT RECALL CAMPAIGN INFORMATION

Please see the attached documents related to the campaign listed above





News Channel Update | Vans Customer Service and Parts

Campaign No. :	Campaign I	Desc. :		
2021xxxxxx	VS3VINC	CHA CHA	Update incorrect VIN	
This is to notify you of an upcoming Recall Campaign concerning correcting the VIN on 1 MY19 Mercedes-Benz Sprinter van. The recall campaign will be visible on the <u>www.safercar.gov</u> website and may generate questions from the customer. All affected VIN will be flagged " OPEN " in VMI and <u>cannot be sold</u> .				
		Ba	ackground	
Issue	Mercedes-Benz AG (MBAG), the manufacturer of Mercedes-Benz vans, has determined that on one platform 907 (VS30) Sprinter vehicle, the VIN number listed on the vehicle's dashboard, certification label and body-in-white is not recorded accurately. The affected vehicle that does not comply with 49CFR567. As a result, the consumer may not receive information about open safety-recall campaigns.			
What We're Doing	An authorized Mercedes-Benz Sprinter dealer will replace the VIN Labels on the dash and the seat frame base, as well as engrave a new VIN on the firewall.			
Parts	Parts are available	e		
		Veh	icles Affected	
Vehicle Model Year(s)	2019			
Vehicle Model (s)	Sprinter(907)			
		Vehi	cle Populations	
Total Recall	1			
Dealer Inventory	0			
Given this notice, it			aler to sell or lease any <u>new</u> Sprinter vehicles in dealer inventory nuntil the vehicle has been repaired.	
Loaner a	nd demonstrator veh	icles may conti	nue to be driven, but must not be retailed until repaired.	
Additionally, given th	· · ·		<u>aw</u> for rental companies to rent new Sprinter vehicles covered by this the vehicle has been repaired.	
		Next	Steps/Notes	
Customer Notificat	ion Timeline	An owner notif	ication letter will be mailed Mid-May, 2021.	
		AOMs – This re notice to your	call may generate questions from your dealers. Please forward this dealers ASAP.	
Rental Fleet Partners fleet representa		fleet represent	affect vehicles in your fleet. Please contact your respective MBUSA tative for further information and next steps. For repairs, please preferred MBUSA dealer.	
While we regret any inconvenience this may cause, we are determined to maintain a high level of vehicle quality and customer satisfaction.				



A Daimler AG Company



Recall Campaign Bulletin



Mercedes-Benz

Campaign No. 2021050004, May, 2021

TO: ALL MERCEDES-BENZ CENTERS

SUBJECT: Model 907 Sprinter, Model Year 2019 Update Incorrect VIN

Mercedes-Benz AG (MBAG), the manufacturer of Mercedes-Benz vans, has determined that on one platform 907 (VS30) Sprinter vehicle, the VIN number listed on the vehicle's dash board, certification label and body-in-white is not recorded accurately. As a result, the consumer may not receive information about open safety-recall campaigns. An authorized Mercedes-Benz Sprinter dealer will update the VIN to reflect the accurate information and replace the vehicle certification label and the VIN label at the dash board on the affected vehicle.

Prior to performing this Recall Campaign:

- Please check VMI to determine if the vehicle is involved in the Campaign and if it has been previously repaired.
- Please review the entire Recall Campaign bulletin and follow the repair procedure exactly as described.

Please note that Recall Campaigns **do not expire** and may also be performed on a vehicle with a vehicle status indicator.

Only **1** vehicle is involved.

Order No. V-RC-2021050004 This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.

UIJƏIING UBIEdwen IISE

Recall Campaign Bulletin

Campaign Bulletin

SM60.00-D-0005SG	Adjust vehicle identification number (code: VS3VINCHA,	22.04.2021
	acc. no.: 58 917 64)	

Model 907.7

with code ZU8 (National version for USA)

Operation no. of the operation texts or standard texts and flat rates

Category	Op. no.	Operation text	Time	Damage Code	Code
L	02 1341	Operations: Adjust vehicle identification number	0.8hrs	58 917 64	VS3VINCHA
L	85 9800	Carry out spot repair, location:	ZM (as needed)	58 917 64	VS3VINCHA

1 Information label



D60.00-A054-06



2 Information label

3 Instrument panel



4 Reserve field for vehicle identification number

5

D60.00-A056-79 Standard field for vehicle identification number

≜ Caution	Risk of injury caused by scraping or cutting body parts on sharp vehicle parts	Always wear protective gloves when working on or near sharp and non-deburred vehicle parts. Deburr repair panels.	AS00.00-Z-0017-01A
Notice	Notes on carrying out repair work in the vehicle interior		AH68.00-N-0001-01S
4	Check		
1	Check whether vehicle is affected by measure.	i For authorized Mercedes-Benz service partners, only the entry in the Extended VEGA Application (EVA) system, in the "Current" tab, is decisive. An additional test of the affected vehicles in the workshop information system (WIS) or vehicle list is thereby not necessary.	
	Replace		
2	Replace information label (1).	Bonding surface must be absolutely dry and free of dust and grease.	
		This prevents any adhesion problems.	
		i Incorrect vehicle identification number:	
		WDZPF0ED6KT016360	
		Correct vehicle identification number:	
		W1Z40FHYXKT016360	
		Cleaner	BR00.45-Z-1025-04A
3	Replace information label (2).	Bonding surface must be absolutely dry and free of dust and grease.	
		This prevents any adhesion problems.	
		Incorrect vehicle identification number:	
		WDZPF0ED6KT016360 Correct vehicle identification	
		number: W1Z40FHYXKT016360	
		i Aid of helper required.	
		Cleaner	BR00.45-Z-1025-04A

X	Remove		
4	Remove ventilation box.		
₩ AR			AR83.10-D-0010TS
5	Remove engine compartment seal in area of reserve field (4).		
	Punch in VIN		
6	Stamp correct vehicle identification number into reserve field (4).		
₩AR		 i Cross out incorrect vehicle identification number in standard field (5). i Incorrect vehicle identification number: 	AR60.00-D-0800TS
		WDZPF0ED6KT016360 Correct vehicle identification number:	
		W1Z40FHYXKT016360	
		Stamping guide	906 589 10 63 00
		Star marking punch	000 589 02 39 00
		S Letter marking punch	000 589 00 39 00
		S Letter marking punch	000 589 03 39 00
		S Die stamp numbers	000 589 01 39 00
<u> </u>	Risk of explosion caused by paint vapors igniting. Risk of poisoning caused by inhaling paint vapors.	No smoking! No open fire! Use respiratory protection, protective clothing, gloves, safety glasses and protective skin cream. Ensure that the area is well ventilated.	AS98.00-Z-0002-01A
7	Paint repair area and adjacent surfaces using a brush or spray can.		
Notice	Notes on paintwork repairs	i Use only paints approved by Daimler AG: http://xentryportal.mercedes- benz.com	AH98.00-P-9408-02A
		If there is a repair point in the visible area, ↓ apply spot repair.	
X	Install	- FL.7 - F	
8	Attach engine compartment seal.		
9	Install ventilation box.		
9 ₩ F AR			AR83.10-D-0010TS



Stamping guide

000 589 03 39 00

Letter marking punch





Star marking punch

Die stamp numbers



Letter marking punch

Repair materials

Number	Designation	Order number
BR00.45-Z-1025-04A	Cleaner	A 005 989 19 71

Parts ordering note

Part no.	Designation	Quantity
A 907 584 34 05	Information label (identification plate)	1
A 906 584 80 38	Information label (vehicle identification number)	1