ATTENTION: Dealer Principal, Warranty Manager, Service Manager, Parts Manager Freightliner Dealers – U.S. and Canada Western Star and Sterling Dealers - U.S. and Canada FCCC Dealers - U.S. and Canada Direct Warranty Customers - U.S. and Canada Export Distributors

01/12/2022

REF #: ICI22-002

Release: 01/12/2022

Effective:

Daimler Trucks North America LLC



This letter is to inform you that a revised bulletin for DETROIT[™] Recall Campaign D21R7, *Tie* Rod Clamp (Lock nut) Over-Crimped is available on DTNAConnect. Please print and use the revised bulletin for all work under D21R7 from this point forward.

REVISION 1: D21R7 Work Instructions are being modified by removing the *Tie Rod Inspection* and Mileage Check as well as removing the Clamp - Locknut Replacement. Going forward it will only be necessary to proceed with the *Tie Rod Assembly Replacement* instructions.

REVISION 2: As a result of Revision 1, Table 1 has been adjusted accordingly. Tables 2 and 3 have been modified with updated SRTs and labor times that include test drive and account for the repairing outlets that may not have an alignment rack and need to sublet out this portion of the repair.

REVISION 3: Step 12 of the Corrective Procedure has been modified with a specific reminder in order to perform the alignment properly. This was already part of the workshop manual alignment instructions.

REVISION 4: Step 14 of the Corrective Procedure was added for test drive after bumper install to calibrate the Electronic Stability Control system.