



***Jaguar Land Rover North America, LLC has informed the National Highway Traffic Safety Administration (NHTSA) of its intent to perform a Recall on certain Land Rover vehicles imported into the United States market. Information relating to this Recall will be posted on the National Highway Traffic Safety Administration website.***

***United States Federal regulations require that retailers must be notified within a reasonable time after the manufacturer decides that a defect that relates to motor vehicle safety or a noncompliance exists.***

***United States Federal law requires retailers to complete any outstanding Recall service before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a retailer could result in a maximum civil penalty of up to \$22,992.00 per violation and \$114,954,525.00 for a related series of violations.***

***This Aftersales Bulletin serves as notification to all Land Rover retailers in the United States and Federalized Territories that any affected new vehicles may not be sold and delivered for customer use until the Recall repair is completed.***

## **DESCRIPTION OF ISSUE**

An issue has been identified on certain Land Rover vehicles within the listed Affected Vehicle Range where, due to insufficient contact of the battery ground stud to the chassis, the vehicle may exhibit various electrical faults. The vehicle could cut out while in motion and may lose all electrical power.

## **AFFECTED VEHICLE RANGE**

A total of 1,383 vehicles are potentially involved in the USA and Federalized Territories.

Discovery

Model Year: .....2020-2021

VIN: ..... SALRU2RV3L2427521-SALRT2RV7L2446236

..... SALRT4RU1M2446804-SALRT4RU3M2453141

Visit the British Brands Sales Suite (BBSS) website for a list of affected vehicles at your retailer.

## **EFFECT ON VEHICLE OPERATION**

Vehicle cut out while in motion and loss of exterior lighting without warning to the driver could lead to an increased risk of a crash.

## **SERVICE PROGRAM / REWORK ACTION**

Owners will be notified by mail and instructed to take their vehicle to an authorized retailer who will replace the ground stud with an aftermarket specification part. There will be no charge to owners for this action under this Program.

Unsold vehicles must have this done as part of the Pre-Delivery Inspection (PDI) process and/or before vehicle handover to the customer.

## **OWNER NOTIFICATION**

Owner notification is expected to occur on or before August 13, 2021.

## **ACTION TO BE TAKEN**

Use the Jaguar Land Rover claims submission system to make sure that the vehicle is affected by this Program prior to undertaking any rework action.

Retailers are required to HOLD affected new vehicles that are within your control and refrain from releasing the vehicles for new vehicle sale pending completion of the rework action.

Jaguar Land Rover North America, LLC recommends that affected sales demonstrator and loaner vehicles are repaired before use and that used vehicles are repaired before sale. Retailers who choose to proceed against this recommendation, where legally permitted, must clearly and conspicuously disclose the open recall to the applicable customers.

A Technical Bulletin will be published once repair instructions are finalized and any required parts have been procured.

Thank you for your cooperation in this matter. Jaguar Land Rover North America apologizes for any inconvenience this may cause.