


# AMB7 Recall campaign – Replacing axle carrier side section



## AMB7 Recall campaign - Replacing axle carrier side section

### Overview

There is a possibility that carrier side sections that do not meet the required specifications, due to a manufacturing error, were installed on the rear axle of the affected vehicles.

If this is the case, one or both wishbone mounts on the carrier side section can break over the service life of the vehicle.

If both mounts break, this would result in impaired wheel guidance. A potential loss of control of the vehicle cannot be ruled out if this happens.

To prevent this, the carrier side sections at the left and right must be replaced on the affected vehicles.

**Model type**

Boxster (981)

	Cayman (981)
<b>Model year</b>	2013 to 2015
<b>Number</b>	4,932

## Porsche Mobility

If requested, the mobility of the affected customer can be guaranteed by offering a suitable replacement vehicle.

Please invoice this additional service with the campaign scope via WWS.

## Parts required

Part number	Designation	Quantity/vehicle	Parts return request*
V04015800AM	Rear-axle carrier side section	1	No
V04015800AN	Rear-axle carrier side section	1	No
99907340201	Cheese head bolt, M12 x 1.5 x 72	4	No
9A700758500	Cheese head bolt, M12 x 1.5 x 85	4 (only for I-no. 450)	No
99907284301	Combination screw, M10 x 80	2	No
99907282901	Hexagon-head bolt, M10 x 45	2	No
99733121703	Eccentric screw	2	No
99908444501	Lock nut, M12 x 1.5	2	No
99908444909	Lock nut, M12 x 1.5	2	No
99907289001	Lock nut, M12 x 1.5	2	No
PAF103353	Lock nut, M12 x 1.5	2	No
99908412309	Collar nut, M10	2	No
PAF008868	Hexagon nut, M10	2	No

\* The parts must be stored until such a time as **the related warranty or campaign claim has been credited in WWS**. If a **barcode is generated** with the credit note, the affected part must be sent to Porsche AG as usual. If no barcode is generated with the credit note, the part can go directly into the genuine remanufactured parts process or be scrapped.

## Warranty processing

Please enter the campaign that was carried out in the Warranty and Maintenance booklet for the vehicle.

### Scope 1:

- **Vehicles without PCCB (Porsche Ceramic Composite Brake)**

Damage code	<b>AMB7 99 000</b>
Repair code	<b>2</b>
Working time	<b>484 TU</b>

### Scope 2:

- **Vehicles with PCCB (Porsche Ceramic Composite Brake) (I-no. 450)**

Damage code	<b>AMB7 99 000</b>
Repair code	<b>2</b>
Working time	<b>484 TU</b>

### Scope 3:

- **Vehicles without PCCB (Porsche Ceramic Composite Brake)**
- **Automatic distance control (ACC) (I-no. 456)**

Damage code	<b>AMB7 99 000</b>
Repair code	<b>2</b>
Working time	<b>525 TU</b>

### Scope 4:

- **Vehicles with PCCB (Porsche Ceramic Composite Brake) (I-no. 450)**
- **Automatic distance control (ACC) (I-no. 456)**

Damage code	<b>AMB7 99 000</b>
Repair code	<b>2</b>
Working time	<b>525 TU</b>

### Scope 5:

- **Vehicles without PCCB (Porsche Ceramic Composite Brake)**
- **Speed limit display (Traffic sign recognition) (I-no. 631)**

Damage code	<b>AMB7 99 000</b>
Repair code	<b>2</b>
Working time	<b>509 TU</b>

## **Scope 6:**

- **Vehicles with PCCB (Porsche Ceramic Composite Brake) (I-no. 450)**
- **Speed limit display (Traffic sign recognition) (I-no. 631)**

Damage code	<b>AMB7 99 000</b>
Repair code	<b>2</b>
Working time	<b>509 TU</b>

## **Scope 7:**

- **Vehicles without PCCB (Porsche Ceramic Composite Brake)**
- **Speed limit display (Traffic sign recognition) (I-no. 631)**
- **Automatic distance control (ACC) (I-no. 456)**

Damage code	<b>AMB7 99 000</b>
Repair code	<b>2</b>
Working time	<b>540 TU</b>

## **Scope 8:**

- **Vehicles with PCCB (Porsche Ceramic Composite Brake) (I-no. 450)**
- **Speed limit display (Traffic sign recognition) (I-no. 631)**
- **Automatic distance control (ACC) (I-no. 456)**

Damage code	<b>AMB7 99 000</b>
Repair code	<b>2</b>
Working time	<b>540 TU</b>