



MAZDA DEALER EMAIL

August 12, 2022

Attention: Mazda General, Parts and Service Managers

Subject: Safety and Emissions Recall 5321K – Fuel Delivery Module (FDM) Harness Ordering Update

Dear Mazda Dealer Partners,

During the repair of this recall, some dealer technicians have found damage to the short cord contained in the Fuel Delivery Module. This required a call to the Mazda Technical Hotline for a replacement short cord harness to be sent to the dealership.

Effective Monday August 15, if the dealer technician discovers there is damage to the short cord, Mazda dealers can now order the harness using the part numbers below via the Restricted Parts Ordering (RPO) screen in eMDCS. The Repair Procedure and Parts & Warranty Information have been updated on Mazda Global Service Support (MGSS) to reflect this change.

NOTE: *When placing the order on the RPO screen you should select CEO to have the part sent via overnight delivery. The harness parts are not orderable for stock at dealers due to the very low failure rates and must be ordered individually. To order, you must provide the VIN of the vehicle currently under repair. Orders will be matched to the RO and VIN claim submission. While waiting for parts to arrive, place the customer in an MCVP vehicle if needed, and any request for a rental car must follow Mazda Warranty guidelines.*

5321K - FDM Harness Part Number	Model
2921-35-0021	CX-5
2921-35-0321	CX-3 (2WD), Mazda6, CX-9, Mazda3*, Mazda2*
2921-35-1074	MX-5
2921-35-0181	CX-3 (AWD)

* Mexico, Canada or US Territory vehicles only

We appreciate everyone's patience and support in carrying out this recall and all Mazda campaigns. If you have recall questions, please fill out the Dealer Recall Help form on OneMazda ([Click here](#)).

Protect What is Important to You

Sincerely,

Travis Young
Manager Recalls, Technical Services Division
Mazda North American Operations

MAZDA NORTH AMERICAN OPERATIONS