



SAFETY RECALL

CAMPAIGN BULLETIN Fuel Pump Voluntary Safety Recall Campaign

Reference: R21B8
Date: March 1, 2022

Attention: Dealer Principal, Sales, Service & Parts Managers

IMPORTANT: It is a violation of Federal law for dealers to sell or deliver vehicles in their inventory covered by this notification until the campaign action is performed.

UPDATE March 1, 2022
Please discard earlier versions of this bulletin.

The announcement from December 10, 2021 has been revised to include:

- The following parts have been placed on parts restriction. Dealers may place an SVC order for the parts listed below via DBS **beginning March 1, 2022**. Orders will be fulfilled in the order they were received.
 - **17040-6RE0B** – Fuel Pump-In Tank (2WD)
 - **17040-6RE1B** – Fuel Pump-In Tank (4WD)
 - **17343-6RE0B** – Lock Ring
 - **17342-9TA0A** – O-Ring

Affected Models/Years:	Affected Population:	Dealer Inventory:	SERVICE COMM Activation date:	Stop Sale In Effect
MY2021 Rogue (T33)	24,793	76	December 10, 2021	YES

****** Campaign Summary ******

Nissan is issuing a Voluntary Safety Recall Campaign on specific 2021 Rogue (T33) vehicles identified in Service Comm to replace the fuel pump assembly.

Due to a supplier manufacturing assembly error, affected fuel pumps may experience abnormal wear between the fuel pump brush and commutator, which may cause excess heat and melting damage. If this condition is present, the fuel pump module may fail, which may result in an engine stall while driving, increasing the risk of a crash. Alternatively, the engine may not start because of this condition.

****** What Dealers Should Do******

- Verify campaign applicability using Service Comm or DBS National Service History – Open Campaign I.D. **R21B8**.
 - New vehicles in dealer inventory can also be identified using DBS (Sales-> Vehicle Inventory, and filter by Open Campaign).
 - Refer to NPSB 15-460 for additional information
 - Please continue to check newly arriving inventory for campaign applicability.**
- Dealers **must not sell, lease trade, rent or loan** any vehicles in dealer inventory subject to this recall campaign until after the vehicle has been remedied.

3. Dealers should use **NTB21-113** to correct any vehicles subject to this campaign once parts become available.
4. Once remedied, dealers should submit the claim, using the claims coding provided, and release the vehicle.

****** Release Schedule ******

Parts	<p>The following parts have been placed on parts restriction. Dealers may place an SVC order for the parts listed below via DBS beginning March 1, 2022. Orders will be fulfilled in the order they were received.</p> <ul style="list-style-type: none"> ➤ 17040-6RE0B – Fuel Pump-In Tank (2WD) ➤ 17040-6RE1B – Fuel Pump-In Tank (4WD) ➤ 17343-6RE0B – Lock Ring ➤ 17342-9TA0A – O-Ring
Special Tool	<ul style="list-style-type: none"> • J-45747 (Fuel Tank Lock Ring Wrench) <p>Additional tools are available via TechMate @ 1-800-662-2001 or www.nissantechmate.com.</p>
Repair	<ul style="list-style-type: none"> • NTB21-113
Owner Notification	<p>Nissan began sending notifications to owners of all potentially affected vehicles in January 2022 via U.S. Mail.</p>

****** Dealer Responsibility ******

It is the dealer's responsibility to check Service Comm or DBS National Service History Open Campaign using the appropriate Campaign I.D. for the campaign status on each vehicle falling within the range of this voluntary safety recall campaign, which for any reason enters the service department. This includes vehicles purchased from private parties or presented by transient (tourist) owners and vehicles in dealer inventory. If a VIN subject to this recall campaign was part of a dealer trade, the letter associated with that VIN should be forwarded to the appropriate dealer for service completion.

NISSAN NORTH AMERICA, INC.

Aftersales DIVISION

Frequently Asked Questions (FAQ):

Q. Is this a Stop Sale?

A. Yes.

Q. What is the reason for this safety recall?

A. Due to a supplier manufacturing assembly error, affected fuel pumps may experience abnormal wear between the fuel pump brush and commutator, which may cause excess heat and melting damage.

Q. What is the possible effect of the condition?

A. If this condition is present, the fuel pump module may fail, which may result in an engine stall while driving, increasing the risk of a crash. Alternatively, the engine may not start because of this condition.

Q. What will be the corrective action?

A. Dealers will replace the fuel pump assembly.

Q. How long will the corrective action take?

A. The remedy should take approximately one (1) hour to complete. However, your Nissan dealer may require the vehicle for a longer period of time based upon their work schedule.

Q. When will vehicle owners be notified?

A. Nissan began sending notifications to owners of all potentially affected vehicles in **January 2022** via U.S. Mail.

Q. Is my vehicle safe to drive?

A. If any of the following conditions occur, please contact your local Nissan dealer for instructions on how to transport your vehicle to the dealership for immediate inspection:

- Engine stall with Malfunction Indicator Lamp (MIL) illuminated
- No start
- Poor acceleration
- Rapid change or fluctuations in engine Revolutions Per Minute (RPMs) visible on the combination meter

If your vehicle is subject to this campaign, you will receive an Owner Notification letter from Nissan, which will provide instructions on how to remedy your vehicle. Affected owners are encouraged to have their vehicles remedied as soon as possible upon notification.

Q. Is there anything owners can do to mitigate this condition?

A. No.

Q. Is there any charge for this repair?

A. No, the remedy will be performed for the customer free of charge for parts and labor.

Q. Are parts readily available?

A. Parts are on restriction and may be ordered via DBS.

Q. Will I have to take my vehicle back to the selling dealer to have the service performed?

A. No, any authorized Nissan dealer is able to perform the recall campaign.

Q. Will a rental vehicle be provided while the dealer is servicing the vehicle?

A. Please consult your dealer for alternate transportation availability while your vehicle is being serviced. Rental is available upon customer request, while parts are on order.

EXPENSE CODE	DESCRIPTION	AMOUNT
502	Rental Expense	\$156 (Max)
Contact the Warranty claims call center 1-800-258-7008 Option 7, if additional expense is required. Please refer to the Goodwill Rental Guidelines in the APRM for detailed information regarding application of rental reimbursement.		

Q. Is towing covered for vehicles outside of warranty that are no longer eligible for Nissan Roadside Assistance?

A. Yes, the campaign will cover the towing costs for affected vehicles that are no longer eligible for Roadside Assistance (out of warranty):

EXPENSE CODE	DESCRIPTION	AMOUNT
501	Towing	\$100 (Max)
Contact the Warranty claims call center 1-800-258-7008 Option 7, if additional expense is required.		

Q. I have lost confidence in the vehicle. Will Nissan replace or repurchase the vehicle?

A. The remedy will fully correct this condition. As the condition will be corrected, there is no basis for repurchasing or replacing your vehicle.

Q. What model year vehicles are involved?

A. Certain 2021 Rogue vehicles manufactured from October 16, 2020 to May 21, 2021 at the Kyushu plant are affected.

Revision History:

Date	Announcement	Purpose
December 10, 2021	Voluntary Safety Recall Campaign	New campaign announcement
March 1, 2022	REVISION 1	Parts Update