

Technical Service Bulletin

 Technical Service Bulletin: TSB210146
 Released Date: 13-Sep-2021

Safety Campaign #4495 RBAB Lift Cable Crimp Issue

Safety Campaign #4495 RBAB Lift Cable Crimp Issue

Warranty Statement

The information in this document authorizes specific changes to the repair practice for failures covered under product warranty coverages.

Contents

Product Affected

RBAB Spec G

lssue

Symptom:

• Lifting cable around the alternator may be improperly crimped and unable to carry its rated weight, which condition may cause the cable to fail during lifting.

Root Cause:

• Cable supplier quality issue with crimping tool.

Verification/Confrimation

If the unit has one of the serial numbers listed below, the unit needs to be inspected for uncrimped cable ferrules. If the cable ferrules do not have a marking on them to show it has been crimped, (see arrows in Figure 1 below) the cable needs to be replaced.

<image/> <image/>		
Table 4 Serial Number	Figure 1, Cable Marl	kings
Table 1, Serial NumberA210866229	B210891579	D210915365
A210866230	C210891527	D210915366
A210866231	C210891528	D210915367
A210867286	C210900416	D210919566
B210875016	C210902316	D210919567
B210875018	C210904096	D210919600
B210891526	D210906237	E210919559
B210891556	D210906240	E210919561
B210891576	D210909137	E210919562
B210891577	D210915363	
B210891578	D210915364	

If the unit is found to have one of the above serial numbers, follow the below steps in the resolution to inspect and/or replace the cable.

Note: This issue has been resolved by the supplier. New cables and generator sets outside of this serial number list do not have ferrule crimping issues.

Resolution

Warning: Ensure Engine is off and generator set is not connected to a power source to prevent accidental running of the generator set.

Warning: Wear the appropriate PPE to protect worker while performing this repair.

Warning: The generator set is over 90 kg (200 lbs). Use caution when lifting.

Warning: Do not use the lifting eye cable to lift the unit. Use an alternative method.

1. If installed, lift unit out of vehicle using 4 lifting holes on each side. Do not use lifting eye cable




2. Remove front enclosure panel.



Figure 3, Front Panel Removed

3. Remove left side enclosure panel and grate.






5. Inspect the cable ferrules for the marking to see if the unit's cable is properly crimped. The cable can also be visually inspected for a crimped cable.



Note: If cable has no crimp marking, continue to follow the steps below and replace the cable. If cable is marked (and properly crimped), no repair is required. Replace enclosure panel.

Note: To order replacement cable, see 'Service Instructions' section below.

6. Remove right side enclosure panel and cut cable tie to slide wire leads through enclosure panel



7. Remove only the left side ring terminals in control box. Do not lose the two jumper wires.





Figure 8, Left Side Ring Terminal Disconnect

8. Cut cable ties on alternator output leads.







Figure 10, Unplug fast-on connectors

10. Disconnect brush block connectors.









Figure 12, Chassis Ground

12. Remove Control box.







14. Push coolant temp sensor through control grommet.




Warning: Confirm unit is still disabled to ensure fan does not accidentally spin

15. Remove fan shroud and fan mounting bolts. Fan and shroud come off together





17. Use puller to remove fan



before removing

18. Remove hydraulic hose.




Figure 19, Remove Hose


19. Remove hose coupler connection on hydraulic pump.





Figure 21, Remove Pump

21. Remove the 4 alternator mounting bolts.



Warning: Alternator weighs over 75 lbs. Use caution when lifting.

Warning: Do not use the lifting eye cable to lift the unit. Use an alternate lift method


22. Lift with rated lifting strap and remove alternator from base pan. Do not use lifting eye cable.



23. Remove bolt and grommet bracket.




24. Remove brush blocks.




20. The allocation up and out on pump one with online pointing

26. Remove 4 bolts holding on alternator end.



28. Slide off old cable.



1. Install new cable



Figure 29, Install New Cable

2. Feed wires through alternator end and line up bolt holes.



3. Install 4 mounting bolts with washers to alternator.

4. Make sure all vibration isolators are installed and oriented correctly.



- 5. Tilt alternator and set on 4 mounting isolators.
- 6. Reinstall wire grommet bracket. Make sure it is seated completely and flush.




Figure 32, Seated and Flush

7. Reinstall 2 pump bolts by hand first. Then torque to 58 Nm.







Figure 34, Test Fit Fan for Interference

9. Reinstall brush blocks, ensure bolt C clip is installed.



10. Reinstall hose coupler to pump. Torque to 97 Nm.




Figure 36, Hose Coupler Installation


Warning: Alternator weighs over 34 kg (75 lbs). Use caution when

11. Lift alternator and reinstall alternator in base pan, torque bolts to 46 Nm.



Figure 37, Lift and Install Alternator

12. Reinstall hose, torque hose fittings to 97 Nm,






https://quickserve.cummins.com/qs3/pubsys2/xml/en/tsb/2021/tsb210146.html

14. Reinstall fan and shroud.




- 15. Push side panel over pump inlet. Do not install panel bolts yet (see step 20).
- 16. Reinstall coolant temperature sensor through control grommet and connect pump connector.
- 17. Reinstall control



18. Push generator output wire leads through side panel.



19. Feed the 7 wire connectors through the side panel. Install wire holder and twist up into opening.




20. Install side panel bolts.




Figure 44, Side Cover Installation

21. Install wire jumpers to bottom terminal.



22. Install chassis ground connections (green jumper, silver strap and white with blue ring terminal).



- 23. Install brush blocks (Wire F1 on the left, Wire F2 on the right).
- 24. Connect two blue fast-on connectors.
- 25. Run J1 through top current transformer loop.






Figure 47, J1 Through Top CT

26. Run J4 through bottom current transformer loop.



Safety Campaign #4495 RBAB Lift Cable Crimp Issue

- 28. Take wires T3, T2, and jumper wire TB1-2 TB1-4 and install to third from bottom terminal.
- 29. Take orange wire and T1 and install in top terminal



30. Push wires inside base pan and install 3 cable ties.



6 Cummer of the second se

32. Reinstall side panel and grate.

33. Reinstall top two enclosure panels.

34. Reinstall front enclosure panel.

Service Instructions

Campaign Filing Instructions:

Fail Code: JSLIML

Account Code: 65

Authorization Code: 4495

Applicable SRT's:

00-901: 0.7 hours- Administrative time (shop)

99-999: 1.0 hours Inspect cable ferrules

25-3AG: 5.1 hours cable replacement

Parts: Email: cpgf.customer.quality@cummins.com to order a replacement cable. In the email please provide the **model and serial number** of the unit being repaired, and the attention and **address** of where to ship the cable.

Travel: If travel to customer site is necessary, travel allowed else follow in-shop repair procedures and claims filing.

Expiration Date: None

Document History

Date	Details	
2021-7-8	Module Created	
2021-9-10	Non-Product Problem Solving (PPS)	
2021-9-13	Non-Product Problem Solving (PPS)	

Last Modified: 13-Sep-2021