

VOLUNTARY RECALL CAMPAIGN

 Classification:
 Reference:
 Date:

 RS22-001A
 ITB22-005A
 July 26, 2023

VOLUNTARY SAFETY RECALL CAMPAIGN 2003 FX35/45; FRONT PASSENGER AIRBAG MODULE

This bulletin has been amended. See AMENDMENT HISTORY on the last page.

Please discard previous versions of this bulletin.

CAMPAIGN ID #: R21C1

APPLIED VEHICLES: 2003 FX35/45 (S50)

Check Service COMM or Dealer Business Systems (DBS) National Service History to confirm campaign eligibility.

INTRODUCTION

Infiniti is conducting this voluntary safety recall campaign, on certain specific model year 2003 FX35/45 vehicles, to replace the passenger (RH) side front airbag module. This service will be performed at no charge to the client for parts or labor.

TK Services and RXO Logistics have issued return packaging, shipping labels, documents, and directions that must be used and followed in order to properly carry out this campaign. Information on this documentation is provided in this bulletin.


IDENTIFICATION NUMBER

Infiniti has assigned identification number R21C1 to this campaign. This number must appear on all communication and documentation of any nature dealing with this campaign.

RETAILER RESPONSIBILITY

It is the retailer's responsibility to check Service COMM or Dealer Business Systems (DBS) National Service History for the campaign status on each vehicle falling within the range of this voluntary safety recall which for any reason enters the service department. This includes vehicles purchased from private parties or presented by transient (tourist) owners and vehicles in a retailer's inventory. Federal law requires that new vehicles in retailer inventory which are the subject of a safety recall must be corrected prior to sale. Failure to do so can result in civil penalties by the National Highway Traffic Safety Administration. While federal law applies only to new vehicles, Infiniti strongly encourages retailers to correct any used vehicles in their inventory before they are retailed.

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti retailer to determine if this applies to your vehicle.



REQUIRED SPECIAL TOOL J-52352 (new part number NI-52352)

Quick Scan Tool

- One Quick Scan Tool J-52352 (new tool number NI-52352) has been previously shipped to each retailer (Figure 1).
- Additional Quick Scan Tools may be purchased from Tech•Mate: www.TechMateTools.com or 1-833-397-3493.



Figure 1

SERVICE PROCEDURE

IMPORTANT: Follow all cautions, warnings, and notices in the Electronic Service Manual (ESM) when working on or near a Supplemental Restraint System (SRS), such as an airbag.

NOTICE

To avoid damage to the interior trim, handle interior trim carefully and with clean hands. If not handled carefully with clean hands, damage and/or stains to these parts may occur. Use protective covers as needed.

1. Turn the ignition ON and write down the radio settings.

Presets	1		2		3	4	5	6
AM								
FM 1								
FM 2								
SAT 1								
SAT 2								
Bass Treble			В	alance	Fade	Speed S Vol.	Sen.	

- 2. Write down any other client settings that will be lost when the battery is disconnected.
- 3. Turn the ignition OFF.
- 4. Disconnect both battery cables, negative cable first.
- 5. Wait at least 3 minutes before continuing to step 6.
- 6. Remove the new passenger airbag module from its packing and register the module's serial number as outlined in steps 7 12 on pages 5 7.

4/18

ITB22-005A

7. Attach the Quick Scan Tool (J-52352 or NI-52352) to a CONSULT PC's USB port.




Figure 2

8. Open ASIST, select **TECH SUPPORT INFO**, and then **Inventory Vehicle Actions**.




Figure 3

9. Select CLICK HERE... next to Airbag to VIN Registration.




Figure 4

 Using the Quick Scan Tool (J-52352), scan the bar code (VIN) located on the driver (LH) side B-pillar label.

HINT:

- o Make sure the VIN label is clean.
- o Hold tool J-52352 about six (6) inches away from the VIN label.
- Hold down the trigger until tool
 J-52352 is finished scanning the VIN label.
- o Some VIN labels may not scan quickly.
- o The VIN will populate automatically. See Figure 8 on page 7.
- o If needed, the VIN can be entered manually.



 The airbag module serial number will populate automatically below the VIN.
 See Figure 8 on page 7.



Figure 5



Figure 6

• If needed, the airbag module serial number can be entered manually.

HINT: Do not enter the asterisks when entering the airbag module serial number manually.




Figure 7

12. Once the VIN and Airbag Serial Number fields are populated, select Submit.




Figure 8

- 13. Replace the airbag module with the new one that has been scanned.
 - For the airbag module replacement procedure, refer to ASIST.

Select:

- a. **FX**
- b. The correct model year
- c. The Service Manual tab, and then
- d. Serv. Man. Amendment (Figure 9)



Figure 9

7/18

ITB22-005A

• On the next screen, select 2003-2008 FX; Revised Front Passenger Air Bag Module Service Procedure, and then select the view button.

HINT: In addition to the amended service manual procedure, steps 14 - 21 on pages 9 - 12 describe how to access the airbag module's center fixing nut.




Figure 10

14. Remove the two (2) screws from the LH side of the blower case and one (1) bolt from the RH side of the blower case (Figure 11).

HINT: The top LH blower case screw is not visible in Figure 11.




Figure 11

- 15. Disconnect the blower motor wire harness connector and disengage the blower motor wire harness from the retainer (Figure 12).
- 16. Disengage the intake door motor wire harness from the retainer.




Figure 12

- 17. To release the case, push the blower case toward the passenger (RH) side of the vehicle, and then pull downward on the driver (LH) side of the blower case.
- 18. Slightly rotate the bottom of the blower case and pull toward you, and then lower the blower case to the front passenger floor.




Figure 13

19. Disconnect the intake door motor wire harness connector, and then remove the blower case from the vehicle (Figure 14).




Figure 14

- 20. Remove the upper center fixing nut from the airbag module support bracket (Figure 15, shown with instrument panel removed).
 - The fixing nut will <u>not</u> be reused.




Figure 15

- 21. Install the new front passenger airbag module (Figure 16, Figure 17, and Figure 18).
 - a. Using the three (3) <u>new</u> fixing nuts supplied with the replacement airbag module, secure the front passenger airbag module mounting brackets to the supports on the back of the instrument panel.
 - Fixing nut torque: 6.0 N•m (0.61 kg-m, 53.5 in-lb)

HINT: One of the side fixing nuts is hidden (Figure 16).




Figure 16

HINT: Figure 17 and Figure 18 show the center fixing nut's general location when viewed with the case removed, and while lying on the front passenger floor with your head under the instrument panel and looking up.

- b. Install the center fixing bolt (Figure 17).
 - o Center fixing bolt torque: 24.5 N·m (2.5 kg-m, 18 ft-lb)




Figure 17




Figure 18

- 22. Reassemble all removed components in reverse order. Refer to the ESM, section **SRS-Supplemental Restraint System**, for installation information.
- 23. Reconnect both battery cables, positive cable first.
- 24. Turn the ignition ON and reset/reinitialize systems as needed.
- 25. Turn the ignition OFF and then ON and observe the airbag warning light.
 - The airbag warning light should illuminate for 7 seconds and then go out.
 - **HINT:** If the airbag warning light does not operate as described above there may be an issue not covered by this campaign. Refer to ASIST and the ESM for additional diagnostic and repair information.
- 26. Return the removed (old / non-deployed) module in the box that the new module arrived in.
 - TK Services and RXO Logistics have provided return instructions for the recalled Takata inflators and modules at pages 14-17 of this bulletin.
 - Reminder: Federal Hazardous Material Regulations (HMR) govern preparation of shipments of hazardous materials and prohibit handling and preparation for shipment by any person who is not trained and certified as required by the HMR. The HMR impose specific requirements for retailers, packaging, labeling and pre-transportation functions. Violations can result in civil penalties by the Pipeline and Hazardous Materials Safety Administration. (Title 49 Code of Federal Regulations Subchapter C)

Hazardous Materials Training/Certification Responsibility

In accordance with Title 49, Code of Federal Regulations (49 CFR), Sections 172 Subpart H and 173.1(b), it is the responsibility of the dealer to ensure that every employee handling and preparing hazardous materials for shipment is properly trained/certified. Initial and recurring training can be completed by contacting one of the training companies listed below, or any other company that offers hazardous material training/certification.

SHIPMATE, INC.

Hazardous Materials Training & Consulting 780 Buckaroo Trail, Suite D Sisters, OR 97759 Website: www.shipmate.com, Tel: 310.370.3600, Fax: 310.370.5700

DGI Training Center

West Seminar Registrations and On-Site Information 1060 El Camino Real, Suite B Redwood City, CA 94063-1645 Website: www.dgitraining.com, Tel: 650.306.8450 or

800.338.2291

Lion Technology

570 Lafayette Rd. Sparta, NJ 07871-3447 Email: info@lion.com, Tel: 888.546.6511,

Fax: 973.579.6818

TAKATA AIRBAG RECALL RETURN INSTRUCTIONS

IMPORTANT: Must be performed by certified DOT HAZMAT personnel.

Inflator

Takata


Inflator and Module Returns Shipping Instructions

06/20/2023

Airbag Recall

Please contact scfieldaction.14305@rxo.com for documentation and to arrange pickup If retailers do not receive a response from an RXO logistics specialists within 48 to 72 hours, then they

can utilize the escalation number, (210) 317-6436 for further assistance.



5. Shipping Instructions - Prepare the Pallet

- a) Accumulate and palletize Kits
- b) Arrange Kits on Pallet as pictured here
 - 20 boxes per row/layer (5x4)
 - 10 rows/layers per pallet (200 boxes)
- c) Shrink-wrap Kits to Pallet
- d) Affix Over-pack Label and Pallet Label on (1) side of Pallet (Not on Top)
- e) If 200 boxes are not accumulated every 2 weeks, please proceed to step 6.

Note: If you receive non-uniform sized kits (Older version), Please contact RXO via the Instructions in Box 6 for additional Instructions



2. Packing Instructions

DO NOT DEPLOY THE INFLATOR

a) Confirm box is in acceptable condition. Box should be in good condition with no visible signs of damage and should be capable of withstanding additional transportation.

- b) If a new box is needed, follow the New Box instructions located in section #8 of this page.
- C) Place the un-deployed air bag inflator or module in the "cradle" of the box insert.

6. Shipping Instructions - Schedule Pickup

- a) Upon Accumulating 200 kits (1 Over-pack/Pallet) Minimum
- Contact RXO at the e-mail noted above If 200 Kits have not been accumulated every 2 weeks, please contact RXO for direction.
- Complete shipping template and attach to E-Mail.
- Have the following Information Available
- Dealer #
- Quantity of Over-packs/Pallets
- Quantity of Driver Kits and Quantity of Passenger Kits on each Pallet
- Email Address where shipping Documentation can be received
- Lift gate Service Needed?

3. Closure Instructions

a) Close the top box flap, per box closure instructions located on front panel of box using a 2" wide by 4" long piece of tape to securely Close the box.





Module

7. Shipping Instructions - Ship

a) Give 1 Copy of BOL and 1 Copy of ERG to Driver

8. Requesting a New Box / Shipping Labels

b) Retain 1 Copy of BOL for Dealership records and archive for at least 2 Years

Primary Contact:

If a new box or replacement box shipping labels are needed, please contact a representative by email to request replacement materials.

E-Mail: scfieldaction.14305@rxo.com

To help expedite your request, please be prepared to an information:

a) Serial number on the original box


(if replacement box is needed)

b) What Type of shipping material needed

- Replacement Box
- Two Part Return Label
- Bill of Lading
- **ERG Form**

c) Dealer Shipping Information

- Contact Name
- Dealer Address
- Phone Number



NOTE: International and ALL Locations outside of the Continental United States (APAC, EMEA, Mexico, Hawaii, Alaska, Puerto Rico, and US Virgin Islands dealers) CANNOT follow above shipping instructions. Instead, dealerships in these locations MUST contact TK services /RXO USA representative directly for shipping instructions: RXO Representative .Email: scfieldaction.14305@rxo.com Continental US 48 State Dealerships, please follow steps 1-8 above.

PALLET (S) MUST BE READY BEFORE SENDING IN THE TEMPLATE. ALL FIELDS							
PERTAINING TO YOUR LOAD MUST BE FILLED IN AND SENT TO							
SCFIE	SCFIELDACTION.14305@RXO.COM.						
ESCALATIO	N PHON	NE NUN	BER:	210-317	-6436		
TEMPLATE MUST					CONTRACTOR CONTRACTOR		
Dealer Code							
and the second second							
Dealer Name							
Pickup Address							
City, State & Zip							
YOUR Name & Phone#(DO NOT GIVE							
YOUR CELL #)	_						
Hours available for pickup							
Email Address for BOL							
Do you need a truck with lift gate and pallet jack (YES or NO)							
SPECIAL EQPT NEEDS OR SPECIFIC CARRIER REQUEST							
	Pallet	Pallet	Pallet	Pallet	Pallet		
	#1	#2	#3	#4	#5		
Driver Side Count							
Passenger Side Count							
TOTAL	0	0	0	0	0		
	Pallet	Pallet	Pallet	Pallet	Pallet		
	#6	#7	#8	#9	#10		
Driver Side Count							
Passenger Side Count							
TOTAL	0	0	0	0	0		
	Pallet	Pallet	Pallet	total			
	#11	#12	#13	boxes			
Driver Side Count				0			
Passenger Side Count				0			
TOTAL	0	0	0	0			
TRUCK LOAD IS 14 +	LISE	THIS SI	CTION	FOR 1	4 PALLETS OR MORE		
PALLETS	USE	11113 31	-01101		T ALLE IS ON WORL		
TOTAL PALLET COUNT							
TOTAL DRIVER COUNT							
TOTAL PASSENGER COUNT							
TOTAL WEIGHT							

PALLET (S) MUST BE READY BEFORE SENDING IN THE TEMPLATE. ALL FIELDS PERTAINING TO YOUR LOAD MUST BE FILLED IN AND SENT TO SCFIELDACTION.14305@RXO.COM ESCALATION PHONE NUMBER 210-317-6436 MIGUEL PRIGAADA

Dealer (Code				De	aler or Bu	usiness Na	ame							
Pickup	Address								City, Stat	e & Zip 🗌					
Physica	l Address	s (if differe	ent from p	ickup addn	ess)					Cit	y, State &	Zip			
YOUR Na	ame & Pho	ne#						- 5	Hours Av	allable for	Pickup [
									Days/hou (lunch ho	ırs pickup ur if shut	is not allo down)	wed			
Email ad	dress for E	BOL						j		eed a truc pallet jack		YES	; <u> </u>	NO]
Where co	an the driv property?	er expect Please giv	to find ve clear di	rections						nstruction driver loca					
	Pallet #1	Pallet #2	Pallet #3	Pallet #4	Pallet #5	Pallet #6	Pallet #7	Pallet #8	Pallet #9	Pallet #10	Pallet #11	Pallet#12	Pallet#13	Pallet#14	Total Boxes
Driver Side Count															
assenger Side Count															
Total	0	0	0	0	0	0	0	0	0	0.	0	0	0	0	0

PARTS INFORMATION

DESCRIPTION	PART NUMBER	QUANTITY	
MODULE ASSY – AIRBAG, ASSIST KIT	K851E-CG88D	1	

CLAIMS INFORMATION

Submit a "CM" line claim using the following claims coding:

CAMPAIGN ("CM") ID	DESCRIPTION	OP CODE	FRT
R21C1	Remove and Replace Front Passenger Airbag Module Assembly	R21C10	1.0

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
February 7, 2022	ITB22-005	Original bulletin published
July 26, 2023	ITB22-005A	Pages 13 and 15 updated and pages 14, 16 and 17 added. "NOTE" changed to "HINT". Other changes made throughout.