

VOLUNTARY SAFETY RECALL CAMPAIGN 2022 PATHFINDER; DRIVER SIDE 2ND ROW CAPTAIN'S CHAIR SEAT FRAME INSPECTION

CAMPAIGN ID #: PC845 APPLIED VEHICLES: 2022 Pathfinder (R53)

> Check Service COMM or Dealer Business Systems (DBS) National Service History to confirm campaign eligibility.

NOTE: This bulletin only applies to the driver (LH) side 2nd row captain's chair seat assembly.

INTRODUCTION

Nissan is conducting this voluntary safety recall campaign, on certain specific model year 2022 Pathfinder vehicles, to inspect and, if necessary, replace the driver (LH) side 2nd row captain's chair seat assembly. This service will be performed at no charge to the customer for parts or labor.

IDENTIFICATION NUMBER

Nissan has assigned identification number PC845 to this campaign. This number must appear on all communication and documentation of any nature dealing with this campaign.

DEALER RESPONSIBILITY

It is the dealer's responsibility to check Service COMM or Dealer Business Systems (DBS) National Service History for the campaign status on each vehicle falling within the range of this voluntary safety recall which for any reason enters the service department. This includes vehicles purchased from private parties or presented by transient (tourist) owners and vehicles in a dealer's inventory. Federal law requires that new vehicles in dealer inventory which are the subject of a safety recall must be corrected prior to sale. Failure to do so can result in civil penalties by the National Highway Traffic Safety Administration. While federal law applies only to new vehicles, Nissan strongly encourages dealers to correct any used vehicles in their inventory before they are retailed.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

REQUIRED SPECIAL TOOL

Each dealer has been shipped one Quick Scan Tool, special tool J-52352.

Additional tools are available from Tech•Mate online: www.nissantechmate.com, or by phone: 1-800-662-2001.



Figure 1

SERVICE PROCEDURE

Seat Frame Weld Inspection

- 1. Open the LH rear door and fold the 2nd row seat forward to the flat position.
- 2. Slide the LH 2nd row seat fully forward.
- 3. Using a finesse stick, disengage the lower seatback cover retainer, as shown in Figure 2.
 - a. Starting on the outboard side, carefully separate the lower seatback cover retainer.
 - b. Fold the lower portion of the seatback cover downward.

ACAUTION

To avoid the risk of minor personal injury or property damage, use the recommended tool while performing this procedure, as there is a sharp edge under the lower seatback cover.



Figure 2

4. Lift the lower portion of the seatback cover out from the seatback frame slot, as shown in Figure 3.



Figure 3

5. Carefully disengage the hook and loop fasteners and the seatback cover retainer on the outboard portion of the seatback, as shown in Figure 4.




Figure 4

6. Using a forked finesse stick, remove the three (3) retainer clips shown in Figure 5.




Figure 5

7. Separate the seatback cover material and position it, as shown in Figure 6.



Figure 6

8. Using a suitable light source, look in the area shown in Figure 7 to locate the weld to be inspected.




Figure 7

- 9. Inspect and compare the weld to the No Good (NG) examples (Figures 8 13 on page 6) and the OK examples (Figures 14 16 on page 7).
 - If the weld is found to be OK, reassemble the seatback in the reverse order of disassembly, and then skip to the **CLAIMS INFORMATION** on the last page.
 - If the weld is NG, proceed to step 10 on page 8 to determine the correct captain's chair seat assembly part number for ordering.

NOTE:

- o The weld should evenly cover both parts of the joint.
- The weld should run the entire length of the joint.
- The weld should run parallel to the joint.
- The weld should <u>not</u> have any cracks or separations between the two parts.

No Good (NG) Conditions




Figure 8

Figure 9

Figure 10




Figure 11

Figure 12

Figure 13

OK Conditions



Figure 14



Figure 15



Figure 16

Order the Seat Assembly Replacement

IMPORTANT: Before starting, make sure:

- ASIST on the CONSULT PC has been synchronized (updated) to the current date.
- All C-III plus software updates (if any) have been installed.
- 10. Connect the quick scan tool (J-52352) to a CONSULT PC USB port.






Figure 17

11. Open ASIST.



12. Select Tech Support Info, and then select Bulletin Support Items.

13. Select CLICK HERE... next to PC845, PC846, PC847 2022 Pathfinder 2nd Row Seat Part Number Look up.





14. Enter the **Dealer Code**.

Dealer Code	XXXX	
VIN		
Note: VIN can be scann	ned or entered manually	



15. Using the quick scan tool (J-52352), scan the bar code on the VIN Certification Label located at the base of the B-Pillar.

NOTE:

- Make sure the VIN Certification Label is clean.
- Hold the quick scan tool (J-52352) about 6 inches away from the label.
- Hold the trigger down until the quick scan tool (J-52352) is finished scanning the label, an audible 'beep' sound will be heard.
- Some VIN Certification Labels may not scan quickly.
- Once the VIN automatically populates in the form, verify all 17 digits are correct (Figure 22).
- If needed, the VIN can be entered manually.



Figure 21

Dealer Code	XXXX	
VIN	XXXXXXXXXXXXXXXXX	
Note: VIN can be scam	and or entered manually	

Figure 22

16. Select **Submit** on the ASIST screen.




Figure 23

17. The part number for the 2nd row seat assembly will be provided along with a **Confirmation code**.




Figure 24

- 18. Place an order in DBS for <u>only</u> the part that is needed.
 - When placing an order in DBS, enter the **Confirmation code** into the comments section.
 - **IMPORTANT:** If the **Confirmation code** is not provided when the order is placed, the order will be canceled.

Side Airbag Module Registration

- **NOTE:** A new Side Airbag Module is part of the replacement seat assembly and the replacement Side Airbag Module must be registered before the replacement seat assembly is installed.
- 19. Open ASIST.
- 20. Select Tech Support Info, and then select Inventory Vehicle Actions.

NISSAN AS	AUTOMOTIVE SE	RVICE INFORMATION SUPPORT TERMINAL English (US)-LAN Edition Windows 10 Enterprise Version 15.3.4
	VIN: Retrieve VIN Clear Model:	V Year:
TECH LINE DB Search	What's New Service Manual DTC Codes Symptom Diag. Service	History Campaigns Quality Action Acc. In
Latest TSBs		
TSB Search	Keyword Search:	Tips to Improve
CONSULT-II 😵	* Red indicates TSBs & Campaigns amended within last 30 days. * New flashing icon indicates newly received TSBs & Campaigns wi	Panasonic
NATS & Keycode 🛛 😵		CF-19 Performance
Specialty Tools TECH LINE Support Tech Support Info Bulletin Support Items	Tech Support Info	
Harness Repair Inventory Vehicle Actions Inventory Vehicle Actions NuRnet2.0 Power truth Gal Center Assistance Request Forms Symptom Surveys & VRP IEGCI FALK/RTRA TALK TIPS VCAT Warranty Call Center pre-Call Forms	Inventory Vehicle Action	S Click here or go to www.ASISTRA.com for additional information
Tech-Mate 😵		~

Figure 25

21. Select CLICK HERE... next to Airbag to VIN Registration.

NNA Nissan Dealer Inventory Action		
Inventory Inspections - Nissan		
Airbag to VIN Registration CLICK HERE		
PM691 - Sentra (B17) Airbag Inflator Scan Tool CLICK HERE		
PC592 - Rogue (T32) Second Row Seat Scan Tool CLICK HERE		

Figure 26

22. Using the quick scan tool (J-52352), scan the bar code on the VIN Certification Label located at the base of the B-Pillar.

NOTE:

- Make sure the VIN Certification Label is clean.
- Hold the quick scan tool (J-52352) about 6 inches away from the label.
- Hold the trigger down until the quick scan tool (J-52352) is finished scanning the label, an audible 'beep' sound will be heard.
- Some VIN Certification Labels may not scan quickly.
- Once the VIN automatically populates in the form, verify all 17 digits are correct (Figure 28).
- If needed, the VIN can be entered manually.



Figure 27


Airb	oag to VIN Registration	
9/8/20	21 11:03:15 AM (Mountain Standard Time)	
Please enter/scan	the VIN and Airbag Inflator Serial Number	
Dealer Code		
Key Number		
VIN	XXXXXXXXXXXXXXXXXXXX	
Airbag Serial Number		Submit

Figure 28

23. Using the quick scan tool (J-52352), scan the QR code (serial number) on the new Airbag Module.

NOTE:


- Make sure the QR code label is clean.
- Hold the quick scan tool (J-52352) about 6 inches away from the QR code.
- Hold the trigger down until the quick scan tool (J-52352) is finished scanning the QR code, an audible 'beep' sound will be heard.
- Once the serial number automatically populates in the form, verify all the digits are correct (Figure 31).
- If needed, the serial number can be entered manually.







24. Select **Submit** on the ASIST screen.



LH Captain's Chair Seat Assembly Replacement

- 25. Replace the LH 2nd row captain's chair seat assembly.
 - Refer to the ESM: BODY INTERIOR > SEAT > REMOVAL AND INSTALLATION
 > SECOND ROW SEATS > Removal and Installation

PARTS INFORMATION

DESCRIPTION	PART NUMBER	QUANTITY
SEAT ASSY – 2 nd ROW, LH	88050 – (1)	1
(Captain's Chair Seat Assembly)	00000 - (1)	(If Needed)

(1) Refer to steps 10 - 18 on pages 8 - 11 to order the correct part number.

CLAIMS INFORMATION

Submit a "CM" line claim using the following claims coding:

CAMPAIGN ("CM") ID	DESCRIPTION	OP CODE	FRT
Dools	OK Condition Inspect LH 2 nd Row Captain's Chair Seat Assembly	PC8450	0.2
PC845	<u>NG Condition</u> Inspect and Replace LH 2 nd Row Captain's Chair Seat Assembly	PC8451	0.7

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
September 23, 2021	NTB21-089	Original bulletin published