Technical Bulletin



RECALL CAMPAIGN BULLETIN

Classification: Reference: Date:

BT21-019 NTB21-090 September 23, 2021

VOLUNTARY SAFETY RECALL CAMPAIGN 2022 PATHFINDER; DRIVER SIDE 2ND ROW BENCH SEAT FRAME INSPECTION

CAMPAIGN ID #: PC846

APPLIED VEHICLES: 2022 Pathfinder (R53)

Check Service COMM or Dealer Business Systems (DBS) National Service History to confirm campaign eligibility.

NOTE: This bulletin only applies to the driver (LH) side 2nd row bench seat assembly (60%).

INTRODUCTION

Nissan is conducting this voluntary safety recall campaign, on certain specific model year 2022 Pathfinder vehicles, to inspect and, if necessary, replace the driver (LH) side 2nd row bench seat. This service will be performed at no charge to the customer for parts or labor.

IDENTIFICATION NUMBER

Nissan has assigned identification number PC846 to this campaign. This number must appear on all communication and documentation of any nature dealing with this campaign.

DEALER RESPONSIBILITY

It is the dealer's responsibility to check Service COMM or Dealer Business Systems (DBS) National Service History for the campaign status on each vehicle falling within the range of this voluntary safety recall which for any reason enters the service department. This includes vehicles purchased from private parties or presented by transient (tourist) owners and vehicles in a dealer's inventory. Federal law requires that new vehicles in dealer inventory which are the subject of a safety recall must be corrected prior to sale. Failure to do so can result in civil penalties by the National Highway Traffic Safety Administration. While federal law applies only to new vehicles, Nissan strongly encourages dealers to correct any used vehicles in their inventory before they are retailed.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

REQUIRED SPECIAL TOOL

Each dealer has been shipped one Quick Scan Tool, special tool J-52352.

Additional tools are available from Tech•Mate online: www.nissantechmate.com, or by phone: 1-800-662-2001.



Figure 1

SERVICE PROCEDURE

Seat Frame Weld Inspection

- 1. Open the LH rear door.
- 2. Locate the seat inspection area, as shown in Figure 2.




Figure 2

3. In the inspection area, push the seat cushion inward, as shown in Figure 3, to reveal the weld to be inspected (Figure 4).






Figure 3 Figure 4

4. Using a light source, locate the weld by looking between the seat trim and the depressed seat cushion.





Figure 5

- 5. Inspect the weld for a burn-through condition (a visible hole in the weld).
 - If the weld has a burn-through condition (Figure 6), continue to step 6 on page 5 to determine the correct bench seat assembly part number for ordering.
 - If the weld does <u>not</u> have a burn-through condition (Figure 7), skip to CLAIMS INFORMATION on the last page.



4/12

NTB21-090

Order the Seat Assembly Replacement

IMPORTANT: Before starting, make sure:

- ASIST on the CONSULT PC has been synchronized (updated) to the current date.
- All C-III plus software updates (if any) have been installed.
- 6. Connect the quick scan tool (J-52352) to a CONSULT PC USB port.



Figure 8

- 7. Open ASIST.
- 8. Select **Tech Support Info**, and then select **Bulletin Support Items.**




Figure 9

9. Select CLICK HERE... next to PC845, PC846, PC847 2022 Pathfinder 2nd Row Seat Part Number Look up.



Figure 10

10. Enter the **Dealer Code**.




Figure 11

11. Using the quick scan tool (J-52352), scan the bar code on the VIN Certification Label located at the base of the B-Pillar.

NOTE:

- Make sure the VIN Certification Label is clean.
- Hold the quick scan tool (J-52352) about 6 inches away from the label.
- Hold the trigger down until the quick scan tool (J-52352) is finished scanning the label, an audible 'beep' sound will be heard.
- Some VIN Certification Labels may not scan quickly.
- Once the VIN automatically populates in the form, verify all 17 digits are correct (Figure 13).
- If needed, the VIN can be entered manually.



Figure 12




Figure 13

12. Select **Submit** on the ASIST screen.




Figure 14

13. The part number for the 2nd row seat assembly will be provided along with a **Confirmation code**.




Figure 15

- 14. Place an order in DBS for only the part that is needed.
 - When placing an order in DBS, enter the Confirmation code into the comments section.

IMPORTANT: If the **Confirmation code** is not provided when the order is placed, the order will be canceled.

Side Airbag Module Registration

NOTE: A new Side Airbag Module is part of the replacement seat assembly and the replacement Side Airbag Module must be registered before the replacement seat assembly is installed.

- 15. Open ASIST.
- Select Tech Support Info, and then select Inventory Vehicle Actions.




Figure 16

17. Select CLICK HERE... next to Airbag to VIN Registration.



Figure 17

 Using the quick scan tool (J-52352), scan the bar code on the VIN Certification Label located at the base of the B-Pillar.

NOTE:

- Make sure the VIN Certification Label is clean.
- Hold the quick scan tool (J-52352) about 6 inches away from the label.
- Hold the trigger down until the quick scan tool (J-52352) is finished scanning the label, an audible 'beep' sound will be heard.
- Some VIN Certification Labels may not scan quickly.
- Once the VIN automatically populates in the form, verify all 17 digits are correct (Figure 19).
- If needed, the VIN can be entered manually.



Figure 18




Figure 19

19. Using the quick scan tool (J-52352), scan the QR code (serial number) on the new Airbag Module.

NOTE:

- Make sure the QR code label is clean.
- Hold the quick scan tool (J-52352) about 6 inches away from the QR code.
- Hold the trigger down until the quick scan tool (J-52352) is finished scanning the QR code, an audible 'beep' sound will be heard.
- Once the serial number automatically populates in the form, verify all the digits are correct (Figure 22).
- If needed, the serial number can be entered manually.




Figure 20 Figure 21

20. Select **Submit** on the ASIST screen.



Figure 22

LH Bench Seat Assembly Replacement

- 21. Replace the LH bench seat assembly (60%).
 - Refer to the ESM: BODY INTERIOR > SEAT > REMOVAL AND INSTALLATION
 > SECOND ROW SEATS > Removal and Installation

PARTS INFORMATION

DESCRIPTION	PART NUMBER	QUANTITY
SEAT ASSY – 2 nd ROW, LH	88050 – (1)	1
(Bench Seat Assembly, 60%)	00030 – (1)	(If Needed)

⁽¹⁾ Refer to steps 6 - 14 on pages 5 - 8 to order the correct part number.

CLAIMS INFORMATION

Submit a "CM" line claim using the following claims coding:

CAMPAIGN ("CM") ID	DESCRIPTION	OP CODE	FRT
PC846	OK Condition Inspect LH 2 nd Row Bench Seat Assembly (60%)	PC8460	0.2
	NG Condition Inspect and Replace LH 2 nd Row Bench Seat Assembly (60%)	PC8461	0.6

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
September 23, 2021	NTB21-090	Original bulletin published