

IMPORTANT SAFETY RECALL

NHTSA Recall Number: 21V844 This notice applies to your vehicle: Insert VIN

RENOTIFICATION

OCTOBER 23, 2024

THIS IS A RENOTIFICATION OF AN EARLIER COMMUNICATION ISSUED ON NOVEMBER 29, 2021, WHICH NOTIFIED ALL OWNERS OF THE AFFECTED 2017-2018 MY KIA OPTIMA HEV AND OPTIMA PHEV VEHICLES OF A SAFETY RECALL. OUR RECORDS INDICATE THAT YOU ARE THE CURRENT REGISTERED OWNER OF THIS VEHICLE AND THAT THIS RECALL HAS NOT BEEN COMPLETED.

KIA IS REQUESTING THAT YOU CONTACT AN AUTHORIZED KIA DEALERSHIP IMMEDIATELY TO SCHEDULE AN APPOINTMENT TO INSPECT, TEST, AND IF NECESSARY, REPLACE YOUR ENGINE. IN ADDITION, DEALERS WILL ALSO PERFORM A KNOCK SENSOR DETECTION SYSTEM (KSDS) SOFTWARE UPDATE TO THE ENGINE CONTROL UNIT (ECU) IN YOUR VEHICLE TO PREVENT ENGINE DAMAGE DUE TO POTENTIAL EXCESSIVE CONNECTING ROD BEARING WEAR. THIS RECALL WILL BE PERFORMED FREE OF CHARGE AT NO COST TO YOU.

IF YOU HAVE ALREADY TAKEN YOUR VEHICLE TO A KIA DEALER AND HAD THIS SAFETY RECALL PERFORMED, PLEASE DISREGARD THIS NOTICE.

IMPORTANT SAFETY RECALL

(NHTSA Recall Number: 21V844) This notice applies to your vehicle: (Insert VIN)

November 29, 2021

Dear Kia Optima Hybrid ("HEV") and Plug-In Hybrid ("PHEV") Owner:

Kia has identified a defect in your vehicle which relates to motor vehicle safety.

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Kia America, Inc. has decided that a defect which relates to motor vehicle safety exists in 2017-2018 MY Kia Optima HEV and 2017-2018 MY Kia Optima PHEV vehicles. Engine damage can increase the risk of an engine stall and/or a fire. A vehicle stall increases the risk of a crash, and a fire increases the risk of injury. Our records indicate that you own or lease one of the potentially affected vehicles.

What Is The Problem?

The connecting rod bearing can become damaged for different reasons. If the connecting rod bearing becomes damaged,

abnormal knocking noise from the engine and/or illumination of the oil pressure warning light and can occur. If the vehicle continues to be driven in this condition, severe engine damage can occur, thereby increasing the risk of an engine stall and/or a fire due to a connecting rod puncturing the engine block allowing engine oil to leak onto a hot exhaust. Kia is conducting this recall to mitigate any unreasonable risk due to engine damage.

Kia Will Test And, If Necessary, Replace The Engine, And Will Install The KSDS Software At No Cost To You.

In an effort to mitigate the potential fire risk, Kia will perform an engine test to determine the existence of any connecting rod bearing damage and, if necessary, replace the engine at no cost to you. The estimated time required for the engine test is approximately 1 to 2 hours. However, your vehicle may be needed longer depending on the result of the test. If an engine replacement is necessary, the estimated time required is eight (8) hours or more. We recommend scheduling a service appointment to minimize your inconvenience.

In addition, Kia will install a Knock Sensor Detection System (KSDS) software that will prevent engine damage from potential excessive connecting rod bearing damage at no cost to you. The estimated time required to install the software will be approximately one (1) hour. Upon completion of the KSDS software installation, Kia will extend the warranty coverage to 15 years/150,000 miles, whichever occurs first, for engine long block assembly repairs needed due to connecting rod bearing damage, provided the vehicle has had regular oil change in accordance with the maintenance requirements set forth in the vehicle's Owner's Manual.

What Will The KSDS Software Do?

If excessive bearing wear is detected after the KSDS software has been installed, the following will occur:

The Malfunction Indicator Lamp ("MIL") will blink continuously, and the vehicle will be placed in a reduced power and 1. acceleration mode [referred to as "Limp Home Mode"].



 Your vehicle can continue to be operated for a <u>limited time</u> in Limp Home Mode to permit you to drive the vehicle to a safe location, but it will accelerate slowly and have a reduced maximum speed. Engine RPMs will be limited to approximately 1800-2000 RPM. This means the maximum vehicle speed will be limited to approximately 65mph or less depending on vehicle loading and road conditions.

What Should You Do?

- In the interest of the safety of your passengers, as well as your own safety, please immediately contact your Kia dealer to arrange for the recall repair to be conducted.
- Continue to follow the maintenance schedule outlined in the Maintenance Section of your vehicle's Owner's Manual. Changing the oil and filter pursuant to your vehicle's oil maintenance schedule is ESSENTIAL to the proper functioning of your engine. Failing to do so can result in engine damage and/or failure. In the worst case, an engine compartment fire may occur.
- To find your nearest dealer, visit <u>www.kia.com</u> and click the "Find Dealer" button in the upper right corner ("Dealers" on a mobile device). You can also use the QR code below with your mobile device to access this information *(see the bottom of this letter for more information about QR code use)*.



What If You Have Already Paid To Have This Situation Corrected?

If you have incurred expense to remedy this issue prior to the date of this notice, you may have the opportunity to obtain reimbursement for that expense. You may submit your receipts online to Kia via the Owners section of www.kia.com or mail your receipts with a copy of the attached Request for Reimbursement form directly to Kia for review and consideration:

Kia Customer Care Kia America, Inc. P.O. Box 52410 Irvine, CA 92619-2410 1-800-333-4542

Pursuant to the General Reimbursement Plan issued by Kia pursuant to Federal Regulation 49 CFR 573.13, Kia will use its best efforts to respond to your claim within sixty (60) days of receipt and at that time Kia may either accept or reject that claim or it may request more information to evaluate the claim.

Have You Changed Your Address Or Sold Your Kia?

If you have changed your home address, sold your Kia vehicle, or no longer own your vehicle, please complete the attached prepaid "Change of Address/Ownership" card and mail it to us. You can also contact the Customer Care Center phone number listed above.

What If You Are A Vehicle Lessor?

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

What If You Have Other Questions?

If your dealer does not respond to your service request in a timely manner, we suggest that you call Kia's Customer Care Center at 1-800-333-4542. This number has TTY capability. If you still are not satisfied that we have remedied this situation without charge and within a reasonable amount of time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, DC 20590; or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to http://www.safercar.gov.

This action has been taken in the interest of your safety, and we regret any inconvenience this situation may cause you.

Sincerely,

Customer Care Department

QR Code Use:

- A QR Code is a square, 2-dimensional barcode that can be read by mobile devices loaded with an appropriate barcode or **QR Code Reader App**. The app reads the barcode image and then launches/uploads the specific information the code contains, such as URLs, text, photos, videos.
- With a mobile device, download a QR Code Reader App. With many devices, you can do this through an app store or marketplace.

• Open the QR Code Reader App on your mobile device. The app will utilize your device's camera. Center the code in the camera viewing area. With some apps, the URL or other information will automatically load when the code is recognized. For others, you may have to snap or take a picture of the QR code. Refer to the QR Reader Code App instructions.

REQUEST FOR REIMBURSEMENT FORM SC218 - 2017-2018 MY OPTIMA HYBRID AND OPTIMA PLUG-IN HYBRID ENGINE COMPARTMENT FIRE SAFETY RECALL CAMPAIGN

If you have incurred expense to remedy this issue prior to the date of this notice, you may have the opportunity to obtain reimbursement for that expense. You may <u>submit your receipts online to Kia via the Owners section of www.kia.com</u> (Owners>Contact Us or directly at this link: <u>https://customercare.kiausa.com</u>).

If you do not have access to a computer or prefer to submit your request by mail, please complete this Request for Reimbursement and mail it to the following address for review and consideration, along with backup documentation:

Kia Customer Care Kia America, Inc. P. O. Box 52410 Irvine, CA 92619-2410 1-800-333-4542

Please allow at least sixty (60) days for review and response.

Customer First Name:			Custom	er Last Name:				
Customer Address:								
Customer City:			State:		Zip:			
Phone #: () -		Email:					
Vehicle Identification N	umber:							
Mileage at Time of Rep	air:			Date of Repair:		/	/	
Amount of Reimbursem	ent Requested	\$						

Attach the following:

- Repair Order showing:
 - Name & address of person paying for the repair
 - Vehicle Identification Number (VIN) of vehicle repaired
 - Description of the problem repaired
 - Date of repair, mileage at the time of repair and total cost of claimed repair expense
- Evidence of Payment of Repair showing:
 - o Date of Payment
 - Amount Paid (e.g., copies of cancelled check or credit card receipt)

I certify that the documents attached to this Request for Reimbursement are true and accurate and should be used as the basis for a reimbursement to me under this campaign.

CLAIMANT'S SIGNATURE: