N212336230 Improper Inspection for Overcured Tires



Release Date: August 2021 Revision: 02

Revision Description: This bulletin is being revised to include an additional procedure on disabling the tire. Please discard all previous copies of N212336230.

Attention:

It is a violation of Federal law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by this notification under a sale or lease until the defect or noncompliance is remedied.

All involved vehicles that are in dealer inventory must be held and not delivered to customers, dealer traded, or used for demonstration purposes until the repair contained in this bulletin has been performed on the vehicle.

IMPORTANT: Please be sure the factory installed Continental tires are being inspected for this recall and the inspection is not being performed on an alternate set of customer tires, such as winter, performance or accessory substitutes. If alternate tires are installed, the customer will have to return once the OE tires are reinstalled on their vehicle.

		Model Year			
Make	Model	From	То	RPO	Description
Chevrolet	Silverado 1500	2010	2010		
GMC	Sierra 1500	2019	2019		

Involved vehicles are marked "open" on the Investigate Vehicle History screen in GM Global Warranty Management system. This site should always be checked to confirm vehicle involvement prior to beginning any required inspections and/or repairs.

Condition	General Motors has decided that a defect which relates to motor vehicle safety exists in certain
	Continental tires installed as original equipment on certain 2019 model year Chevrolet Silverado 1500
	and GMC Sierra 1500 vehicles. According to the tire manufacturer, Continental Tires the Americas
	(Continental), the affected tires may have an overcure condition and Continental has initiated a safety
	recall for these tires. Due to an omission in the service bulletin for General Motors' recall N212329050,
	dealers may have failed to identify and replace, as necessary, suspect tires on 2019 Silverado and Sierra
	vehicles that were inspected under that recall. According to Continental, overcured tires may experience
	a carcass break in the sidewall with sudden air loss or could develop a belt edge separation which could
	lead to partial or full tread/belt loss. These conditions may increase the risk of a crash.
Correction	Dealers will inspect vehicles and replace tires that have DOT number and production mold number
	combinations identified by Continental.

Parts

Quantity	Part Name		Part No.
As Required	P255/70 R 17	110S TL GRABBER HTS	23242101

Important: Verify that any service replacement tires are not part of this recall. Before installing the service tire, inspect the sidewall and verify the DOT date and mold number are not listed in the Tire Information Chart listed in the Service Procedure.

US Dealers:

If you have concerns acquiring replacement tires through your normal process, please call the GM Tire Program at 1-877-728-4737.

Canada Dealers:

If you have concerns acquiring replacement tires through your normal process, please call their Continental Rep or 1-855-453-1962.

Warranty Information

Labor Operation	Description	Labor Time	Trans. Type	Net Item
9105809	Inspect 4 Road Tires for Production Information (Inspect Only) Add: Inspect Spare Tire	0.2 0.1	ZFAT	N/A
9105810*	Replace First Tire (Includes Inspection) Add: Each Additional Tire Replacement	0.5 0.3	ZFAT	N/A

N212336230 Improper Inspection for Overcured Tires



*US & Canada Dealers: In the case of tire replacements, first prepare the ZREG transaction Tire PRA and then submit a ZFAT transaction. Instructions for submitting a PRA are at the end of the service procedure.


US & Canada - Net / Admin Allowance - \$25 may be claimed for submitting the Tire Pre-Repair Authorization (PRA) into the Global Warranty Management (GWM) system and to return the tire(s) to the tire manufacturer.

US Dealers in Hawaii, Alaska, Puerto Rico, Guam and Canadian Dealers in Northwest and Yukon Territories - do not submit a Tire PRA but contact Continental at 1-888-799-2168.

Service Procedure

IMPORTANT: Silverado and Sierra vehicles equipped with 17" General tires may have a spare tire involved in this recall. Inspect the spare tire and determine if it is the same size and brand as the road tires. If it matches, inspect the sidewall information as described in the procedure. If it does not match, no further action is required for the spare tire.

This procedure involves inspecting the tire sidewall for manufacturing information. The mold number, in parenthesis along with the last four numbers in the DOT stamp (Date Code) indicate if the tire is involved in this recall. See the examples in the photographs below.



5672012



5672013


N212336230 Improper Inspection for Overcured Tires



Tire Information Chart

Model	Affected PN	Affected DOT wk(s) -
		Mold # combination
Silverado	23242101	4118 - 414559
Sierra		4418 - 414560

The tires must contain the exact DOT week and mold number combination as specified in the chart above.



- 1. Inspect the tire sidewall as shown and verify the mold number (2) and the DOT week (1).
- 2. If the mold number and DOT date match the *Affected DOT wk(s) Mold # combination* in the tire information chart, replace the tire.

Additional Procedures for US/Canada

Federal regulations require all recalled tires to be completely disabled within 24 hours of removal. If the DOT date and Mold # combination matches the information provided in the chart, the tire needs to be rendered inoperable immediately after it is removed. It is necessary to drill two 13mm (or ½ inch) holes in the tire sidewall to ensure it is not put back into service. Do not drill through the DOT date or Mold # combination.

N212336230 Improper Inspection for Overcured Tires





5682490

Drill two 13mm holes in the tire sidewall. Do not drill through the DOT date or Mold # combination.

Tire Return Instructions:

Note: The recalled tire return procedures are region specific. Please follow your country's return procedures outlined below

Note: failure to comply with providing the necessary information puts the dealership at risk of a debited claim.

For US and Canada:

The following process only applies to vehicle tires replaced per this recall. Follow the normal process for all other warranty replacement tires.

Drill two 13mm or ½ inch holes in the sidewall immediately after removal per the instructions above.

Create a New Tire Pre-Repair Authorization Document in Global Warranty Management (GWM)

- Select ZREG transaction type
- Select Tire Replacement Pre-Repair Type
- Enter required information on Tire Pre-Repair Authorization tab. Required fields are marked with an "*". Enter 8060460 in the Labor Operation field.
- Enter required information on the Tire Pre-Repair Authorization tab. Select "Other" as the Removal Reason and enter "Product Safety Recall N21-2336230, Tire DOT Date ____(enter #### four-digit date) and Mold #____(enter ##### six-digit mold number)" in the text box.
- For the two questions at the bottom of the page:
 - Select "Yes" for the first question at the bottom of the page (Was there visible cracking....?) and enter "Product Safety Recall N21-2336230, Tire DOT Date ____(enter #### four-digit date) and Mold #____(enter ##### six-digit mold number)" in the text box.
 - Select "No" for the second question (Did the tire issue cause.....?)
- Print the GWM Tire Replacement Document. Attach a copy of the complete Document to the job card.
- Detach the shipping label portion of the document, attach a copy to each tire using clear packing tape.
- Mark tires with the word "RECALL" on the sidewall
- Ship tire(s) immediately to address on GWM shipping label.
- Once the Tire PRA is in "Accept" status, submit the transaction as follows:
 - Select ZFAT transaction

N212336230 Improper Inspection for Overcured Tires



- o Enter Pre-Repair Authorization Number in the "Reference Number" field
- Use applicable tire replacement labor operation provided in this bulletin (9105810)
- o Enter replacement tire part number and quantity in the Parts section
- No proration applies to used tires subject to this recall
- o DO NOT select GM Pre-Repair Authorization in the "Authorization/Comments" section of the transaction
- DO NOT enter the Tire PRA number in the Pre-Repair Authorization Number field.

Dealer Responsibility - For USA & Export (USA States, Territories, and Possessions)

It is a violation of Federal law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by this notification under a sale or lease until the defect or noncompliance is remedied.

The US National Traffic and Motor Vehicle Safety Act provides that each vehicle that is subject to a recall of this type must be adequately repaired within a reasonable time after the customer has tendered it for repair. A failure to repair within sixty days after tender of a vehicle is prima facie evidence of failure to repair within a reasonable time. If the condition is not adequately repaired within a reasonable time, the customer may be entitled to an identical or reasonably equivalent vehicle at no charge or to a refund of the purchase price less a reasonable allowance for depreciation. To avoid having to provide these burdensome remedies, every effort must be made to promptly schedule an appointment with each customer and to repair their vehicle as soon as possible. In the recall notification letters, customers are told how to contact the US National Highway Traffic Safety Administration if the recall is not completed within a reasonable time.

Dealer Responsibility – All

All new, used, GM Certified Used, courtesy transportation vehicles, dealer shuttle vehicles, etc. in dealers' possession and subject to this recall <u>must</u> be held and inspected/repaired per the service procedure of this bulletin <u>before</u> customers take possession of these vehicles. Involved vehicles must be held and not delivered to customers, dealer-traded, released to auction, used for demonstration, or any other purpose.

All GM Certified Used vehicles currently in the dealers' inventory within the Certified Pre-Owned Inventory System (CPOIS) will be de-certified and must be held and remedied per the service procedure in this bulletin. Upon submitting an accepted/paid warranty transaction in the Global Warranty Management (GWM) system, the vehicle can be re-certified for sale within the CPOIS system, or once again be used in the CTP program.

Dealers are to service all vehicles subject to this recall at no charge to customers, regardless of mileage, age of vehicle, or ownership, from this time forward.

Customers who have recently purchased vehicles sold from your vehicle inventory, and for which there is no customer information indicated on the dealer listing, are to be contacted by the dealer. Arrangements are to be made to make the required correction according to the instructions contained in this bulletin. A copy of the customer letter is provided in this bulletin for your use in contacting customers. Recall follow-up cards should not be used for this purpose, since the customer may not as yet have received the notification letter.

In summary, whenever a vehicle subject to this field action enters your vehicle inventory you must take the steps necessary to ensure the program correction has been made before selling the vehicle. In addition, for vehicles entering your facility for service, you are required to ensure the customer is aware of the open field action and make every reasonable effort to implement the program correction as set forth in this bulletin prior to releasing the vehicle.

Dealer Reports

For dealers with involved vehicles, a listing has been prepared and will be available through GM GlobalConnect Maxis Field Action Reports or sent directly to export dealers. The Inventory tab of the dealer reports will contain VINs that apply to this recall. This information is intended to assist dealers with the **PROMPT COMPLETION** of these vehicles. The Customer In-Service tab will contain customer names and addresses from Motor Vehicle Registration Records. The use of such motor vehicle registration data for any purpose other than follow-up necessary to complete this recall may be a violation of law in several states.

Courtesy Transportation - For USA & Canada

Courtesy transportation is available for customers whose vehicles are involved in a product program and still within the warranty coverage period. See General Motors Service Policies and Procedures Manual for courtesy transportation program details.

N212336230 Improper Inspection for Overcured Tires



Customer Notification

USA & Canada - General Motors will notify customers of this recall on their vehicle (see copy of customer letter included with this bulletin).

N212336230 Improper Inspection for Overcured Tires





IMPORTANT SAFETY RECALL

June 2021

This notice applies to your vehicle, VI	N:

Dear General Motors Customer:

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

General Motors, based on information provided by Continental Tires the Americas (CTA), has decided that a defect which relates to motor vehicle safety exists in certain Continental tires installed as original equipment on certain 2019 model year Chevrolet 1500 and GMC Sierra 1500 vehicles. As a result, GM is conducting a safety recall. We apologize for this inconvenience. However, we are concerned about your safety and continued satisfaction with our products.

IMPORTANT

- Your vehicle is involved in GM safety recall N212336230.
- Schedule an appointment with your GM dealer.
- This service will be performed for you at **no charge**.

Why is your vehicle being recalled?

According to the tire manufacturer, Continental Tires the Americas (Continental), the affected tires may have an overcure condition and Continental has initiated a safety recall for these tires. Due to an omission in the service bulletin for General Motors' recall 21V-115 (N212329050), dealers may have failed to identify and replace, as necessary, suspect tires on 2019 Silverado and Sierra vehicles that were inspected under that recall.

According to Continental, overcured tires may experience a carcass break in the sidewall with sudden air loss or could develop a belt edge separation which could lead to partial or full tread/belt loss. These conditions may increase the risk of a crash.

What will we do?

Your GM dealer will inspect your vehicle's tires. If a tire has the DOT number and production mold number combinations identified by Continental as subject to the recall, your dealer will replace the tire with a new tire of the same or equivalent size and description free of charge, including mounting, balancing and taxes.

If you have already replaced an affected tire prior to your receipt of this notice due to the condition described, Continental may reimburse you for the cost of the comparable replacement tire, including mounting, balancing and taxes. To be eligible for reimbursement, you must complete a Reimbursement Request Form and submit this form with the required documents to Continental. The Reimbursement Request Form is available at www.continentaltire.com, scroll to the bottom of the page and click on TIRE RECALL or you may request a form by calling CTA Customer Relations at 1-888-799-2168.

The tires must meet both DOT and mold number in order to be part of the recall. Details of the DOT and mold number combinations can also be found on www.continentaltire.com, scroll to the bottom of the page and click TIRE RECALL.

What should you do?

You should contact your GM dealer to arrange a service appointment as soon as possible.

N212336230 Improper Inspection for Overcured Tires



Do you have questions?

If you have questions or concerns that your dealer is unable to resolve, please contact the appropriate Customer Assistance Center at the number listed below.

Division	Number	Text Telephones (TTY)	
Chevrolet	1-800-630-2438	1-800-833-2438	
GMC	1-866-996-9463	1-800-462-8583	
Puerto Rico – English	1-800-496-9992		
Puerto Rico – Español	1-800-496-9993		
Virgin Islands	1-800-496-9994		
GM Medium Duty Truck	1-800-862-4389		

If after contacting your dealer and the Customer Assistance Center, you are still not satisfied we have done our best to remedy this condition without charge and within a reasonable time, you may wish to write the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590, or call the toll-free Vehicle Safety Hotline at 1.888.327.4236 (TTY 1.800.424.9153), or go to http://www.safercar.gov. The National Highway Traffic Safety Administration Campaign ID Number for this recall is 21V423.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

MaryAnn Combs Vice President Global Vehicle Safety

GM Recall: N212336230