N162016079 Park/Position Lamp Intensity



Revision: 01 Release Date: October 2021

Revision Description: This bulletin has been revised to add a copy of the customer letter. Please discard all

copies of bulletin N162016079.

Attention: It is a violation of Federal law for a dealer to deliver a new motor vehicle or any new or used item of motor

vehicle equipment (including a tire) covered by this notification under a sale or lease until the defect or

noncompliance is remedied.

All involved vehicles that are in dealer inventory must be held and not delivered to customers, dealer traded, or used for demonstration purposes until the repair contained in this bulletin has been performed on the vehicle.

		Model Year			
Make	Model	From	То	RPO	Description
Cadillac	CT6	2016	2017		

Involved vehicles are marked "open" on the Investigate Vehicle History screen in GM Global Warranty Management system. This site should always be checked to confirm vehicle involvement prior to beginning any required inspections and/or repairs.

Condition	General Motors has decided that certain 2016-2017 Cadillac CT6 vehicles fail to conform to Federal Motor Vehicle Safety Standard (FMVSS) 108 "Lamp, Reflective Devices and Associated Equipment." The light output of the forward Park/Position lamps may exceed the maximum values permitted by the
	standard. Lamps that are brighter than compliant lamps may be distracting to other drivers, increasing the risk of a crash.
Correction	Dealers will install right and left side in-line headlamp jumper harnesses that correct the condition.

Parts

Quantity	Part Name	Part No.
2	Harness – Headlamp Jumper	84240083

There are only 6 vehicles involved in this recall. Please do not order parts for shelf stock.

Reminder: Parts may be removed from Retail Inventory Management (RIM). Dealers should review the affected parts to confirm RIM managed status. Parts may have quantity limiters in effect.

Warranty Information

Labor		Labor	Trans.	Net
Operation	Description	Time	Type	Item
9105970	Install Left and Right Headlamp Jumper Harness	0.4	ZFAT	N/A
9105971	Customer Reimbursement Approved - For USA and Canada dealers only	N/A	ZFAT	*
9105972	Customer Reimbursement Denied – For USA dealers only	N/A	ZFAT	**

Note: To avoid having to "H" route the customer reimbursement transaction for approval, it must be submitted prior to the repair transaction.

Service Procedure

1. Turn the front wheels to the full right position.

^{*} For USA and Canada: Submit the dollar amount reimbursed to the customer in Net/Reimbursement. Submit \$20.00 administrative allowance in Net/Admin Allowance.

^{**} Submit \$10.00 administrative allowance in Net/Admin Allowance.

N162016079 Park/Position Lamp Intensity





4626092

2. Remove the four left wheelhouse liner fasteners as shown.



4626094

3. Unplug the left headlamp wiring harness from the lamp.




4626097

4. Install the jumper harness to the lamp harness and plug the jumper into the left headlamp.

N162016079 Park/Position Lamp Intensity





4627038

5. After the jumper harness is installed, engage the CPA clip (the red locking tab on the connector).



4626101

- 6. Twist the harness connector 180 Deg. and clip the retainer to the cast aluminum wheelhouse.
- 7. Reinstall the four left wheelhouse liner fasteners. Tighten 2.5 N.m (22 lb in).
- 8. Turn the front wheels to the full left position.
- 9. Remove the four right wheelhouse liner fasteners.
- 10. Unplug the right headlamp wiring harness from the lamp.
- 11. Install the jumper harness to the lamp harness and plug the jumper into the right headlamp.
- 12. After the jumper harness is installed, engage the CPA clip (the red locking tab on the connector).

N162016079 Park/Position Lamp Intensity





1626103

- 13. Clip the retainer to the cast aluminum wheelhouse.
- 14. Reinstall the four right wheelhouse liner fasteners. Tighten 2.5 N.m (22 lb in).
- 15. Perform a final function test to ensure the front lamps turn on.
- 16. CALIFORNIA VEHICLES ONLY: Complete a "Proof of Correction" certificate and provide to the vehicle owner upon recall completion.

Dealer Responsibility - For USA & Export (USA States, Territories, and Possessions)

It is a violation of Federal law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by this notification under a sale or lease until the defect or noncompliance is remedied.

The US National Traffic and Motor Vehicle Safety Act provides that each vehicle that is subject to a recall of this type must be adequately repaired within a reasonable time after the customer has tendered it for repair. A failure to repair within sixty days after tender of a vehicle is prima facie evidence of failure to repair within a reasonable time. If the condition is not adequately repaired within a reasonable time, the customer may be entitled to an identical or reasonably equivalent vehicle at no charge or to a refund of the purchase price less a reasonable allowance for depreciation. To avoid having to provide these burdensome remedies, every effort must be made to promptly schedule an appointment with each customer and to repair their vehicle as soon as possible. In the recall notification letters, customers are told how to contact the US National Highway Traffic Safety Administration if the recall is not completed within a reasonable time.

Dealer Responsibility – All

All new, used, GM Certified Used, courtesy transportation vehicles, dealer shuttle vehicles, etc. in dealers' possession and subject to this recall <u>must</u> be held and inspected/repaired per the service procedure of this bulletin <u>before</u> customers take possession of these vehicles. Involved vehicles must be held and not delivered to customers, dealer-traded, released to auction, used for demonstration, or any other purpose.

All GM Certified Used vehicles currently in the dealers' inventory within the Certified Pre-Owned Inventory System (CPOIS) will be de-certified and must be held and remedied per the service procedure in this bulletin. Upon submitting an accepted/paid warranty transaction in the Global Warranty Management (GWM) system, the vehicle can be re-certified for sale within the CPOIS system, or once again be used in the CTP program.

Dealers are to service all vehicles subject to this recall at no charge to customers, regardless of mileage, age of vehicle, or ownership, from this time forward.

Customers who have recently purchased vehicles sold from your vehicle inventory, and for which there is no customer information indicated on the dealer listing, are to be contacted by the dealer. Arrangements are to be made to make the required correction according to the instructions contained in this bulletin. A copy of the customer letter is provided in this bulletin for your use in contacting customers. Recall follow-up cards should not be used for this purpose, since the customer may not as yet have received the notification letter.

In summary, whenever a vehicle subject to this field action enters your vehicle inventory you must take the steps necessary to ensure the program correction has been made before selling the vehicle. In addition, for vehicles entering

N162016079 Park/Position Lamp Intensity



your facility for service, you are required to ensure the customer is aware of the open field action and make every reasonable effort to implement the program correction as set forth in this bulletin prior to releasing the vehicle.

Dealer Reports

For dealers with involved vehicles, a listing has been prepared and will be available through GM GlobalConnect Maxis Field Action Reports or sent directly to export dealers. The Inventory tab of the dealer reports will contain VINs that apply to this recall. This information is intended to assist dealers with the **PROMPT COMPLETION** of these vehicles. The Customer In-Service tab will contain customer names and addresses from Motor Vehicle Registration Records. The use of such motor vehicle registration data for any purpose other than follow-up necessary to complete this recall may be a violation of law in several states.

Customer Notification

USA & Canada - General Motors will notify customers of this recall on their vehicle (see copy of customer letter included with this bulletin).

Customer Reimbursement

Customer requests for reimbursement of previously paid repairs to correct the condition described in the bulletin can be submitted at anytime to the dealer. See General Motors Service Policies and Procedures Manual, Product Field Action Customer Reimbursement Procedure (USA & Canada) or local Policies and Procedures, for details.

N162016079 Park/Position Lamp Intensity





IMPORTANT SAFETY RECALL

November 2021

This notice applies to your vehicle, VIN:	
ral Matera Customer	

Dear General Motors Customer:

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

General Motors has decided that certain 2016-2017 Cadillac CT6 vehicles fail to conform to Federal Motor Vehicle Safety Standard (FMVSS) 108 "Lamp, Reflective Devices and Associated Equipment." As a result, GM is conducting a recall. We apologize for this inconvenience. However, we are concerned about your safety and continued satisfaction with our products.

IMPORTANT

- Your vehicle is involved in GM safety recall N162016079.
- Schedule an appointment with your GM dealer.
- This service will be performed for you at **no charge**.

Why is your vehicle being recalled?

The light output of the forward Park/Position lamps may exceed the maximum values permitted by the standard. Lamps that are brighter than compliant lamps may be distracting to other drivers, increasing the risk of a crash.

What will we do?

Your GM dealer will install right and left side in-line headlamp jumper harnesses that correct the condition free of charge. Because of service scheduling requirements, it is likely that your dealer will need your vehicle longer than the actual service correction time of approximately 30 minutes.

What should you do?

You should contact your GM dealer to arrange a service appointment as soon as possible.

Did you already pay for this repair?

Even though you may have previously had repairs for this condition, you will still need to take your vehicle to your dealer for additional repairs. If you have already paid for repairs for the recall condition, please complete the enclosed reimbursement form and present it to your dealer with all required documents. Working with your dealer will expedite your request, however, if this is not convenient, you may mail the completed reimbursement form and all required documents to Reimbursement Department, PO Box 33170, Detroit, MI 48232-5170.

Do you have questions?

If you have questions or concerns that your dealer is unable to resolve, please contact the appropriate Customer Assistance Center at the number listed below.

Division	Number	Text Telephones (TTY)
Cadillac	1-800-333-4223	1-800-833-2622
Puerto Rico – English	1-800-496-9992	
Puerto Rico – Español	1-800-496-9993	
Virgin Islands	1-800-496-9994	

If after contacting your dealer and the Customer Assistance Center, you are still not satisfied we have done our best to remedy this condition without charge and within a reasonable time, you may wish to write the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590, or call the toll-free Vehicle Safety Hotline at 1.888.327.4236 (TTY 1.800.424.9153), or go to http://www.safercar.gov. The National Highway Traffic Safety Administration Campaign ID Number for this recall is 21V759.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

FMVSS Noncompliance Recall N162016079 Park/Position Lamp Intensity



Regina A. Carto Vice President Global Product Safety and Systems

Enclosure

GM Recall: N162016079