OMB Control No.: 2127-0004

# Part 573 Safety Recall Report

# 22E-099

Manufacturer Name: Williamsen-Godwin Truck Body Company LLC

Submission Date: APR 18, 2023 NHTSA Recall No.: 22E-099 Manufacturer Recall No.: 22E-080



#### **Manufacturer Information:**

Manufacturer Name: Williamsen-Godwin Truck Body

**Company LLC** 

Address: 1925 west Indiana Ave

Salt Lake City UT 84070

Company phone: 8019739400

## **Population:**

Number of potentially involved : 12 Estimated percentage with defect : 100%

## **Equipment Information:**

Brand / Trade 1: WILLIAMSEN-GODWIN

Model: WPED5W-SL2255
Part No.: STEERING AXLE

Size: NR Function: NR

Descriptive Information: RECALL NOTICE CAME FROM DEXTER AXLE

Production Dates: APR 01, 2021 - JUN 18, 2021

#### **Description of Defect:**

Description of the Defect: STEER ARM

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: STEER ARM CAN SHEAR UNDER HEAVY LOAD

 $\begin{array}{c} \textbf{Description of the Cause:} & \textbf{NR} \\ \textbf{Identification of Any Warning} & \textbf{NR} \\ \end{array}$ 

that can Occur:

#### **Involved Components:**

Component Name: SMART STEER 2.0 SELF STEERING AXLE

Component Description: 25K SELF STEERING AXLE

Component Part Number: SSA750048-NPA-ACRD-22.5B

#### **Supplier Identification:**

#### **Component Manufacturer**

Name: DEXTER CANADA (INGERSOLL AXLES)

Address: 160 INGERSOLL STREET SOUTH

ONTARIO Foreign States N5C3J7

Country: Canada

#### **Chronology:**

10/19/2022 INFORMATION WAS PROVIDED BY DEXTER FOR RECALL # NHTSA ID 22E-080

10/31/2022 EMAILED THE RECALL INFORMATION PROVIDED TO CUSTOMER.

11/16/2022 NOTIFIED BY NTHSA ABOUT THE RECALL, SIGNED UP ON THE PORTAL.

12/15/2022 NOTIFIED OUR ACCOUNT WAS SET UP AND APPROVED AND BEGAN THE FILLING

12/21/2022 RECALL PROCESSED

3/15/2023 OWNER LETTER SENT TO CUSTOMER

## **Description of Remedy:**

Description of Remedy Program: SERVICE WORK WILL INCLUDE THE FOLLOWING STEPS (PER SB015)

1. REMOVE THE EXISTING STEER ARMS AND MOUNTING HARDWARE.

2. CLEAN MOUNTING SURFACE AND SURROUNDING SURFACES TO PREPARE FOR MOUNTING OF THE NEW BOLT-ON STEER ARM AND

ADDITIONAL WELDS.

3. GRIND A 3/16" CHAMFER ALONG THE MOUNTING FACE EDGE (SEE

PAGE THREE FOR LOCATION AND DETAIL).

4. MOUNT NEW DESIGN STEER ARMS (PART #703293-LH/RH) WITH

SUPPLIED HARDWARE AND TORQUE TO 400 FT-LBS

5. ADD WELDS AS SHOWN ON PAGE THREE OF THIS BULLETIN

from Recalled Component:

How Remedy Component Differs NEW DESIGN HAS HIGHER STRENGTH MATERIAL AND WELDED TO THE

from Recalled Component: STEERING KNUCKLE

# Part 573 Safety Recall Report

22E-099

Page 3

Identify How/When Recall Condition IMPLEMENTED A NEW DESIGN WITH HIGHER STRENGTH MATERIAL AS

was Corrected in Production: WELL AS AN ADDITIONAL WELD CONNECTING THE ARM TO THE

KNUCKLE INTO PRODUCTION AT DEXTER CANADA ON 30-OCTOBER-22

#### **Recall Schedule:**

Description of Recall Schedule: CUSTOMER WILL BE CONTACTED DIRECTLY TO HAVE UNITS BROUGHT

IN TO HAVE THE RECALL COMPLETED.

Planned Dealer Notification Date: NR - NR

Planned Owner Notification Date: DEC 15, 2022 - JUN 01, 2023

#### **Purchaser Information:**

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name: NR

Address: NR

NR

Country: NR

Company Phone: NR

<sup>\*</sup> NR - Not Reported