

# Part 573 Safety Recall Report

## 22V-080

**Manufacturer Name :** Jaguar Land Rover North America, LLC

**Submission Date :** FEB 28, 2022

**NHTSA Recall No. :** 22V-080

**Manufacturer Recall No. :** N664



### Manufacturer Information :

### Population :

**Manufacturer Name :** Jaguar Land Rover North America, LLC

**Number of potentially involved :** 18,824

**Address :** 100 Jaguar Land Rover Way

**Estimated percentage with defect :** 100 %

Mahwah NJ 07495

**Company phone :** 8188500

### Vehicle Information :

**Vehicle 1 :** 2020-2020 LAND ROVER RANGE ROVER EVOQUE

**Vehicle Type :** LIGHT VEHICLES

**Body Style :** SUV

**Power Train :** NR

**Descriptive Information :** Jaguar Land Rover is conducting a voluntary safety recall campaign involving certain 2020MY Range Rover Evoque vehicles built at the Halewood Assembly Plant, UK from November 2, 2018, to November 12, 2020. 18,824 Range Rover Evoque vehicles in the United States and Federalized Territories. The basis of the recall population was derived from Jaguar Land Rover data where the VIN range for vehicles affected were determined based on manufacturing dates where there was a pattern and trend of the defect.

**Production Dates :** NOV 02, 2018 - NOV 12, 2020

**VIN Range 1 : Begin :** SALZM2GX5LH000181 **End :** SALZL2FX7LH121881  Not sequential

### Description of Defect :

**Description of the Defect :** A concern has been identified with the supplementary restraint system (SRS) warning system on certain 2020 Model Year Land Rover Range Rover Evoque vehicles where the diagnostic check for the SRS is overly sensitive due to an incorrect diagnostic parameter for the driver airbag. Vehicles with this condition may experience intermittent SRS warning light illumination although the driver air bag will correctly operate with the known error state present.

**FMVSS 1 :** NR

**FMVSS 2 :** NR

**Description of the Safety Risk :** Vehicles with false illumination of the SRS system warning light may not properly warn the driver of an actual airbag system fault which may increase the risk of serious injury in the event of an accident of sufficient severity necessitating driver airbag deployment.

Description of the Cause : NR  
Identification of Any Warning NR  
that can Occur :

## Involved Components :

Component Name 1 : RCM (Restraints Control Module) Software  
Component Description : RCM (Restraints Control Module) Software  
Component Part Number : K8D2-14C028-A\*

## Supplier Identification :

### Component Manufacturer

Name : Jaguar Land Rover Limited  
Address : Abbey Road  
Whitley, Coventry Foreign States CV3 4LF  
Country : United Kingdom

## Chronology :

See File "Recall N664 Chronology Updated".

## Description of Remedy :

Description of Remedy Program : Retailers will update the RCM software by a wired update to a level with the specified system resistance value threshold for the driver airbag circuit.

There will be no charge to owners for this repair.

The affected vehicles will be covered under Land Rover's new vehicle warranty program. Therefore, reimbursement for pre-notice remedies is not necessary because the affected vehicles are still under warranty.

How Remedy Component Differs NR  
from Recalled Component :

Identify How/When Recall Condition was Corrected in Production : NR

**Recall Schedule :**

Description of Recall Schedule : Distribution of owner notification letters will occur on or before April 14, 2022. Notifications to retailers will occur on March 1, 2022.

Planned Dealer Notification Date : MAR 01, 2022 - MAR 01, 2022

Planned Owner Notification Date : APR 14, 2022 - APR 14, 2022

\* NR - Not Reported