

Part 573 Safety Recall Report

22V-120

Manufacturer Name : AEBI-Schmidt**Submission Date :** DEC 12, 2022**NHTSA Recall No. :** 22V-120**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : AEBI-Schmidt

Address : 201 MB Lane

Chilton WI 53014

Company phone : 920 898 1035

Population :

Number of potentially involved : 1

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2019-2019 AEBI - Schmidt MB3

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : UNKNOWN

Power Train : DIESEL

Descriptive Information : Vehicles equipped with Cummins X12 Part number D0S005BX03 Diesel engine. These engines are equipped with High Pressure Common Rail fuel systems and sold for installation in mixer, truck, coach, emergency vehicle, refuse truck, recreational vehicle and crane applications. The recall consists of the entire population of engines equipped with a certain Injector Fuel Supply Tube (fuel tube) prior to the implementation of corrective action.

Production Dates : APR 26, 2016 - OCT 11, 2021

VIN Range 1 : Begin : 1M9BBBAP1KC967385 End : 1M9BBBAP1KC967385 Not sequential**Description of Defect :**

Description of the Defect : The fuel tubes between the fuel rail and the injector for cylinders 4, 5 and 6 may be susceptible to cracking, resulting in a high pressure fuel leak.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : A high pressure fuel leak in the presence of an ignition source may increase the risk of a fire.

Description of the Cause : The subject fuel tubes (for cylinders 4, 5 and 6) are susceptible to cracking due to metal fatigue failure resulting from a combination of vibration strain, assembly strain and material strength.

Identification of Any Warning that can Occur : Fuel leaks may be detected during maintenance. An operator may smell fuel or observe a mist due to the fuel leak

Involved Components :

Component Name 1 : Injector Fuel Supply Tube

Component Description : Fuel tube between fuel rail and fuel injector

Component Part Number : 5536516

Component Name 2 : Injector Fuel Supply Tube

Component Description : Fuel tube between fuel rail and fuel injector

Component Part Number : 5486389

Component Name 3 : Injector Fuel Supply Tube

Component Description : Fuel tube between fuel rail and fuel injector

Component Part Number : 3695190

Supplier Identification :

Component Manufacturer

Name : Cummins, Inc.

Address : Box 3005

Mail Code 41303 Columbus Indiana 47202-3005

Country : United States

Chronology :

December 13, 2021 - Letter from Cummins concerning recall 21E-099 - Request for Owner Addresses and Vehicle Recall Numbers

December 13, 2021 - Reply to Cummins for qty 1, On-Highway machine with requested details.

February 14, 2022 - Information request from US DOT regarding recall 21E-099

Description of Remedy :

Description of Remedy Program :	The subject fuel tubes for cylinders 4, 5 and 6 (the rear half of the engine) will be replaced with new fuel tubes (having the same part number as the recalled components) and vibration isolators will be added to the fuel tubes. A recall-specific reimbursement plan will be provided on the Recall Portal for those units not covered by the manufacturer's limited warranty.
How Remedy Component Differs from Recalled Component :	The replacement fuel tubes will also have vibration isolators. The fuel tube and vibration isolator combination will have a new part number.
Identify How/When Recall Condition was Corrected in Production :	The injector alignment to the cylinder head was improved by implementing an improved alignment fixture during engine assembly and vibration isolators were added to the fuel tubes during engine assembly on November 2, 2021.

Recall Schedule :

Description of Recall Schedule :	NR
Planned Dealer Notification Date :	NR - NR
Planned Owner Notification Date :	NR - NR

* NR - Not Reported