

# Part 573 Safety Recall Report

# 22V-262

**Manufacturer Name :** Autocar, LLC**Submission Date :** APR 15, 2022**NHTSA Recall No. :** 22V-262**Manufacturer Recall No. :** ACX-2202**Manufacturer Information :**

Manufacturer Name : Autocar, LLC

Address : 551 S WASHINGTON STREET  
HAGERSTOWN IN 47346

Company phone : 7654895499

**Population :**

Number of potentially involved : 908

Estimated percentage with defect : 100 %

**Vehicle Information :**

Vehicle 1 : 2019-2021 Autocar Xpeditor (ACX)

Vehicle Type : BUSES, MEDIUM &amp; HEAVY VEHICLES

Body Style : OTHER

Power Train : NR

Descriptive Information : All Xpeditor (ACX) units manufactured with the suspect wiring harness are included.

Production Dates : MAR 04, 2019 - NOV 12, 2020

VIN Range 1 : Begin : 5VCACLEF4KC229795 End : 5VCACLAF2MC234843  Not sequential**Description of Noncompliance :**

Description of the Noncompliance : The hazard lamps will not function with the ignition off.

FMVSS 1 : 108 - Lamps, reflective devices, and assoc. Equipment

FMVSS 2 : NR

Description of the Safety Risk : Non-compliance as the hazard lighting is disabled with the ignition and increases the risk of personal injury or a crash.

Description of the Cause : An Autocar design error that allows the hazard lighting function to be disabled with the ignition.

Identification of Any Warning that can Occur : None

**Involved Components :**

Component Name 1 : Autocar Wiring Harness

Component Description : Autocar Wiring Harness

Component Part Number : A8731172-002

## Supplier Identification :

### Component Manufacturer

Name : Autocar LLC

Address : 551 S Washington St  
Hagerstown Indiana 47346

Country : United States

## Chronology :

March 31, 2022 Autocar personnel discovered hazard lighting non-functional with the ignition off. April 1, 2022 - April 8, 2022 an investigation determined the wiring harness had been revised to provide ignition voltage to the hazard lighting. April 8, 2022 Autocar decides to perform a voluntary safety recall for all affected units.

## Description of Remedy :

Description of Remedy Program : The wiring harness will be repaired or replaced to provide battery voltage to the hazard lighting at no charge to the owner.

How Remedy Component Differs from Recalled Component : Battery voltage will be supplied to the hazard lighting.

Identify How/When Recall Condition was Corrected in Production : March-April 2022. All in-house units were reworked and a clean point established for production.

## Recall Schedule :

Description of Recall Schedule : Owner and dealer notifications will begin June 13, 2022 and end June 14, 2022.

Planned Dealer Notification Date : JUN 13, 2022 - JUN 14, 2022

Planned Owner Notification Date : JUN 13, 2022 - JUN 14, 2022

\* NR - Not Reported