OMB Control No.: 2127-0004

Part 573 Safety Recall Report

22V-834

Manufacturer Name: Navistar, Inc. **Submission Date:** DEC 19, 2022 NHTSA Recall No.: 22V-834 Manufacturer Recall No.: 22521



Manufacturer Information:

Manufacturer Name: Navistar, Inc.

Address: 2701 Navistar Drive

Lisle IL 60532

Company phone: 331-332-1590

Population:

Number of potentially involved: Estimated percentage with defect: 10 %

Vehicle Information:

Vehicle 1: 2023-2023 International MV

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style: OTHER Power Train: DIESEL

Descriptive Information: •

The suspect population is identified by models equipped with feature code 14AKL Meritor MS-19-13X-3DFR single rear axle with "R" hubs or 14AWB Dana

Spicer 2060S single rear axle with "R" hubs.

- The inclusive dates of manufacture were determined by the build date of the unit that experienced a failure in the field and the date the last vehicle in the suspect population was built with this option.
- The vehicles in the suspect population were built with feature code 14AKL Meritor MS-19-13X-3DFR single rear axle with "R" hubs or 14AWB Dana Spicer 2060S single rear axle with "R" hubs and all similar vehicles not subject to this recall were

There are 10 MV series trucks in the suspect population.

Production Dates : APR 14, 2022 - JUL 22, 2022

VIN Range 1: Begin: End: NR Not sequential

Description of Defect:

Description of the Defect: The locking clips of the wheel hub retaining nut may have been damaged

during installation allowing the retaining nut to work lose and result in

eventual hub separation from the axle housing.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: A wheel hub that separates from the axle housing may increase the risk of a

vehicle crash.

Description of the Cause: The work instructions for non-standard work did not include details for proper

orientation of the socket and there was no validation the locking tabs were

properly engaged.

Identification of Any Warning that can Occur: The vehicle operator may experience a vibration from the rear of the vehicle prior to wheel hub separation.

Involved Components:

Component Name 1: Axilock retaining nut

Component Description: Wheel hub retaining nut

Component Part Number: 2032055C1

Supplier Identification:

Component Manufacturer

Name: N/A - Assembly issue

Address: NR

NR

Country: NR

Chronology:

- 10/12/2022 Navistar Compliance notified a chassis enroute to a body builder experienced a wheel hub separation.
- 10/17/2022 Navistar Manufacturing quarantines potential suspect vehicles at the manufacturing plants and communicates the issue to Compliance.
- \bullet 10/25/2022 Navistar Compliance, Aftersales, and Quality meet to determine the impact to International vehicles.
- 11/02/2022 Navistar Compliance finalizes the suspect population.
- 11/02/2022 Navistar Aftersales initiates field inspections of the 10 suspect units in the field.
- 11/3/2022 Navistar declares a Safety Recall.
- 12/14/2022 Navistar Compliance documents the field inspections found all rear wheel hub nuts were properly installed or have been repaired.

Description of Remedy:

Description of Remedy Program: •

- The remedy will involve inspecting the hub retaining nuts for damaged locking fingers and replacing any nut found with damaged fingers.
- Navistar's plan for reimbursement of pre-notification remedies, on file with NHTSA and dated 05/06/2022, applies and reimbursement instructions will be included in the customer notification.

How Remedy Component Differs The remedy assembly involves verifying the locking fingers of the axilock from Recalled Component: nut are properly engaged where the original assembly process did not inspect for proper locking finger engagement.

Identify How/When Recall Condition 10/12/2022 – Navistar manufacturing began use of updated work was Corrected in Production: instructions that included details for proper insertion of nut to socket and verification the axilock nut locking fingers were properly engaged.

Recall Schedule:

Description of Recall Schedule: Because the recall remedy has been performed while all units were

located at dealers, body builders, or logistic providers, there will be no

recall schedule.

Planned Dealer Notification Date: NR - NR Planned Owner Notification Date: NR - NR

^{*} NR - Not Reported