OMB Control No.: 2127-0004

Part 573 Safety Recall Report

22V-936

Manufacturer Name: Mercedes-Benz USA, LLC

NHTSA Recall No.: 22V-936

Manufacturer Recall No.: 2022120016



Manufacturer Information:

Manufacturer Name: Mercedes-Benz USA, LLC

Address: 13470 International Parkway

Jacksonville FL 32218

Company phone: 1-877-496-3691

Population:

Number of potentially involved : 69 Estimated percentage with defect : 100 %

Vehicle Information:

Vehicle 1: 2021-2022 Mercedes-Benz GLE350

Vehicle Type: LIGHT VEHICLES

Body Style: SUV Power Train: GAS

Descriptive Information: Mercedes-Benz MY2021-2022 GLE-Class 53 vehicles

The recall population was determined through production records.

Vehicles outside of the recall population have the steering coupling locking screw

tightened to the specified torque value.

Production Dates: JUL 22, 2021 - MAY 26, 2022

VIN Range 1 : Begin : NR End : NR Not sequential

Vehicle 2: 2021-2022 Mercedes-Benz GLE450

Vehicle Type: LIGHT VEHICLES

Body Style: SUV Power Train: GAS

Descriptive Information: Mercedes-Benz MY2021-2022 GLE-Class 13 vehicles

The recall population was determined through production records.

Vehicles outside of the recall population have the steering coupling locking screw

tightened to the specified torque value.

Production Dates: JUL 22, 2021 - MAY 26, 2022

Vehicle Type : Body Style : Power Train :				
Production Dates :	JUL 22. 2021 -	MAY 26. 2022		
VIN Range 1:		NR	End: NR	☐ Not sequential
	8			
Vehicle Type : Body Style : Power Train : Descriptive Information :	2022-2022 Mercedes-Benz AMG GLE63 LIGHT VEHICLES STATIONWAGON GAS Mercedes-Benz MY2022 AMG GLE-Class 1 vehicle The recall population was determined through production records. Vehicles outside of the recall population have the steering coupling locking screw tightened to the specified torque value.			
Production Dates :				
VIN Range 1:	Begin:	NR	End: NR	☐ Not sequential
Vehicle Type : Body Style : Power Train :				
Production Dates: JUL 22, 2021 - MAY 26, 2022				
VIN Range 1:	,	NR	End: NR	☐ Not sequential

Description of Defect:

Description of the Defect: Mercedes-Benz AG ("MBAG"), the manufacturer of Mercedes-Benz vehicles, has

determined that on certain Model Year ("MY") 2021-2022 GLE and GLS (167 platform) vehicles, the steering coupling locking screw might not be tightened

to the specified torque value.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: Insufficient tightening torque of the steering coupling locking screw might

lead to free play in the connection, which would cause noises when driving on

uneven roads.

Should these noises not be noticed and therefore the vehicle not be brought to a workshop, the steering coupling locking screw may subsequently loosen further due to vibrations during driving and ultimately might back out of the steering coupling. In this condition, it cannot be fully ruled out that the steering coupling may detach from the steering shaft. This would impair the

ability to steer of the vehicle, and increase the risk of a crash.

Description of the Cause: Due to a deviation in the production process, the steering coupling locking

screw might not be tightened to the specified torque value.

Identification of Any Warning Before the issue occurs, the driver may be made aware of the issue by resulting

that can Occur: noises when driving on uneven roads.

Involved Components:

Component Name 1: FILLISTER HEAD SCREW

Component Description: FILLISTER HEAD SCREW - STEERING COUPLING TO STEERING GEAR

Component Part Number: A0109905604

Supplier Identification:

Component Manufacturer

Name: Mercedes-Benz AG

Address: NR

Foreign States

Country: Germany

Chronology:

In the end of August 2022, MBAG received a single field report outside the US describing noises while steering. The analysis of the vehicle rendered that a loose steering coupling locking screw caused the subject noises. MBAG launched investigations in order to identify the failure mechanism and root cause for an incorrectly torqued steering coupling locking screw.

In September 2022, the investigation concluded that the issue was caused by an individual worker error in the vehicle rework process of the assembly plant. Accordingly, all vehicles reworked by the subject worker were considered to be potentially affected, and a plant rework campaign was started to identify, block and rework all vehicles still in access of MBAG.

In October 2022, potentially affected vehicles in the field were identified and potential consequences of an incorrectly torqued locking screw were analyzed.

On December 9, 2022, MBAG determined that a potential safety risk cannot be ruled out and decided to conduct a recall.

MBAG confirms there are no warranty claims, field or service reports, and other information (such as the numbers of deaths and/or injuries) related to this defect in the USA.

Description of Remedy:

Description of Remedy Program: An authorized Mercedes-Benz dealer will replace the steering coupling

locking screw on the affected vehicles.

Pursuant to 49 C.F.R. \S 577.11(e), MBUSA does not plan to provide notice about pre-notice reimbursement to owners since none of the involved vehicles would have been previously subject to the condition described

and all remain covered under the new vehicle warranty.

How Remedy Component Differs The steering coupling locking screw tightened to the specified torque

from Recalled Component: value.

Remedy Part:

A0109905604 - FILLISTER HEAD SCREW - STEERING COUPLING TO

STEERING GEAR; M10X30

Identify How/When Recall Condition A change in the rework process ensures that this issue can no longer occur

was Corrected in Production: from August 4, 2022 onwards.

Recall Schedule:

Description of Recall Schedule: Dealers will be notified of the pending voluntary recall campaign on

December 23, 2022. Owners will be notified of the voluntary

recall campaign on January 27, 2023.

A copy of all communications will be provided when available.

Planned Dealer Notification Date : DEC 23, 2022 - NR Planned Owner Notification Date : JAN 27, 2023 - NR