Recall 234: Driver Airbag Emblem – Remedy Available Dealer Best Practice September 30, 2022

Updates to this Document

STOP

Hyundai

 Recall 234 – Remedy Available (TSB 22-01-079H) for replacement of the driver's side airbag has been published

STOP! DO NOT SELL NEW VEHICLES IN DEALER INVENTORY.



Date

<u>A dealer "stop sale" has been issued in accordance with federal regulation for affected vehicles unsold at dealers.</u>

* IMPORTANT

*** Dealer Stock & Retail Vehicles ***

Vehicle repairs related to safety recalls are critically important and must be performed properly in accordance with TSB procedures. Review this bulletin in its entirety prior to beginning any repair work.

As required by federal law, dealers must not deliver new vehicles for sale or for lease to customers until all open recalls have been performed. Dealers must also perform all open recalls on used vehicles, demo, and rental vehicles prior to placing them into customer use and whenever an affected vehicle is in the shop for any maintenance or repair.

Access the "Vehicle Information" screen (VIS) via WEBDCS to identify open recalls.

Description of Campaign:

The driver's air bag emblem on certain 2022MY Elantra N vehicles and 2022-23MY Elantra (with N Line Trim) vehicles may not have been welded properly during installation and may detach during a frontal air bag deployment, increasing the risk of injury in a crash.

Affected Vehicles:

Certain 2022MY Elantra N (CN7N) equipped with 2.0L Turbo engines produced between 12/08/2021 – 05/24/2022.
 Certain 2022-2023MY Elantra with N Line Trim equipped with 1.6L Turbo engines produced between 12/07/2021 – 05/17/2022.

> To check vehicle specific recall applicability, access the "Vehicle Information" screen via WebDCS.

➢ For this recall, please note that there are some new vehicles currently in dealer stock.

Remedy Information:

Replace the Driver's Air Bag.

- Estimated Repair Time: 0.4 M/H
- <u>Recommended Technician Training Level:</u> Expert (or above) service technician that has completed the Special Service Tools Training

Recommended Alternative Transportation:

This recall can be performed while the customer waits so a Service Rental Car (SRC) would not be needed.



Best Practice Checklist

Reservation: Did you check WebDCS for additional campaigns or recalls?
(Readiness: Are parts in stock to complete this campaign?
Yes – Provide customer with ETA
No – Contact parts and get ETA
(Reception: Did you explain to the customer the expected repair time based on the repair?
Reception: Did you explain to customer the warranty requirements?
Reception: Did you offer the customer Alternative Transportation?
\checkmark Yes
Repair: Did you provide the customer with an eMPI?
Repair: Does the Technician meet the recommended training requirements to complete this recall/campaign?
Return: Did you get the customer's signature on all warranty lines in addition to the final RO?

Parts

• The two (2) part numbers below are on Critical Supply Part (CSP) restriction; dealers required a valid recall VIN to order these parts

MODEL	PART NAME	PART NUMBER	IMAGE
ELANTRA N (CN7N)	DAB (DRIVER AIRBAG)	80100-IB000NNBQH	B
ELANTRA (CN7) WITH N-LINE TRIM	DAB (DRIVER AIRBAG)	80100-AA200NNBQH	- Xer Jonder

Important: WTC Callback of Parts

Removed airbag <u>must be deployed</u> before shipping if parts are requested for WTC return. The incident parts are subject to callback through the normal Warranty Technical Center (WTC) parts return process. Please ensure parts are retained. Please pay attention to any related callback request in WEBDCS. **Campaign claim will be subject to debit if the parts are requested and not returned.**



SST (Special Service Tools):

DESCRIPTION	PART NUMBER	IMAGE
H4/H5 ALLEN WRENCH OR SCREWDRIVER	N/A	
AIRBAG DEPLOYMENT TOOL*	0957A-34100A (SUPERSEDED BY 0957A-34100C)	S CA

*NOTE: This is an essential tool that was previously shipped to all dealers. Additional units can be ordered through BOSCH at 1-866-539-4248.

Warranty:

MODEL	OP. CODE	OPERATION	OP. TIME	CAUSAL PART	NATURE	CAUSE
ELANTRA N (CN7N)	21D116R0	DAB (DRIVER AIRBAG) REPLACEMENT	0.4 M/H	80100- IB000NNBQH	B12	ZZ7
ELANTRA (CN7) WITH N-LINE TRIM	21D116R1	DAB (DRIVER AIRBAG) REPLACEMENT	0.4 M/H	80100- AA200NNBQH	B12	ZZ7

NOTE 1: Submit claim on Campaign Claim Entry Screen

NOTE 2: If a part that is not covered by this campaign is found in need of replacement while performing this Campaign and the affected part is still under warranty, submit a separate claim using the same repair order. If the affected part is out of warranty, submit a prior approval request for goodwill consideration prior to performing the work.

NOTE 3: Removed airbag MUST be deployed before shipping if parts are requested for WTC return.

The incident parts are subject to callback through the normal Warranty Technical Center (WTC) parts return process. Claim is subject to debit if the parts requested and not returned.

NOTE 4: A STUI picture of the new air bag label (before inserted into the steering wheel) along with a piece of paper displaying the last 6 digits of the VIN and the date of the repair must be included and uploaded to STUI. If not included, claim will be subject to debit.

STUI Picture Requirement

Ensure a STUI photo of the driver's airbag label with the last 6 digits of the VIN and the date of repair is included & uploaded. Picture must be taken prior to the new driver airbag being inserted into the steering wheel.

A STUI picture that does not have the last 6 digits of the VIN, date of repair, and driver's airbag label is not acceptable. Claim will be subject to debit.

Acceptable STUI photo is shown below:





FAQs:

Q1: What is the issue?

A1: The emblem affixed to the driver's air bag cover in the subject vehicles may have been welded improperly during installation.

Q2: What is the safety concern?

A2: An improperly secured emblem could detach during frontal air bag deployment, increasing the risk of injury during a crash.

Q3: Have there been any accidents or injuries?

A3: As of the date of the filing (08/17/22) to NHTSA, there are no related injuries or reported incidents in the U.S.

Q4: What will be done during this recall service at the dealer?

A4: All owners of the subject vehicles will be notified by first class mail with instructions to bring their vehicles to a Hyundai dealer for replacement of the driver air bag. This remedy will be offered at no cost to owners for all affected vehicles, regardless of whether the affected vehicles are still covered under Hyundai's New Vehicle Limited Warranty.

Additionally, Hyundai will provide owners of affected vehicles reimbursement for out-of-pocket expenses incurred to obtain a remedy for the recall condition in accordance with the reimbursement plan submitted to NHTSA on February 24, 2022.

Q5: Will a Stop Sale be issued?

A5: Yes, a "stop sale" has been issued in accordance with federal regulation for affected vehicles unsold at dealers.

Q6: When will owners be notified?

A6: Owners will be notified in October 2022.

Contact Reference

Please see the following page for commonly referred to contacts.

Thank you for your prompt attention to this important safety matter and continued commitment to Hyundai customers.



Key Contact Information			
Dealer Support	Contact Information	Description	
Parts	HyundaiPartsHotline@MobisUSA.com 1-800-545-4515	Parts ordering hotline	
Techline	1-800-325-6604	Vehicle Technical Support for Hyundai Dealer Technicians	
Warranty HELPREP Line	1-877-446-2922	Warranty Claim questions for Hyundai Dealers	
Warranty Prior Approval (PA) Center	PA@hmausa.com	Warranty Prior Approval (PA) Center for Hyundai Dealers	
Xtime Technical Support	Support@xtime.com 1-866-984-6355	Assistance with Car Care Scheduling: Appointment / Shop Capacity Management / Campaign Integration / Operation Codes	
AutoLoop Technical Support	Support@autoloop.com 1-877-850-2010	Assistance with Car Care Scheduling: • Appointment / Shop Capacity Management / Campaign Integration / Operation Codes	
CDK Technical Support	https://serviceconnect.support.cdk. com/	 Assistance with Car Care Scheduling: Appointment / Shop Capacity Management / Campaign Integration / Operation Codes 	
Customer Support	Contact Information	Description	
Hyundai Customer Care Center (Recall/Campaign Questions)	1-855-671-3059	Customer questions or concerns related to <u>recall or</u> service campaigns	
Hyundai Recall /Campaign Website	www.hyundaiusa.com/recall	Updated information related to the specific recall or service campaign	
Hyundai Customer Care Center (General Questions)	1-800-633-5151	Customers general questions, non-campaign related	
Hyundai Roadside Assistance	1-800-243-7766	Hyundai Roadside Assistance	
	Key Reference Inform	mation	
Name		Source	
Campaign Central	Consolidated repository of recall and service campaign dealer best practices. Located on the service tab homepage in www.HyundaiDealer.com		
Car Care Scheduling (Xtime) - Tutorials	www.HyundaiDealer.com > Service > Dealer Resources > Documents Library > Car Care Scheduling		
Car Care Scheduling (Xtime) - Recall Appointment Notification	 Log into Xtime Under the menu at the top left, select 'CONFIGURE' Under the dealership tab, click "EMAIL COMMUNICATION" Slide the toggle to "ADVANCED" Populate as many e-mails as desired in the "PARTS DESK EMAIL FIELD" 		
Parts – Campaign Parts Management (CPM) Procedure	As applicable; <u>www.HyundaiDealer.com</u> > Parts > Documents Library > Campaign Parts Management		
(), C	SRC Documentation: www.HyundaiDealer.com > Service tab > Documents Library > Service Rental Car TSD: www.HyundaiDealer.com > Service tab > SRC Fleet Mgmt Software Insurance: www.HyundaiDealer.com > Service tab > SRC Insurance		
Technical Service Bulletin (TSB)	www.HyundaiDealer.com > Service tab > Hyundai Tech Info		
Uncompleted Campaign VIN Listing	A listing of vehicles is located on WEBDCS > SERVICE tab > select UNCOMPLETED CAMPAIGN VIN LISTING – Dealer Stock (New, SRC, CPO, etc.) and Retailed.		
Recall Campaign Website	www.hyundaiusa.com/recall		
NHTSA Website	www.safercar.gov		



<u>Appendix</u>

History	Date
Remedy Not Available	08/19/2022